Sea-Bird Scientific
13431 NE 20th Street
Bellevue, WA 98005
USA

+1 425-643-9866
seabird@seabird.com
www.seabird.com

SENSOR SERIAL NUMBER: 1869
CALIBRATION DATE: 08-Mar-26

SBE 37 CONDUCTIVITY CALIBRATION DATA
PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

```
g =  -1.051051e+00
h =   1.512005e-01
i =  -8.074376e-05
j =   3.379817e-05

CPcor = -9.5700e-008
CTcor =  3.2500e-006
WBOTC =   5.1842e-06
```

BATH TEMP (° C)	BATH SAL (PSU)	BATH COND (S/m)	INSTRUMENT OUTPUT (Hz)	INSTRUMENT COND (S/m)	RESIDUAL (S/m)
22.0000	0.0000	0.00000	2636.20	0.00000	0.00000
1.0000	34.6043	2.95956	5142.12	2.95957	0.00001
4.5000	34.5862	3.26515	5333.47	3.26514	-0.00001
15.0000	34.5491	4.24229	5903.02	4.24228	-0.00001
18.5000	34.5419	4.58588	6090.36	4.58588	0.00001
24.0000	34.5350	5.14139	6381.28	5.14139	0.00001
29.0000	34.5321	5.66098	6641.53	5.66099	0.00000
32.5000	34.5313	6.03189	6821.03	6.03188	-0.00000

f = Instrument Output(Hz) * sqrt(1.0 + WBOTC * t) / 1000.0

t = temperature (°C); p = pressure (decibars); δ = CTcor; ε = CPcor;

Conductivity (S/m) = $(g + h * f^2 + i * f^3 + j * f^4) / (1 + \delta * t + \varepsilon * p)$

Residual (Siemens/meter) = instrument conductivity - bath conductivity