Sea-Bird Electronics, Inc.
13431 NE 20th Street
Bellevue, WA 98005 United States
(Do Not Send Payments To This Physical Address – See Remit to Information)

+1-425-643-9866
service@seabird.com
www.seabird.com

SERVICE REPORT

RMA #: 00002589

Date: 24-AUG-2026

CUSTOMER INFORMATION

Name: NOAA - PMEL PACIFIC MARINE ENVIRO LAB
Account : 40279844
David Strausz
david.strausz@noaa.gov
206-526-4510

PO Number: CC-Weiming Tan
Notes:

Bill To Address
NOAA - PMEL PACIFIC MARINE ENVIRO LAB
7600 SAND POINT WAY NE
SEATTLE, WA, 98115-6349
US

Ship To Address
NOAA - PMEL PACIFIC MARINE ENVIRO LAB
7600 SAND POINT WAY NE
SEATTLE, WA, 98115-6349
US

PRODUCTS SERVICED

Sales Order	Serial	Instrument	Description	Problems Found	Work Performed
	16P31373-4424	16P.LEGACY	(LEGACY) SBE 16Plus (V1/V2) CT(D)	Unable to update old V1 firmware The battery bulkhead had corrosion damage on the posts. A battery retainer plate was missing.	Perform initial diagnostic evaluation. Replaced corroded battery bulkhead. Replaced the O-rings. Performed a hydrostatic pressure test. Verified operation of LOG AMP. Issue may be with customer sensor or cable. Performed "POST" cruise calibration. Installed battery retainer plate.
	16P63320-6826	16P.LEGACY	(LEGACY) SBE 16Plus (V1/V2) CT(D)	No problems found.	Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Current firmware is most recent for this CTD.
	37SM26834-2024	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	The conductivity cell was found to require cleaning and re-platinization.	Performed initial diagnostic evaluation. Performed “POST” cruise calibration. Cleaned and replatinized the conductivity cell. Unable to update the firmware. Performed a "Final" Calibration. Performed complete system check and full diagnostic evaluation.
	37SM28082-2329	37SM.LEGACY	(LEGACY) SBE 37SM MicroCAT	No problem found.	Performed initial diagnostic evaluation. Unable to update the firmware. Performed “POST” cruise calibration. Performed complete system check and full diagnostic evaluation.
	3925210-504	39.LEGACY	(LEGACY) SBE 39 Temperature (Depth) Recorder	No problem found.	Performed initial diagnostic evaluation. Unable to update the firmware. Performed “POST” cruise calibration. Performed complete system check and full diagnostic evaluation. Installed (1) new battery.
	3928082-0805	39.LEGACY	(LEGACY) SBE 39 Temperature (Depth) Recorder	No problem found.	Performed initial diagnostic evaluation. Performed “POST” cruise calibration. Performed complete system check and full diagnostic

					evaluation. Upgraded the Firmware to Current Version. Installed (1) new battery.
	3931349-1161	39.LEGACY	(LEGACY) SBE 39 Temperature (Depth) Recorder	No problem found.	Performed initial diagnostic evaluation. Performed “POST” cruise calibration. Performed complete system check and full diagnostic evaluation. Upgraded the Firmware to Current Version. Installed (1) new battery.
	3931349-1165	39.LEGACY	(LEGACY) SBE 39 Temperature (Depth) Recorder	No problem found.	Performed initial diagnostic evaluation. Performed “POST” cruise calibration. Performed complete system check and full diagnostic evaluation. Upgraded the Firmware to Current Version. Installed (1) new battery.
	3936048-1640	39.LEGACY	(LEGACY) SBE 39 Temperature (Depth) Recorder	No problem found.	Performed initial diagnostic evaluation. Performed pressure calibration. Performed “POST” cruise calibration. Performed complete system check and full diagnostic evaluation. Unable to update the firmware. Installed (1) new battery.

BILLABLE ITEMS

Instrument	Item	Item Description	Qty
16P31373-4424:16P.LEGACY	SBS-SVC-16	COMPREHENSIVE SERVICE/CALIBRATION OF SBE16P AND SBE16PV2. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
16P63320-6826:16P.LEGACY	SBS-SVC-16	COMPREHENSIVE SERVICE/CALIBRATION OF SBE16P AND SBE16PV2. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
37SM26834-2024:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
37SM28082-2329:37SM.LEGACY	SBS-SVC-37	COMPREHENSIVE SERVICE/CALIBRATION OF SBE 37. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION (FRRF)	1
3925210-504:39.LEGACY	SBS-SVC-39	COMPREHENSIVE SERVICE/CALIBRATION OF SBE39 AND SBE39P. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
3928082-0805:39.LEGACY	SBS-SVC-39	COMPREHENSIVE SERVICE/CALIBRATION OF SBE39 AND SBE39P. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
3931349-1161:39.LEGACY	SBS-SVC-39	COMPREHENSIVE SERVICE/CALIBRATION OF SBE39 AND SBE39P. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
3931349-1165:39.LEGACY	SBS-SVC-39	COMPREHENSIVE SERVICE/CALIBRATION OF SBE39 AND SBE39P. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1
3936048-1640:39.LEGACY	SBS-SVC-39	COMPREHENSIVE SERVICE/CALIBRATION OF SBE39 AND SBE39P. INCLUDES ROOM TEMPERATURE PRESSURE CHARACTERIZATION IF REQUIRED (FRRF)	1

UNBILLABLE ITEMS

Instrument	Item	Item Description	Qty

16P31373-4424:16P.LEGACY	801255	SEACATplus BATTERY BULKHEAD, 9-CELL	1
16P31373-4424:16P.LEGACY	SBS-SVC-OTHER	SPECIFIC SERVICE REQUEST - CHECK DETAILED NOTES (FRRF)	1
16P31373-4424:16P.LEGACY	41124	SEACAT PLUS BATTERY COVER PCB	1
3925210-504:39.LEGACY	EXA-ZX0064	BATTERY, 9v, Lithium	1
3928082-0805:39.LEGACY	11183	IC, ZPSD312B-15J/ZPSD302B-90JI EPROM NO WNDW	1
3928082-0805:39.LEGACY	EXA-ZX0064	BATTERY, 9v, Lithium	1
3931349-1161:39.LEGACY	11183	IC, ZPSD312B-15J/ZPSD302B-90JI EPROM NO WNDW	1
3931349-1161:39.LEGACY	EXA-ZX0064	BATTERY, 9v, Lithium	1
3931349-1165:39.LEGACY	11183	IC, ZPSD312B-15J/ZPSD302B-90JI EPROM NO WNDW	1
3931349-1165:39.LEGACY	EXA-ZX0064	BATTERY, 9v, Lithium	1
3936048-1640:39.LEGACY	EXA-ZX0064	BATTERY, 9v, Lithium	1