



Sea-Bird Scientific
13431 NE 20th Street
Bellevue, WA 98005
USA

+1 425-643-9866
seabird@seabird.com
www.seabird.com

SENSOR SERIAL NUMBER: 4607
CALIBRATION DATE: 08-Mar-26

SBE 16plus CONDUCTIVITY CALIBRATION DATA
PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

g = -1.023913e+00
h = 1.325532e-01
i = -2.917202e-04
j = 4.040698e-05

CPcor = -9.5700e-008
CTcor = 3.2500e-006

BATH TEMP (° C)	BATH SAL (PSU)	BATH COND (S/m)	INSTRUMENT OUTPUT (Hz)	INSTRUMENT COND (S/m)	RESIDUAL (S/m)
22.0000	0.0000	0.00000	2784.55	0.0000	0.00000
1.0000	34.6043	2.95956	5489.92	2.9596	-0.00000
4.5000	34.5862	3.26515	5695.92	3.2651	0.00000
15.0000	34.5491	4.24229	6308.75	4.2423	0.00001
18.5000	34.5419	4.58588	6510.21	4.5859	-0.00000
24.0000	34.5350	5.14139	6822.99	5.1414	-0.00001
29.0000	34.5321	5.66098	7102.72	5.6610	-0.00000
32.5000	34.5313	6.03189	7295.60	6.0319	0.00000

f = Instrument Output (Hz) / 1000.0

t = temperature (°C); p = pressure (decibars); δ = CTcor; ϵ = CPcor;

Conductivity (S/m) = $(g + h * f^2 + i * f^3 + j * f^4) / (1 + \delta * t + \epsilon * p)$

Residual (Siemens/meter) = instrument conductivity - bath conductivity

