



Sea-Bird Scientific
13431 NE 20th Street
Bellevue, WA 98005
USA

+1 425-643-9866
seabird@seabird.com
www.seabird.com

SENSOR SERIAL NUMBER: 1869
CALIBRATION DATE: 24-Feb-26

SBE 37 CONDUCTIVITY CALIBRATION DATA
PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

g = -1.051604e+00
h = 1.510781e-01
i = 1.182279e-05
j = 2.677725e-05

CPcor = -9.5700e-008
CTcor = 3.2500e-006
WBOTC = 5.1842e-06

BATH TEMP (° C)	BATH SAL (PSU)	BATH COND (S/m)	INSTRUMENT OUTPUT (Hz)	INSTRUMENT COND (S/m)	RESIDUAL (S/m)
22.0000	0.0000	0.00000	2636.26	0.00000	0.00000
1.0000	34.6508	2.96316	5141.95	2.96318	0.00002
4.5000	34.6327	3.26910	5333.24	3.26909	-0.00002
15.0000	34.5939	4.24721	5902.60	4.24719	-0.00001
18.5000	34.5855	4.59104	6089.83	4.59104	0.00000
24.0000	34.5756	5.14676	6380.52	5.14678	0.00001
29.0000	34.5682	5.66624	6640.43	5.66625	0.00001
32.5000	34.5581	6.03604	6819.23	6.03602	-0.00001

$f = \text{Instrument Output(Hz)} * \sqrt{1.0 + \text{WBOTC} * t} / 1000.0$

t = temperature (°C); p = pressure (decibars); $\delta = \text{CTcor}$; $\epsilon = \text{CPcor}$;

Conductivity (S/m) = $(g + h * f^2 + i * f^3 + j * f^4) / (1 + \delta * t + \epsilon * p)$

Residual (Siemens/meter) = instrument conductivity - bath conductivity

