NOTAMs

NOTAMs have been filtered using the following criteria:

Filtered checklist and trigger NOTAMs (Q code KKKK and TTTT)

Filtered NOTAMs not relevant for IFR

Filtered NOTAMs with a geographical reference more than 80 NM from the route of flight

Filtered NOTAMs outside FL range 360 to 480

Filtered NOTAMs not active during this flight

Filtered all non-oceanic ARTCC NOTAMS

Departure

KISP - Long Island Mac Arthur

AERODROME

ISP 01/163 ISP AD AP RDO ALTIMETER UNREL. AUTOLAND, HUD TO TOUCHDOWN, ENHANCED FLT
VISION SYSTEMS TO TOUCHDOWN, HEL OPS REQUIRING RDO ALTIMETER DATA TO INCLUDE HOVER
AUTOPILOT MODES AND CAT A/B/PERFORMANCE CLASS TKOF AND LDG NOT AUTHORIZED EXC FOR ACFT
USING APPROVED ALTERNATIVE METHODS OF COMPLIANCE DUE TO 5G C-BAND INTERFERENCE PLUS SEE
AIRWORTHINESS DIRECTIVES 2021-23-12, 2021-23-13 2201190501-2401190501

OBSTRUCTION

ISP 04/129 ISP OBST CRANE LGT (ASN 2021-AEA-17433-OE) 404831N0730628W (0.8NM NNW ISP) 288FT (175FT AGL) **U/S** 2304241223-2306012100

ISP 04/130 ISP OBST CRANE (ASN 2022-AEA-13766-OE) 404837N0730628W (0.9NM NNW ISP) 302FT (190FT AGL) FLAGGED AND LGTD 2304241223-2306012100

OBSTACLE DEPARTURE PROCEDURE

FDC 3/8186 ISP ODP LONG ISLAND MAC ARTHUR, NEW YORK, NY. TAKEOFF MINIMUMS AND (OBSTACLE)

DEPARTURE PROCEDURES AMDT 5A... TAKEOFF MINIMUMS: RWY 33R, 300-1 OR STANDARD WITH A

MINIMUM CLIMB OF 490FT PER NM TO 500. TEMPORARY CRANE 288FT MSL 4335FT NORTHWEST OF RWY

15L (2021-AEA-17433-OE). TEMPORARY CRANE 302FT MSL 2952FT N OF RWY 15R (2022-AEA-13766,
67-OE). ALL OTHER DATA REMAINS AS PUBLISHED. 2304071659-2306091659EST

STANDARD INSTRUMENT PROCEDURE

FDC 3/9706 ISP SID LONG ISLAND MAC ARTHUR, NEW YORK, NY. LONG ISLAND SEVEN DEPARTURE...

NOTE: COATE DEPARTURES NA EXCEPT FOR AIRCRAFT EQUIPPED WITH SUITABLE RNAV SYSTEM WITH

GPS, SAX VOR OUT OF SERVICE. 2304110954-2309302111EST

FDC 3/8187 ISP SID LONG ISLAND MAC ARTHUR, NEW YORK, NY. LONG ISLAND SEVEN DEPARTURE...

TAKEOFF MINIMUMS: RWY 33R, 300-1 OR STANDARD WITH A MINIMUM CLIMB OF 490FT PER NM TO
500. TEMPORARY CRANE 288FT MSL 4335FT NORTHWEST OF RWY 15L (2021-AEA-17433-OE).

TEMPORARY CRANE 302FT MSL 2952FT N OF RWY 15R (2022-AEA-13766, 67-OE). ALL OTHER DATA
REMAINS AS PUBLISHED. 2304071659-2306091659EST

STANDARD TERMINAL ARRIVAL ROUTE

FDC 1/8274 ISP STAR LOVES TWO ARRIVAL ALB R-238 UNUSABLE. SUITABLE RNAV/GPS REQUIRED 2107131200-2307131200

INSTRUMENT APPROACH PROCEDURE

FDC 3/2220 ISP IAP LONG ISLAND MAC ARTHUR, NEW YORK, NY. ILS OR LOC RWY 6, AMDT 25A...

ILS RWY 6, AMDT 25A (SA CAT I-II)... MISSED APPROACH: CLIMB TO 600 THEN CLIMBING LEFT

TURN TO 2000 ON HEADING 235 AND ON DPK VOR/DME R-186 TO DEERY INT/I-ISP 12.57 DME AND

HOLD. RADAR REQUIRED FOR PROCEDURE ENTRY EXCEPT FOR AIRCRAFT EQUIPPED WITH SUITABLE RNAV

SYSTEM WITH GPS, CCC VOR/DME OUT OF SERVICE. 2304171200-2306152000EST

FDC 3/2221 ISP IAP LONG ISLAND MAC ARTHUR, NEW YORK, NY. ILS OR LOC RWY 24, AMDT 4D...

MISSED APPROACH: CLIMB TO 1300, THEN CLIMBING RIGHT TURN TO 2000 ON HEADING 035 AND ON

DPK VOR/DME R-082 TO PAZTA INT/8.68 DME AND HOLD. RADAR REQUIRED FOR PROCEDURE ENTRY

EXCEPT FOR AIRCRAFT EQUIPPED WITH SUITABLE RNAV SYSTEM WITH GPS, CCC VOR/DME OUT OF

SERVICE. 2304171200-2306152000EST

FDC 3/8183 ISP IAP LONG ISLAND MAC ARTHUR, NEW YORK, NY. RNAV (GPS) RWY 15R, AMDT 1...

LNAV MDA 600/HAT 501 ALL CATS. VISIBILITY CATS C/D 1 3/8. CIRCLING MDA CAT A 640/HAA

541. TEMPORARY CRANE 288FT MSL 2331FT N OF RWY 15R (2021-AEA-17433-OE). TEMPORARY CRANE

302FT MSL 2952FT N OF RWY 15R (2022-AEA-13766, 67-OE). 2304071659-2306091659EST

FDC 3/8184 ISP IAP LONG ISLAND MAC ARTHUR, NEW YORK, NY. ILS OR LOC RWY 6, AMDT 25A...

CIRCLING MDA CAT A 640/HAA 541. WILAK FIX MINIMUMS (DUAL VOR RECEIVERS OR DME REQUIRED):

CIRCLING MDA CAT A 640/HAA 541. TEMPORARY CRANE 288FT MSL 2331FT N OF RWY 15R

(2021-AEA-17433-OE). TEMPORARY CRANE 302FT MSL 2952FT N OF RWY 15R (2022-AEA-13766,
67-OE). 2304071659-2306091659EST

FDC 3/8185 ISP IAP LONG ISLAND MAC ARTHUR, NEW YORK, NY. ILS OR LOC RWY 24, AMDT 4D...
RNAV (GPS) RWY 24, AMDT 3A... RNAV (GPS) RWY 33L, AMDT 1... RNAV (GPS) RWY 6, AMDT 2B...
CIRCLING MDA CAT A 640/HAA 541. TEMPORARY CRANE 288FT MSL 2331FT N OF RWY 15R
(2021-AEA-17433-OE). TEMPORARY CRANE 302FT MSL 2952FT N OF RWY 15R (2022-AEA-13766,
67-OE). 2304071659-2306091659EST

FDC 3/7672 ISP IAP LONG ISLAND MAC ARTHUR, NEW YORK, NY. ILS OR LOC RWY 24, AMDT 4D...

DISREGARD PLANVIEW NOTE: NOPT FOR ARRIVAL ON CCC VOR/DME AIRWAY RADIALS R-057, AND
R-105. ADD PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS ON CCC VOR/DME AIRWAY RADIALS 193 CW
325. 2303141854-2408111852EST

FDC 2/3767 ISP IAP LONG ISLAND MAC ARTHUR, NEW YORK, NY. ILS RWY 06 (SA CAT I - II),

AMDT 25A ... PROCEDURE NA EXC FOR ACFT USING APPROVED ALTERNATIVE METHODS OF COMPLIANCE

DUE TO 5G C-BAND INTERFERENCE PLUS SEE AIRWORTHINESS DIRECTIVES 2021-23-12, 2021-23-13

2201190500-2401190506EST

NOTAMs: Page 1 of 30

Destination

LOWW - Schwechat

RUNWAY INSTALLED

A1052/23 NOTAMN

- Q) LOVV/QMRCS/IV/BO /A /000/999/4807N01634E005
- A) LOWW B) 2305040403 C) 2307280800EST
- E) RWY 16/34 ALL TORA SIGNS INSTALLED

AERODROME

A0962/23 NOTAMR A0236/23

- Q) LOVV/QFAXX/IV/NBO/A /000/999/4807N01634E005
- A) LOWW B) 2304250551 C) 2307240800EST
- E) 'AIRPORT SLOT ID' FOR GENERAL/BUSINESS AVIATION FLIGHTS TO/FROM COORDINATED AIRPORTS IN AUSTRIA - SEE AIP SUP 017/22.

INSTRUMENT LANDING SYSTEM UNSERVICEABLE

A0903/23 NOTAMN

- Q) LOVV/QICAS/I /NBO/A /000/999/4807N01632E005
- A) LOWW B) 2304240500 C) 2305160500 EST
- E) ILS RWY11 U/S

INSTRUMENT APPROACH PROCEDURE

A0695/23 NOTAMR A0694/23

- Q) LOVV/QPIXX/I /NBO/A /000/999/4807N01634E005
- A) LOWW B) 2303221506 C) 2306142359
- E) WITH IMMEDIATE EFFECT SPEED CONSTRAINTS (K230-) SHALL NOT BE

CONSIDERED FOR THE FOLLOWING WAYPOINTS.

RWY 11: WW652, WW653, WW654, WW655

RWY 16: WW672, WW673, WW674, WW675

RWY 29: WW952, WW953, WW955

RWY 34: WW972, WW973, WW974, WW975, WW976

PAY ATTENTION TO ATC SPEED INSTRUCTIONS NOTE: REVISED RNAV TRANSITION CODING TABLES WILL BE PUBLISHED

WEF 15 JUN 2023-AIRAC AMDT 272

AERODROME

A0648/23 NOTAMN

- Q) LOVV/QFAXX/IV/NBO/A /000/999/4807N01634E005
- A) LOWW B) 2303260000 C) 2306090800 EST
- E) REF AIP AUSTRIA, LOWW AD 2.22, ITEM 2.2
- THE FOLLOWING TIMES ARE CURRENTLY CONSIDERED IN LOWW AS RUSH HOURS: 0600-0730, 0900-1030, 1130-1300, 1400-1530, 1630-1730, 1830-2100

Alternate

KFOK - Francis S Gabreski

AERODROME

FOK 01/019 FOK AD AP RDO ALTIMETER UNREL. AUTOLAND, HUD TO TOUCHDOWN, ENHANCED FLT VISION SYSTEMS TO TOUCHDOWN, HEL OPS REQUIRING RDO ALTIMETER DATA TO INCLUDE HOVER AUTOPILOT MODES AND CAT A/B/PERFORMANCE CLASS TKOF AND LDG NOT AUTHORIZED EXC FOR ACFT USING APPROVED ALTERNATIVE METHODS OF COMPLIANCE DUE TO 5G C-BAND INTERFERENCE PLUS SEE AIRWORTHINESS DIRECTIVES 2021-23-12, 2021-23-13 2201190501-2401190501

INSTRUMENT APPROACH PROCEDURE

FDC 3/3830 FOK IAP FRANCIS S GABRESKI, WESTHAMPTON BEACH, NY. ILS OR LOC RWY 24, AMDT 11A... TERMINAL ROUTE FROM HTO VOR/DME (IAF) TO MATTY INT NA EXCEPT FOR ACFT EQUIPPED WITH SUITABLE RNAV SYSTEM WITH GPS. HTO VOR R-308 UNUSABLE. 2304191450-2504201450EST

FDC 3/2216 FOK IAP FRANCIS S GABRESKI, WESTHAMPTON BEACH, NY. ILS OR LOC RWY 24, AMDT 11A... MISSED APPROACH: CLIMB TO 880, THEN CLIMBING LEFT TURN TO 2700 DIRECT HTO VORTAC AND HOLD, CCC VOR/DME OUT OF SERVICE. 2304171200-2306152000EST

Alternate

LOWG - Graz

RUNWAY DISPLACED

A1016/23 NOTAMN

- Q) LOVV/QMRCM/IV/NBO/A /000/999/4700N01526E005
- A) LOWG B) 2304302200 C) 2307280800 EST
- E) CHANGE OF THE RWY STRIP DIMENSONS:

16C 3120(M) X 280 (M)

34C 3120(M) X 280 (M

RUNWAY USABLE FOR LENGTH/WIDTH OF ...

A0947/23 NOTAMR A0225/23

- Q) LOVV/QMRLL/IV/NBO/A /000/999/4700N01526E005
- A) LOWG B) 2304240523 C) 2307210900 EST
- E) CORRECTION INTERSECTION TAKE OFFS FOR

RWY 34C - TWY Y - TODA (M) 2276

RWY 34C - TWY B - TODA (M) 1377

RWY 34C - TWY X - TODA (M) 1371

RWY 34C - TWY C - TODA (M) 895

NOTAMs: Page 2 of 30

OBSTACLE ERECTED

A0482/23 NOTAMN

- Q) LOVV/QOBCE/IV/M /AE/000/016/4700N01526E005
- A) LOWG B) 2302270600 C) 2305260800 EST
- E) MOBILE CRANE ERECTED AT

TOBELBADER STRASSE 30, 8141 PREMSTAETTEN

COORDINATES: 465842N 0152339E

ELEV: 414,9M 1361,22FT AMSL

HEIGHT ABOVE GND: 58,3M 191,27FT AGL

OBST DAY MARKED: YES OBST NIGHT MARKED: YES

Alternate

LZIB - M.R. Stefanik

MINIMUM ALTITUDE CHANGED

A0786/23 NOTAMN

- O) LZBB/OAACH/IV/BO /AE/000/999/4810N01717E012
- A) LZIB B) 2304280920 C) 2307282359 EST
- E) MNM ALT IN AREA IB SMAA 01 RAISED TO 2100FT AMSL.

REF PAGES AD 2-LZIB-9-1, AD 2-LZIB-9-2.

OBSTACLE ERECTED

A0729/23 NOTAMN

- Q) LZBB/QOBCE/IV/M /E /000/011/4808N01708E001
- A) LZBB B) 2304190000 C) PERM
- E) PERM AIR NAVIGATION OBSTACLE AREA 1:

BRATISLAVA, EUROVEA 2 - BUILDING, PSN: 480823N 0170738E,

ELEV/HGT GND: 310M/171M, LGT-COLOUR: W/R, TYPE: FLG, LIM/LIL.

REF ENR 5.4, PAGE AD 2-LZIB-8-1,

AERONAUTICAL CHART - ICAO 1:500 000.

TAXIWAY CLOSED

A0321/23 NOTAMN

- Q) LZBB/QMXLC/IV/BO /A /000/999/4810N01713E005
- A) LZIB B) 2302241226 C) 2305242359 EST
- E) TWY D BTN RWY 13/31 AND RWY 22 CLSD ACFT PARKING.

TAXIWAY CLOSED

A0320/23 NOTAMN

- Q) LZBB/QMXLC/IV/BO /A /000/999/4810N01713E005
- A) LZIB B) 2302241224 C) 2305242359 EST
- E) TWY B CLSD ACFT PARKING.

ETP Airport

CYQX - Gander International

RUNWAY HAZARD DUE TO

(NEW TODAY)
[Inactive during flight]

\$2273/23 NOTAMR \$2267/23

- Q) CZQX/QFAXX/IV/NBO/A/000/999/4856N05434W005
- A) CYQX B) 2305090847 C) 2305091647
- E) RSC 03 5/5/5 100 PCT WET, 100 PCT WET, 100 PCT WET. VALID MAY 09 0845 MAY 09 1645.

RSC 21 5/5/5 100 PCT WET, 100 PCT WET, 100 PCT WET. VALID MAY 09 0845 - MAY 09 1645.

RSC 13 5/5/5 100 PCT WET, 100 PCT WET, 25 PCT 1/4IN STANDING

WATER AND 75 PCT WET. STANDING WATER 400FT FROM THR OF RWY 31. VALID MAY 09 0845 - MAY 09 1645.

RSC 31 5/5/5 25 PCT 1/4IN STANDING WATER AND 75 PCT WET, 100 PCT

WET, 100 PCT WET. STANDING WATER 400FT FROM THR OF RWY 31. VALID

MAY 09 0845 - MAY 09 1645. ADDN NON-GRF/TALPA INFO:

VOR/DME UNSERVICEABLE

H1163/23 NOTAMN

- Q) CZQX/QNMAS/IV/BO/AE/000/999/4854N05432W025
- A) CYQX B) 2305031030 C) 2307151930
- E) GANDER VOR/DME YQX 112.7MHZ/CH74X U/S

FIREFIGHTING AND RESCUE AVAILABLE ON REQUEST

E1759/23 NOTAMR E0013/23

- Q) CZQX/QFFAR/IV/NBO/A/000/999/4856N05434W005
- A) CYOX B) 2303291825 C) 2306291630
- E) ACFT RESCUE AND FIRE FIGHTING (ARFF)

CAT 5 AVBL 30 MIN PN.

CAT 6, CAT 7 AND CAT 8 AVBL 3 HR PN

CTC 709-256-6674 OR 709-256-6966

NOTAMs: Page 3 of 30

ETP Airport EINN - Shannon International

HOLDING PROCEDURE CHANGED

B1142/15 NOTAMN

- Q) EISN/QPHCH/IV/BO /AE/000/999/5242N00855W025
- A) EINN B) 1510021807 C) PERM
- E) HOLDING PROCEDURE CHANGED. RATE OF DESCENT IN HOLDING PATTERNS AMENDED TO: A STANDARD RATE OF DESCENT OF 1000FT PER MIN IN HOLDING PATTERNS WILL BE USED UNLESS OTHERWISE INSTRUCTED BY ATC. PILOTS MUST ADVISE ATC IF UNABLE TO COMPLY WITH THE STANDARD RATE OF DESCENT.

REF AIP EINN AD 2.22 SECTION 9

AERONAUTICAL INFORMATION SERVICE

B0432/23 NOTAMN

- Q) EISN/QOAXX/IV/BO /A /000/999/5242N00855W005
- A) EINN B) 2304261130 C) 2307241559
- E) ONLINE FLIGHT PLANNING, IAIP IRELAND AND THE PIB WILL BE

AVAILABLE

ON WWW.AIRNAV.IE FROM 27 APRIL 2023 AT 1300 UTC REF AIC 003/23

AIR/GROUND FACILITY

B0426/23 NOTAMR B0222/23

- Q) EISN/QCAXX/IV/NBO/AE/000/999/5242N00855W005
- A) EINN B) 2304251659 C) 2305312359
- E) ATS COMMUNICATIONS FOR GLOBAL REPORTING FORMAT FOR RUNWAY SURFACE CONDITIONS. RUNWAY SURFACE CONDITIONS NOT REPORTED BY ATIS. FLIGHT CREW SHOULD REQUEST THE LATEST RUNWAY SURFACE CONDITIONS FROM SHANNON TOWER OR APPROACH.

FIREFIGHTING AND RESCUE DOWNGRADED TO

(NEW TODAY) [Inactive during flight]

A1170/23 NOTAMN

- Q) EISN/QFFCG/IV/NBO/A /000/999/5242N00855W005
- A) EINN B) 2305090649 C) 2305091400
- E) FIREFIGHTING AND RESCUE DOWNGRADED TO CAT 7.

STANDARD INSTRUMENT DEPARTURE NOT AVAILABLE

A0419/23 NOTAMR A2768/22

- Q) EISN/QPDAU/I /NBO/A /000/999/5242N00855W005
- A) EINN B) 2302271115 C) 2305262359 EST
- E) SID DIGAN3A
- SID TOMTO3A NOT AVAILABLE

REF EINN AD 2.24-5.1

US Enroute Navigation NOTAMs

| NAVIGATION | | | | | | | | | | | | |
|------------|-----|--------|-----|-----|-----|-----|-----------------------|------|------|----|-----|-----------------------|
| | MVY | 05/016 | MVY | NAV | ILS | RWY | 24 | LOC/ | GP/D | ME | U/S | 2305091300-2305091800 |
| | ACK | 05/024 | ACK | NAV | VOR | U/S | 2305101330-2305101830 | | | | | 1830 |

/S 2305101330-2305101830 ACK 03/020 ACK NAV DME U/S 2303111423-2307122000EST

ACK 05/024 ACK NAV VOR U/S 2305101330-2305101830 HVN 05/025 HVN NAV ILS RWY 02 LOC/GP/DME U/S 2305090400-2305091100EST ISP 04/057 CCC NAV VOR/DME U/S 2304171200-2306152000

HYA 04/002 HYA NAV ILS RWY 24 U/S 2304041200-2308261700

ACK 03/020 ACK NAV DME U/S 2303111423-2307122000EST

CYQI - Yarmouth Enroute airport

FUEL AVAILABILITY NOT AVAILABLE

(NEW TODAY) [Inactive during flight]

[Inactive during flight]

[Inactive during flight]

[Inactive during flight]

- Q) CZQM/QFUAU/IV/NBO/A/000/999/4350N06605W005
- A) CYQI B) 2305081938 C) 2305092000

E) FUEL JA-1 SINGLE POINT REFUELING ONLY

CYHZ - Stanfield International Enroute airport

RUNWAY HAZARD DUE TO

S2270/23 NOTAMR S2255/23

E2302/23 NOTAMR E2299/23

(NEW TODAY) [Inactive during flight]

Q) CZQM/QFAXX/IV/NBO/A/000/999/4453N06331W005

- A) CYHZ B) 2305090810 C) 2305091610
- E) RSC 05 6/6/6 DRY, DRY, DRY. VALID MAY 09 0807 MAY 09 1607.
- RSC 23 6/6/6 DRY, DRY, DRY. VALID MAY 09 0807 MAY 09 1607.
- RSC 14 6/6/6 DRY, DRY, DRY. VALID MAY 09 0808 MAY 09 1608.
- RSC 32 6/6/6 DRY, DRY, DRY. VALID MAY 09 0808 MAY 09 1608.

ADDN NON-GRF/TALPA INFO:

NOTAMs: Page 4 of 30

VOR UNSERVICEABLE

H0820/23 NOTAMR H0582/23

- Q) CZQM/QNVAS/IV/BO/AE/000/999/4455N06324W025
- A) CYHZ B) 2303311806 C) 2306302359 EST
- E) HALIFAX VOR YHZ 115.1MHZ U/S

Enroute airport

LFRB - Bretagne

OBSTACLE ERECTED

P4356/22 NOTAMR P2135/22

- Q) LFRR/QOBCE/IV/M /A /000/999/4827N00425W005
- A) LFRB B) 2212211341 C) 2306302359
- E) TREES NEARBY PAPI RWY 07R RDL223/0.18NM THR 07R :
- -PSN: 482627N 0042630W
- -HEIGHT : 46FT
- -ELEV : 326FT -LIGHTING : NIL.

OBSTACLE ERECTED

P1712/23 NOTAMN

- Q) LFRR/QOBCE/IV/M /A /000/999/4827N00425W005
- A) LFRB B) 2305031013 C) 2305242359
- E) OBSTACLE : PYLON OPR RDL261.72/1.48NM LFRB ARP :

PSN: 482636.32N 0042730.53W

HEIGHT: 124.6FT ELEV : 390.4FT LIGHTING : NIL

OBSTACLE ERECTED

P1556/23 NOTAMR P3682/22

- Q) LFRR/QOBCE/IV/M /A /000/999/4827N00425W005
- A) LFRB B) 2304210648 C) 2307240600
- E) TWR CRANE OPR AT 'GUIPAVAS' RDL150/0.6NM LFRB ARP:
- PSN: 482619N 0042451W
- HGT: 142FT
- ELEV: 439FT
- LGT: NIGHT AND DAY

TAXIWAY OPERATING BUT CAUTION ADVISED DUE TO ..

- B1968/23 NOTAMR B1952/23
- Q) LFRR/QMRXX/IV/NBO/A /000/999/4827N00425W005
- A) LFRB B) 2305090712 C) 2306302359 E) TWY N RWY PROTECTION LGT (WIG WAG) U/S.

FIREFIGHTING AND RESCUE HOURS OF SERVICE ARE NOW

B1196/23 NOTAMN

- Q) LFRR/QFFAH/IV/BO /A /000/999/4827N00425W005
- A) LFRB B) 2303260000 C) 2306302359
- E) RFFS LEVELS AND HOURS OF OPS (EU STANDARDS):
- LVL 8 : O/R OR ACCORDING TO SKED
- LVL 7 : MON-SUN 0345-2100
- LVL 5 : MON-SUN 2100-0345

RFFS LEVEL PROVIDED UNTIL LAST SKED FLIGHT ARRIVAL,

ANIMAL STRIKE HAZARD PREVENTION PROVIDED H24.

DECLARED DISTANCES CHANGED

B0796/23 NOTAMR B0787/23

- Q) LFRR/QMDCH/IV/NBO/A /000/999/4827N00425W005
- A) LFRB B) 2302281316 C) PERM
- E) RWY 07R/25L REVISED INTERMEDIATE DECLARED DISTANCES ON REMAINING DISTANCES SIGNPOSTS AT HOLDING POINTS C2, D2 AND E2 (TWY C, D AND E):
- RWY 07R : READ TWY C TORA=1814, TODA=1814, ASDA=1814

TWY D - TORA=1419, TODA=1419, ASDA=1419

- TWY E TORA=1169, TODA=1169, ASDA=1169
- RWY 25L : READ TWY C TORA=1308, TODA=1308, ASDA=1308

TWY D - TORA=1701, TODA=1701, ASDA=1701 TWY E - TORA=1946, TODA=1946, ASDA=1946.

RUNWAY

B0795/23 NOTAMR B0786/23

- Q) LFRR/QMRXX/IV/NBO/A /000/999/4827N00425W005
- A) LFRB B) 2302281314 C) PERM
- E) HOLDING POINTS RWY 07R/25L MODIFIED:

- TWY C:

- . NAME OF HOLDING POINT CAT III : C1
- . NAME OF HOLDING POINT OTHER OPERATION : C2

(NEW TODAY)

NOTAMs: Page 5 of 30

```
- TWY D :
```

- . NAME OF HOLDING POINT CAT III : D1
- . NAME OF HOLDING POINT OTHER OPERATION : D2
- TWY E :
- . NAME OF HOLDING POINT CAT III : E1
- . NAME OF HOLDING POINT OTHER OPERATION : E2.

INSTRUMENT APPROACH PROCEDURE LIMITED TO

B0179/23 NOTAMN

- Q) LFRR/QPILT/I /NBO/A /000/999/4827N00425W005
- A) LFRB B) 2301181306 C) PERM
- E) RNP RWY 07R : PROCEDURE FORBIDDEN BY NIGHT WHEN PAPI OUT OF

SERVICE

REF AD2 LFRB IAC RWY07R RNP

Enroute airport

LFRU - Ploujean

OBSTACLE ERECTED

P0996/23 NOTAMN

- Q) LFRR/QOBCE/IV/M /A /000/999/4836N00349W005
- A) LFRU B) 2303230600 C) 2308312359
- E) OBST : TOWER CRANE ERECTED AT 'MORLAIX' RDL180/0.31NM LFRU ARP :
- -PSN : 483548N 0034853W
- -HEIGHT : 95FT -ELEV : 380FT
- -LIGHTING : DAY AND NIGHT.

Enroute airport

LFRT - Armor

METEOROLOGICAL SERVICE

C1049/23 NOTAMN

- Q) LFRR/QFMXX/IV/NBO/A /000/999/4832N00251W005
- A) LFRT B) 2304060000 C) 2310010000
- E) AUTO METAR AVBL H24

PARKING AREA PRKG LIMITED TO

C1031/23 NOTAMN

- Q) LFRR/QMKLT/IV/M /A /000/999/4832N00251W005
- A) LFRT B) 2304031924 C) 2306021800
- E) COMMERCIAL PRKG AREA PROHIBITED TO ACFT OF LESS THAN 2 TONS.

TAXIWAY CLOSED

C0795/23 NOTAMR C4145/22

- Q) LFRR/QMXLC/IV/BO /A /000/999/4832N00251W005
- A) LFRT B) 2303171524 C) 2306222359
- E) TWY C CLOSED.

Enroute airport

LFRD - Pleurtuit-St. Malo

No relevant Notams found

Enroute airport

LFOV - Entrammes

AERODROME FLIGHT INFORMATION SERVICE HOURS OF SERVICE ARE NOW

C1170/23 NOTAMR C0959/23

- Q) LFRR/QSFAH/IV/BO /A /000/999/4802N00045W005
- A) LFOV B) 2304141241 C) 2306252359
- E) AFIS HOURS OF OPS :

MON-FRI 0600-1000 1200-1500

EXC APR 17 24 : 1200-1500: AFIS PROVIDED

EXC MAY 01 03 08 18 29 : AFIS NOT PROVIDED

Enroute airport

LFRK - Carpiquet

VOR UNSERVICEABLE F0755/23 NOTAMN

- Q) LFRR/QNVAS/IV/BO /AE/000/999/4910N00027W025
- A) LFRK B) 2305090700 C) 2305111500
- E) VOR CAN 114.45MHZ U/S DUE TO MAINT: DO NOT USE, POSSIBLE FALSE INDICATIONS.

DME CAN REMAINS AVBL.

INSTRUMENT LANDING SYSTEM UNSERVICEABLE

C1340/23 NOTAMN

- Q) LFRR/QICAS/I /NBO/A /000/999/4910N00027W005
- A) LFRK B) 2305041621 C) 2305141600
- E) ILS 31 U/S

NOTAMs: Page 6 of 30

(NEW TODAY)

DME ASSOCIATED WITH ILS UNSERVICEABLE

C1339/23 NOTAMR C1326/23

- Q) LFRR/QIDAS/I /NBO/A /000/999/4910N00027W005
- A) LFRK B) 2305041510 C) 2305141601
- E) LDG DME 31 U/S DUE TO MAINT :
- DO NOT USE BECAUSE POSSIBLE FALSE INDICATIONS.

INSTRUMENT APPROACH PROCEDURE CHANGED

C1227/23 NOTAMN

- Q) LFRR/QPICH/I /NBO/A /000/999/4910N00027W005
- A) LFRK B) 2304250000 C) PERM
- E) PROCEDURES CAN BE CARRIED OUT EVEN OUTSIDE DEAUVILLE APCH HOURS.

HOLDING 'XASUD' LIMITED TO MAX LEVEL 4000

REF :

AD2 LFRK IAC RWY13 RNP

AD2 LFRK IAC RWY31 RNP

AERODROME LIMITED TO

C0827/23 NOTAMN

- Q) LFRR/QFALT/IV/NBO/A /000/999/4910N00027W005
- A) LFRK B) 2304010300 C) 2307012359
- E) ARRIVAL AND DEPARTURE SUBJECT TO PPR 24HR FOR ALL NON-SKED

FLIGHTS,

WHICH REQUIRING PARKING AND/OR POSSIBLE INTERVENTION OF AD

ADMINISTRATION.

EXC BASED ACFT, SANITARY FLIGHTS AND TOUCH AND GO.

PPR TO BE REQUESTED FROM AEROTRAFIC (AT) CAEN.CCI.FR

ANY ACFT THAT DOES NOT MEET THESE CRITERIA AND DOES NOT HAVE PPR

NUMBER, WILL NOT BE ALLOWED BY ATC SERVICES.

FOR ANY ACFT HOSTED IN THE PARKING OF AN AD USER, AND NOT REQUIRING ANY INTERVENTION BY AD ADMINISTRATION, MANDATORY NOTICE REDUCED TO

2HR.

INFO TO BE SENT TO:

AEROTRAFIC (AT) CAEN.CCI.FR

AND CAEN. TOUR (AT) AVIATION-CIVILE. GOUV. FR

Enroute airport

LFRM - Arnage

FIREFIGHTING AND RESCUE HOURS OF SERVICE ARE NOW

C1261/23 NOTAMN

- Q) LFFF/QFFAH/IV/BO /A /000/999/4757N00012E005
- A) LFRM B) 2305010000 C) 2305312359
- E) RFFS HOURS OF OPS :

-LEVEL 1 : MON-FRI : 1030-1130

-LEVEL 5 : MON-FRI : 0700-1030 1130-1600

HOURS EXTENSIONS AND LEVEL 5 POSSIBLE ON REQUEST THE DAY BEFORE

BEFORE 1500 BY EMAIL TO : AEROPORT(AT)LEMANS.CCI.FR

AERODROME LIMITED TO

C0828/23 NOTAMN

- Q) LFFF/QFALT/IV/NBO/A /000/999/4757N00012E005
- A) LFRM B) 2303210501 C) 2306212032
- D) SS-SR
- E) BY NIGHT ARRIVING FORBIDDEN FOR RWY 02.

PRECISION APPROACH PATH INDICATOR UNSERVICEABLE

C0829/23 NOTAMN

- Q) LFFF/QLPAS/IV/BO /A /000/999/4757N00012E005
- A) LFRM B) 2303210000 C) 2306212359
- E) PAPI RWY 02 U/S.

Enroute airport

LFOE - Fauville

OBSTACLE ERECTED

P0534/23 NOTAMR P4020/22

- Q) LFFF/QOBCE/IV/M /A /000/999/4902N00113E005
- A) LFOE B) 2302130827 C) 2305130800
- E) OBST: CRANE OPR ON EAST SIDE RDL 173/0.5NM LFOE ARP:

PSN : 490116.4N 0011317.7E

ELEV : 507FT HEIGHT : 62FT

LIGHTING: DAY AND NIGHT

AERODROME LIMITED TO

(NEW TODAY)

M1294/23 NOTAMN

- Q) LFFF/QFALT/IV/NBO/A /000/999/4902N00113E005
- A) LFOE B) 2305100600 C) 2305101500
- E) AD CANNOT BE USED AS AN ALTERNATE AD (ELECTRIC POWER NOT SUPPLIED).

NOTAMs: Page 7 of 30

SURVEILLANCE RADAR ELEMENT OF PRECISION APPROACH RADAR SYSTEM UNSERVICEABLE

M1233/23 NOTAMR M0877/23

- Q) LFFF/QCRAS/I /BO /A /000/999/4902N00113E005
- A) LFOE B) 2304270707 C) 2307270600
- E) ALADIN RADAR APP U/S. ARRIVALS AND DEPARTURES PROC OAT I POSSIBLE ONLY WITH AGREEMENT ROISSY MILITARY CONTROL DETACHMENT EACA ROISSY. (811 487 2983 OR +33(0) 6 72 79 62 42) .

TAXIWAY CLOSED

M1228/23 NOTAMR M0281/23

- Q) LFFF/QMXLC/IV/BO /A /000/999/4902N00113E005
- A) LFOE B) 2304261519 C) 2307261500
- E) BRETELLE DELTA ENTRE LA PISTE ET LE TAXIWAY ALPHA INUTILISABLE

INSTRUMENT APPROACH PROCEDURE LIMITED TO

M1048/23 NOTAMR M0062/23

- Q) LFFF/QPILT/I /NBO/A /000/999/4902N00113E005
- A) LFOE B) 2304071122 C) 2307071100
- E) FINAL VOR RWY22 UNUSABLE.

BEARING STRENGTH CHANGED

M0678/23 NOTAMN

- Q) LFFF/QMBCH/IV/BO /A /000/999/4902N00113E005
- A) LFOE B) 2303081547 C) 2306081600
- E) NEW RWY PCN : 65/F/W/B/T.

RUNWAY ARRESTING GEAR UNSERVICEABLE

M0422/23 NOTAMR M3443/22

- Q) LFFF/QMHAS/IV/NBO/A /000/999/4902N00113E005
- A) LFOE B) 2302130851 C) 2305130800
- E) ARRESTING CABLE U/S.

AERODROME CHANGED

M0421/23 NOTAMR M3673/22

- Q) LFFF/QPMCH/I /NBO/A /000/999/4902N00113E005
- A) LFOE B) 2302130850 C) 2305130800
- E) TKOF PROC MINIMA ENHANCED TO 550M DUE TO FAILURE OF THE OBLIGATION PANELS.

VOR UNSERVICEABLE (NEW TODAY)

F0716/23 NOTAMN

- Q) LFFF/QNVAS/IV/BO /AE/000/999/4902N00113E025
- A) LFOE B) 2305090800 C) 2305101600
- E) VORTAC EVX, VOR PART 112.400MHZU/S DUE TO MAINT :
- DO NOT USE, POSSIBLE FALSE INDICATIONS

Enroute airport

LFPV - Velizy

OBSTACLE ERECTED

P1663/23 NOTAMN

- Q) LFFF/QOBCE/IV/M /A /000/999/4846N00211E005
- A) LFPV B) 2305050600 C) 2307281600
- D) 0600-1600
- E) CRANE OPR AT 'MEUDON' RDL046/1.22NM ARP LFPV:

PSN : 484720N 0021302E

ELEV: 744FT

HGT: 160FT

LGT : DAY AND NIGHT.

OBSTACLE ERECTED

P1345/23 NOTAMN

- Q) LFFF/QOBCE/IV/M /A /000/999/4846N00211E005
- A) LFPV B) 2304110600 C) 2305161600
- D) 0600-1600
- E) OBST : EXCAVATOR ON 'STELLANTIS' SITE ('ROUTE DE GISY') RDL

099/1NM LFPV ARP :

- PSN : 484619N 0021321E
- ELEV : 605FT
- HGT : 35FT

- LGT : DAY.

NOTAMs: Page 8 of 30

STANDARD INSTRUMENT DEPARTURE

M3547/22 NOTAMN

- Q) LFFF/QPDCS/I /BO /A /000/999/4846N00211E005
- A) LFPV B) 2212290000 C) 2306142359
- E) DECOMMISSIONING OF VOR PTV AIRAC AIP SUP 263/22:

OBJECT : MODIFICATION OF CONVENTIONAL DEPARTURES FROM

'VILLACOUBLAY'.

THIS AIP SUP IS AVBL AT WWW.SIA.AVIATION-CIVILE.GOUV.FR

AERODROME CLOSED (NEW TODAY)

M1269/23 NOTAMN

- Q) LFFF/QFALC/IV/NBO/A /000/999/4846N00211E005
- A) LFPV B) 2305090600 C) 2305101800
- D) 0600-1800
- E) TERRAIN FERME CAUSE MAINTENANCE, DIRECTEUR DES VOLS JOIGNABLE UNIQUEMENT AU 06.70.31.97.70.

AERODROME LIMITED TO

M1236/23 NOTAMN

- Q) LFFF/QFALT/IV/NBO/A /000/999/4846N00211E005
- A) LFPV B) 2304270742 C) 2307270600
- E) LFOE APP DOES NOT PROVIDE OAT ARRIVAL AND DEPARTURE FOR LFPV AD.

AERODROME LIMITED TO

M1004/23 NOTAMN

- Q) LFFF/QFALT/IV/NBO/A /000/999/4846N00211E005
- A) LFPV B) 2304062100 C) 2307050530
- D) 2100-0530
- E) CAUSE NOISE POLLUTION, ENGINE TESTS SUBJECT TO AUTHORIZATION FROM THE FLIGHT DIRECTOR. THEY ARE **PROHIBITED** BEYOND 30 MIN BEFORE TKOF AND 30 MIN AFTER ARRIVAL. DEROGATION ONLY FOR FLIGHT SAFETY REASONS.

INSTRUMENT APPROACH PROCEDURE CHANGED

M0864/23 NOTAMN

- Q) LFFF/QPICH/I /NBO/A /000/999/4846N00211E005
- A) LFPV B) 2303240825 C) 2306232359
- E) RNP RWY09 INCREASED (MIAC2/AIP AD2) :
- READ CAT A, B MDA(H) 1010(430) RVR 1500
- INSTEAD OF MDA(H) 990(410) RVR 1500
- READ CAT C MDA(H) 1010(430) RVR 1600
- INSTEAD OF MDA(H) 990 (410) RVR 1500
- READ MVL CAT A, B(H) 1220(640)
- INSTEAD OF 1200(620)
- READ MVL CAT C(H) 1320(740)
- INSTEAD OF 1300(710)
- RNP RWY27 INCREASED (MIAC2/AIP AD2) :
- READ MVL CAT A, B MDA(H) 1220(640)
- INSTEAD OF 1200(620)
- READ MVL CAT C MDA(H) 1320(740)
- INSTEAD OF 1300(710)

VPT Y/Z RWY09 AND RWY27 INCREASED (MIAC2/AIP AD2) :

- READ MVL CAT A, B(H) 1220(640)
- INSTEAD OF 1200(620)
- READ MVL CAT C(H) 1320(740)
- INSTEAD OF 1300(710).

Enroute airport

LFPO - Orly

OBSTACLE ERECTED

- P2940/22 NOTAMN
- Q) LFFF/QOBCE/IV/M /A /000/999/4843N00223E005
- A) LFPO B) 2209070600 C) 2309061800
- E) OBST : TOWER CRANE : RDL 282/3.81NM LFPO ARP :
- PSN : 484413N 0021708E
- HEIGHT : 131FT
- ELEV : 395FT
- LIGHTING : DAY AND NIGHT.

OBSTACLE CHANGED

- P1439/23 NOTAMR P1083/23
- O) LFFF/OOBCH/IV/M /A /000/999/4843N00223E005
- A) LFPO B) 2304130923 C) PERM
- E) OBST 9 WEST OF RWY 06/24 ELEV : READ 98 INSTEAD OF 113.

REF AD 2 LFPO AOC RWY 06/24

NOTAMs: Page 9 of 30

OBSTACLE ERECTED

P1170/23 NOTAMN

- Q) LFFF/QOBCE/IV/M /A /000/999/4843N00223E005
- A) LFPO B) 2303311700 C) 2305311700
- E) TOWER CRANE NEAR HLP 'MASSY CENTRE HOSPITALIER' RDL 275/3.2NM LFPO ARP :
- PSN : 484341N 0021756E
- HEIGHT : 95FT
- ELEVATION : 384FT
- LIGHTING : DAY AND NIGHT.

STANDARD INSTRUMENT DEPARTURE CHANGED

A5536/22 NOTAMN

- Q) LFFF/QPDCH/I /NBO/A /000/999/4843N00223E005
- A) LFPO B) 2211181513 C) 2312292300
- E) REF AD 2 LFPO SID RWY06-07 CONV PTV MONOT DORDI INSTR 01 CHANGED: FOR CONV PTV AND MONOT 9F- 9H DEPARTURE FRENCH VERSION, READ 'AT D 6.5 LOL (OR 9.0 ORE) TO THE RIGHT RDL 245 DEG CLM (MAG 245 DEG) 'INSTEAD OF 'A D 6.5 LOL (OR 6.3 OLW) RDL 245 DEG CLM (MAG 245 DEG)'FOR CONV DEPARTURE PTV AND MONOT 9E-9G, ENGLISH VERSION, READ 'AT D 6.3 OLW (OR D 6.5 LOL) TO THE RIGHT RDL 245 DEG CLM (MAG 245 DEG)'INSTEAD OF 'AT D 6.3 OLW (OR D 6.5 LOL) RIGHT RDL 245 DEG MLN (MAG 245 DEG)'

FOR CONV PTV AND MONOT DEPARTURE 9F-9H ENGLISH VERSION, READ 'AT D 6.5 LOL (OR D 9.0 ORE) TO THE RIGHT RDL 245 DEG CLM (MAG 245 DEG)' INSTEAD OF 'AT D 6.5 LOL (OR D 6.3 OLW) TO THE RIGHT RDL 245 DEG MLN (MAG 245 DEG)'

STANDARD INSTRUMENT DEPARTURE INSTALLED

A5515/22 NOTAMN

- Q) LFFF/QPDCS/I /BO /A /000/999/4843N00223E005
- A) LFPO B) 2212290000 C) 2306142359
- E) DECOMMISSIONING OF VOR PTV AIRAC AIP SUP 259/22: SUBJECT: MODIFICATION OF CONVENTIONAL DEPARTURES FROM 'PARIS ORLY'. THIS AIP SUP IS AVBL AT WWW.SIA.AVIATION-CIVILE.GOUV.FR

INSTRUMENT LANDING SYSTEM UNSERVICEABLE

A2268/23 NOTAMN

- Q) LFFF/QICAS/I /NBO/A /000/999/4843N00223E005
- A) LFPO B) 2305020730 C) 2308030400
- E) ILS RWY 06 U/S

AERONAUTICAL INFORMATION SERVICE

A2230/23 NOTAMN

- Q) LFFF/QPIAU/I /NBO/A /000/999/4843N00223E005
- A) LFPO B) 2305020400 C) 2305252359
- E) AIRAC AIP SUP 029/23 : PHASE 2 ACT

INSTRUMENT LANDING SYSTEM UNSERVICEABLE

A2113/23 NOTAMN

- Q) LFFF/QICAS/I /NBO/A /000/999/4843N00223E005
- A) LFPO B) 2304191700 C) 2305122359
- E) ILS RWY 24 U/S. DO NOT USE, POSSIBLE FALSE INDICATIONS.

DECLARED DISTANCES CHANGED

A2061/23 NOTAMN

- Q) LFFF/QMDCH/IV/NBO/A /000/999/4843N00223E005
- A) LFPO B) 2304200400 C) 2305252359
- E) NEW DECLARED DISTANCES RWY 06:

RWY 06 : TORA TODA ASDA LDA

3650 3710 3650 3320.

TAXIWAY CLOSED

A1869/23 NOTAMN

- Q) LFFF/QMXLC/IV/BO /A /000/999/4843N00223E005
- A) LFPO B) 2304102130 C) 2306230330
- E) TWY W2 FROM LS TO LU EXCLUDED CLSD, AND LT CLSD.

ILS CATEGORY II UNSERVICEABLE

A1729/23 NOTAMN

- Q) LFFF/QITAS/I /NBO/A /000/999/4843N00223E005
- A) LFPO B) 2304080000 C) 2307082200
- E) ILS RWY 07 CAT II AND CAT III U/S.

NOTAMs: Page 10 of 30

ILS CATEGORY III UNSERVICEABLE

A1683/23 NOTAMN

- Q) LFFF/QIUAS/I /NBO/A /000/999/4843N00223E005
- A) LFPO B) 2303311349 C) 2306302200
- E) -ILS RWY 24 CAT II AND CAT III NOT AVBL
- -TKOF RWY 24 WITH RVR BELOW OR EQUAL TO 150M PROHIBITED.

AERODROME LIMITED TO

A1667/23 NOTAMR A6132/22

- Q) LFFF/QFALT/IV/NBO/A /000/999/4843N00223E005
- A) LFPO B) 2303310830 C) 2310022130
- E) ORLY CAN NOT BE CHOSEN AS AN ALTERNATE AD FOR ACFT A380:

REF: AIP AD2 LFPO.AD2.20.3 AND GMC02 CHART.

MOVEMENT AREA MOV AREA LIMITED TO

A1664/23 NOTAMR A6129/22

- Q) LFFF/QMALT/IV/NBO/A /000/999/4843N00223E005
- A) LFPO B) 2303310810 C) 2310022130
- E) 'FOLLOW ME' SERVICE NOT PROVIDED

INSTRUMENT APPROACH PROCEDURE NOT AVAILABLE

A1025/23 NOTAMN

- Q) LFFF/QPIAU/I /NBO/A /000/999/4843N00223E005
- A) LFPO B) 2304200000 C) 2305252359
- E) RENEWAL WORKS ON RWY 06 ILS AIRAC AIP SUP 029/23 :

SUBJECT: UNAVAILABILITY OF IFR PROCEDURES AND AD USE RESTRICTIONS. WORKS CARRIED OUT IN 2 PHASES WHOSE ACTIVATION WILL BE ANNOUNCED BY NOTAM.

THIS AIP SUP IS AVBL AT WWW.SIA.AVIATION-CIVILE.GOUV.FR

INSTRUMENT APPROACH PROCEDURE CHANGED

A0888/23 NOTAMN

- Q) LFFF/QPICH/I /NBO/A /000/999/4843N00223E005
- A) LFPO B) 2303022159 C) 2309301600
- E) MINIMUMS OPS CHANGED, DUE TO CRANE:

- PROC LNAV 02 :

OCH MDA(H) RVR

CAT A B C D 393 690 (400) 1400

- PROC LNAV-VNAV 02:

OCH DA(H) RVR

CAT A 277 570(280) 900

CAT B 289 580(290) 900

CAT C 297 590(300) 900

CAT D 307 610(310) 900

REF : AD2 LFPO IAC RWY02 FNA RNP.

INSTRUMENT APPROACH PROCEDURE CHANGED

A0887/23 NOTAMN

- Q) LFFF/QPICH/I /NBO/A /000/999/4843N00223E005
- A) LFPO B) 2303022104 C) 2309301600
- E) OPERATING MINIMA OF PROC LOC 02 CHANGED DUE TO MOBILE CRANE:

ALL CATEGORIES:

OCH MDA(H) RVR

419 710 (420) 1500

REF: AD 2 LFPO IAC RWY02 FNA ILS CAT 1 LOC.

Enroute airport LFPM - Villaroche

OBSTACLE ERECTED

P1758/23 NOTAMN

- Q) LFFF/QOBCE/IV/M /A /000/999/4836N00240E005
- A) LFPM B) 2305090500 C) 2305121700
- D) 0500-1700
- E) MOBILE CRANE NEAR AD MELUN VILLAROCHE RDL193/0.47NM ARP:

PSN: 483551N 0024005E

HEIGHT : 91FT ELEV : 393FT LGT : DAY.

OBSTACLE ERECTED

P1396/23 NOTAMN

- Q) LFFF/QOBCE/IV/M /A /000/999/4836N00240E005
- A) LFPM B) 2304110500 C) 2305261700

NOTAMs: Page 11 of 30

(NEW TODAY)

```
D) MON-FRT 0500-1700
```

E) MOBILE CRANES OPR IN THE VICINITY OF LFPM AD - RDL211/0.46NM LFPM

- PSN: 483556N 0023953E

- HGT: 163FT

- ELEV: 462FT - LGT: DAY.

INSTRUMENT APPROACH PROCEDURE CHANGED

E4424/22 NOTAMN

- Q) LFFF/QPICS/I /BO /A /000/999/4836N00240E005
- A) LFPM B) 2212290000 C) 2309062359
- E) DECOMMISSIONING OF VOR PTV AIRAC AIP SUP 257/22:

SUBJECT : MODIFICATION OF CONVENTIONAL DEPARTURES AND ARRIVALS

PROCEDURES ON 'MELUN'.

THIS AIP SUP IS AVBL AT WWW.SIA.AVIATION-CIVILE.GOUV.FR

RUNWAY CLOSED (NEW TODAY)

E1798/23 NOTAMN

- Q) LFFF/QMRLC/IV/NBO/A /000/999/4836N00240E005
- A) LFPM B) 2305090700 C) 2305121600
- D) 0700-1600
- E) RWY 01/19 CLSD

Enroute airport

LFQB - Barberey

FIREFIGHTING AND RESCUE AVAILABLE ON REQUEST

C4221/22 NOTAMN

- Q) LFFF/QFFAR/IV/NBO/A /000/999/4819N00401E005
- A) LFQB B) 2212281444 C) PERM
- E) RFFS LEVEL 5 POSSIBLE ON REQUEST:

MON-FRI : PPR THE PREVIOUS DAY, BEFORE 1600

SAT-SUN : PPR ON FRI BEFORE 1600

PUBLIC HOLIDAYS : PPR ON THE LAST WORKING DAY, BEFORE 1600

Enroute airport

LFSG - Mirecourt

(NEW TODAY)

C1357/23 NOTAMN

- INSTRUMENT LANDING SYSTEM UNSERVICEABLE Q) LFEE/QICAS/I /NBO/A /000/999/4820N00604E005
- A) LFSG B) 2305091200 C) 2305121500
- E) ILS RWY 26 U/S DUE TO MAINT :
- DO NOT USE BECAUSE POSSIBLE FALSE INDICATIONS.

AERODROME LIMITED TO (NEW TODAY)

C1229/23 NOTAMN

- Q) LFEE/QFALT/IV/NBO/A /000/999/4820N00604E005
- A) LFSG B) 2305090600 C) 2305121600
- E) AD CIRCUITS AND IFR TRAINING O/R

DUE TO THE EVOLUTION OF 4 ACFT WITHIN LF-R87 FM SFC TO 2500FT AMSL

RUNWAY LIMITED TO

C0675/23 NOTAMN

- Q) LFEE/QMRLT/IV/NBO/A /000/999/4820N00604E005
- A) LFSG B) 2303071506 C) 2306071600
- E) DECLARED DISTANCES CHANGED: TORA RWY 08 FROM TWY B, 1025M

TAXIWAY CENTRE LINE LIGHTS UNSERVICEABLE

C0674/23 NOTAMN

- Q) LFEE/QLXAS/IV/M /A /000/999/4820N00604E005
- A) LFSG B) 2303071503 C) 2306071600
- E) TAXIWAYS D AND T3 LIGHTS U/S.

TAXIWAY LIMITED TO

C0673/23 NOTAMN

- Q) LFEE/QMXLT/IV/M /A /000/999/4820N00604E005
- A) LFSG B) 2303071455 C) 2306071600
- E) TAXIWAY F RESERVED TO AUTHORIZED PILOTS.

NOTAMs: Page 12 of 30

```
Enroute airport LFGA - Houssen

OBSTACLE ERECTED

P1612/23 NOTAMN
Q) LFEE/QOBCE/IV/M /A /000/999/4807N00722E005
A) LFGA B) 2305020500 C) 2305311600
E) TELESCOPIC MOBILE CRANE RDL 195.21/0.49NM THR 01:
PSN: 480547N 0072115E
ELEV: 741FT
HEIGHT: 114FT
LIGHTING BY DAY

CUSTOMS/IMMIGRATION LIMITED TO
```

```
C1263/23 NOTAMN
Q) LFEE/QFZLT/IV/NBO/A /000/999/4807N00722E005
A) LFGA B) 2304261020 C) 2307272359
E) CUSTOMS:
.FLIGHTS FROM/TO A COUNTRY OUTSIDE SCHENGEN AREA OR OUTSIDE EUROPEAN UNION:
MNM 24HR PN VIA MAIL AT: CODT-METZ(AT)DOUANE.FINANCE.GOUV.FR
-MON-FRI: AT LEAST THE DAY BEFORE 1600
-SAT SUN: AT LEAST THE FRIDAY BEFORE 1000
-MAY 01 08 18 29, JULLY 14: AT LEAST THE DAY BEFORE 1000
FORM AVAILABLE ON AD ADMINISTRATION WEBSITE
.FLIGHTS FROM/TO SWISS:
12HR PN VIA MAIL AT: CODT-METZ(AT)DOUANE.FINANCE.GOUV.FR
FORM AVAILABLE ON AD ADMINISTRATION WEBSITE.
```

INSTRUMENT APPROACH PROCEDURE CHANGED

```
C1236/23 NOTAMN

Q) LFEE/QPICH/I /NBO/A /000/999/4807N00722E005

A) LFGA B) 2305020500 C) 2305311600

D) MON-FRI 0500-1600 EXC MAY 08 18 29

E) PROC APCH FNA RNP RWY01, MINIMA LPV MODIFIED:

DA(H) CAT A: 880(250)

DA(H) CAT B: 890(260)

DA(H) CAT C: 900(270)

RVR CAT C: 900

OCH CAT A: 246

OCH CAT B: 258

OCH CAT C: 266
```

INSTRUMENT APPROACH PROCEDURE INSTALLED

C1137/23 NOTAMR C0669/22

- Q) LFEE/QPICS/I /NBO/A /000/999/4807N00722E005
- A) LFGA B) 2304121501 C) 2306142359
- E) OPERATIONAL EVALUATION OF THE RNP 261 PINS IFR PROCEDURE ON COLMAR HOSPITAL PASTEUR HELIPORT AIRAC AIP SUP 043/22 EXTENDED : THE PROVISIONS INCLUDED WITHIN THIS AIRAC AIP SUP ARE EXTENDED TIL 14 JUN 2359.

THIS AIP SUP IS AVBL AT WWW.SIA.AVIATION-CIVILE.GOUV.FR

VSS PROC LNAV AND LNAV/VNAV RWY01 BREAKTHROUGH OF 7.40M.

Enroute airport

LFSB - Basle-Mulhouse

```
INSTRUMENT APPROACH PROCEDURE NOT AVAILABLE A6190/22 NOTAMR A2952/22
```

- Q) LFEE/QPIAU/I /NBO/A /000/999/4735N00732E005
- A) LFSB B) 2212300727 C) 2306302359
- E) INSTRUMENT APPROACH PROCEDURE RNAV GNSS RWY33 NOT AVAILABLE

REF AIP FRANCE : AD 2 LFSB IAC RWY33 RNP.

INSTRUMENT APPROACH PROCEDURE LIMITED TO

A6189/22 NOTAMR A2953/22

- Q) LFEE/QPIAU/I /NBO/A /000/999/4735N00732E005
- A) LFSB B) 2212300725 C) 2306302359
- E) INSTRUMENT APCH ILS Y CAT 1 OR LOC Y RWY33 SUSPENDED REF AIP FRANCE: AD2 LFSB IAC RWY33 FNA-ILS Y CAT 1 LOC Y.

STANDARD INSTRUMENT DEPARTURE NOT AVAILABLE

A6188/22 NOTAMR A2957/22

- Q) LFEE/QPDAU/I /NBO/A /000/999/4735N00732E005
- A) LFSB B) 2212300724 C) 2306302359
- E) FOLLOWING SID ARE SUSPENDED:

RWY 15 LASAT 7S

RWY 33 LASAT 7N

PLANNING THOSE SID IS PROHIBITED

REF : AD2 LFSB SID RWY 15 RNAV

AD2 LFSB SID RWY 33 RNAV.

NOTAMs: Page 13 of 30

STANDARD INSTRUMENT DEPARTURE CHANGED

A5362/22 NOTAMN

- Q) LFEE/QPDTT/I /BO /A /000/999/4735N00732E005
- A) LFSB B) 2301010000 C) 2307122359
- E) EXTENSION OF MODIFICATION, ON AN EXPERIMENTAL BASIS, OF THE RWY
- 15 RNAV SID TOWARDS 'TORPA' AND 'MOROK' AIRAC AIP SUP 252/22 :

THIS AIP SUP IS AVBL AT WWW.SIA.AVIATION-CIVILE.GOUV.FR

INSTRUMENT LANDING SYSTEM UNSERVICEABLE

A2423/23 NOTAMN

- Q) LFEE/QICAS/I /NBO/A /000/999/4735N00732E005
- A) LFSB B) 2305090630 C) 2305101530
- D) 0630-1530
- E) IN CASE OF VISIBILITY MORE THAN 1500M, ILS RWY 15 U/S DUE TO MAINT :

DO NOT USE, POSSIBLE FALSE INDICATIONS.

RUNWAY CLOSED

A2352/23 NOTAMN

- Q) LFEE/QMRLC/IV/NBO/A /000/999/4735N00732E005
- A) LFSB B) 2305022200 C) 2307010300
- D) MON-FRI 2200-0300
- E) RWY 07/25 AND 15/33 CLSD

AERODROME LIMITED TO

A2280/23 NOTAMR A5972/22

- Q) LFEE/QFALT/IV/NBO/A /000/999/4735N00732E005
- A) LFSB B) 2304271310 C) 2306170300
- E) PAVEMENT REHABILITATION WORKS ON TAXIWAY BRAVO AIRAC AIP SUP 277/22:

SUBJECT: RESTRICTION OF THE USE OF BALE-MULHOUSE AD.

THE OPERATIONS WILL BE CARRIED OUT IN THREE PHASES, ALL OF THEM ACTIVATED BY NOTAM.

THE PROVISIONS CONTAINED IN THIS AIRAC AIP SUP 277/22 ARE EXTENDED TIL JUN 17, 2023.

THIS AIP SUP IS AVBL AT WWW.SIA.AVIATION-CIVILE.GOUV.FR

TAXIWAY CLOSED

A2239/23 NOTAMN

- Q) LFEE/QMXLC/IV/BO /A /000/999/4735N00732E005
- A) LFSB B) 2304252323 C) 2305200300
- E) SUP AIP 277/22 : PHASE 2 ACTIVATED.

INSTRUMENT APPROACH PROCEDURE CHANGED

A2235/23 NOTAMN

- Q) LFEE/QPIXX/I /NBO/A /000/999/4735N00732E005
- A) LFSB B) 2304251158 C) PERM
- E) PROC APCH VPT A RWY25:
- -FLW REMARK ADDED :

BY NIGHT, THE VERY BRIGHT URBAN ENVIRONMENT CAN HIDE THE RWY 25 INFRASTRUCTURE TIL THE ENTRY IN A SECTOR OF 15 DEGREES RELATIVE TO THE AXIS

-REMARK (4) WITHDRAWN

REF AIP : AD 2 LFSB IAC RWY25 VPT A

AERODROME

A1497/23 NOTAMN

- Q) LFEE/QFAXX/IV/NBO/A /000/999/4735N00732E005
- A) LFSB B) 2303260100 C) 2306142359
- E) REF : AD2 LFSB AD2.21.1.3.1 AIRCRAFT MOVEMENTS

PARAGRAPH D) AND E)

READ: BTN 2200 AND 2300 (SUMMER:-1HR) INSTEAD OF 2100 AND 2200

AERODROME LIMITED TO

A1196/23 NOTAMN

- Q) LFEE/QFALT/IV/NBO/A /000/999/4735N00732E005
- A) LFSB B) 2303180400 C) 2305200300
- E) AD CANNOT BE CHOOSEN AS A DIVERTED AD, EXC FOR ACFT OF WINGSPAN LESS THAN 36M.

(NEW TODAY)

NOTAMs: Page 14 of 30

Enroute airport

LSZH - Zurich

AERODROME LIMITED TO

A0317/22 NOTAMN

- Q) LSAS/QFALT/IV/NBO/A/000/999/4727N00833E005
- A) LSZH B) 2205280500 C) PERM
- E) REINTRODUCTION OF CROSSING RWY OPERATIONS DRG LDG RWY 34. DEPARTURE PRIORITY WINDOW OPERATIONS (PRIDEP) SUSPENDED.

TAXIWAY CLOSED

A0233/23 NOTAMR A0201/23

- Q) LSAS/QMXLC/IV/BO/A/000/999/4727N00833E005
- A) LSZH B) 2305021239 C) 2305162359
- E) MAINT AREA TWY ${\hbox{\bf CLSD}}$ ABM HANGAR 3 DUE TO WIP. AREA MARKED AND LGTD. STAND D15/D16/D17 TEMPO USED AS BYPASS BTN TWY M AND TWY E. USE OF ACFT HYR THAN CODE C WITH MARSHALLER ONLY.

PARKING AREA PRKG LIMITED TO

A0160/23 NOTAMN

- Q) LSAS/QMKLT/IV/M/A/000/999/4727N00833E005
- A) LSZH B) 2304120400 C) 2306302359
- E) COMPASS COMPENSATION PSN AT GA SECTOR 9 CLSD DUE TO WIP.

AREA MARKED AND LGTD.

TAXIWAY CLOSED

A0161/23 NOTAMN

- O) LSAS/OMXLC/IV/BO/A/000/999/4727N00833E005
- A) LSZH B) 2304120400 C) 2306302359
- E) TWY R CLSD BTN TWY R7 AND GA SECTOR 9 DUE TO WIP.

AREA MARKED AND LGTD.

AIRCRAFT STANDS CLOSED

A0159/23 NOTAMN

- Q) LSAS/QMPLC/IV/BO/A/000/999/4727N00833E005
- A) LSZH B) 2304120400 C) 2306302359
- E) ACFT STANDS W04, W05 AND W23 CLSD DUE TO WIP.

AREA MARKED AND LGT.

TAXIWAY CLOSED

A0133/23 NOTAMN

- Q) LSAS/QMXLC/IV/BO/A/000/999/4727N00833E005
- A) LSZH B) 2304110001 C) 2310282359 EST
- E) TWY E **CLSD** BTN TWY D AND LINK 7 DUE TO WIP, AREA MARKED AND LGT.

TWY LINK 6 AND LINK 7 CLSD DUE TO WIP, AREA LGT.

TAXIWAY CLOSED

A0134/23 NOTAMN

- Q) LSAS/QMXLC/IV/BO/A/000/999/4727N00833E005
- A) LSZH B) 2304110001 C) 2310282359 EST
- E) FOR LDG RWY 34 VACATING VIA TWY E5 OR TWY B ONLY WITH ATC CLR, OTHERWISE VIA TWY E3 OR E2.

TWY E4 CLSD DUE TO WIP. AREA MARKED AND LGT.

TAXIWAY LIMITED TO

A0135/23 NOTAMN

- Q) LSAS/QMXLT/IV/M/A/000/999/4727N00833E005
- A) LSZH B) 2303270001 C) 2306012359
- E) TWY MAINT AREA SELFPOWER MOV OF ACFT WITH MAX CODE C.

RUNWAY CLOSED

A0131/23 NOTAMN

- Q) LSAS/QMRLC/IV/NBO/A/000/999/4727N00833E005
- A) LSZH B) 2303262100 C) 2306020400
- D) SUN-THU 2100-2359

MON-FRI 0000-0400

E) RWY 16/34 CLSD AFT LAST SKED FLT. ACTUAL CLOSURE BCST ON ATIS.

RUNWAY CLOSED

A0132/23 NOTAMN

- Q) LSAS/QMRLC/IV/NBO/A/000/999/4727N00833E005
- A) LSZH B) 2303262100 C) 2308250400 EST
- D) SUN-THU 2100-2359

MON-FRI 0000-0400

E) RWY 10/28 CLSD AFT LAST SKED FLT. ACTUAL CLOSURE BCST ON ATIS.

NOTAMs: Page 15 of 30

Enroute airport

LSZR - Altenrhein

STANDARD INSTRUMENT ARRIVAL LIMITED TO

B1546/21 NOTAMR B1409/21

- Q) LSAS/QPALT/I/NBO/A/000/999/4729N00934E005
- A) LSZR B) 2111220949 C) PERM
- E) STAR KPT 3H:

KPT DVOR/DME 108.40 FIELD STRENGTH INSUFFICIENT AFT ZR612.

EXP RADAR VECTORS TO IAF.

RUNWAY LIMITED TO

B0516/23 NOTAMN

- Q) LSAS/QMRLT/IV/NBO/A/000/999/4729N00934E005
- A) LSZR B) 2304250430 C) 2306301900
- E) ASPH RWY 10/28 GROOVING PARTIALLY MIS.

AERODROME LIMITED TO

B0513/23 NOTAMR B0511/23

- Q) LSAS/QFALT/IV/NBO/A/000/999/4729N00934E005
- A) LSZR B) 2304240749 C) 2305312359 EST
- E) ELECTRIC CHARGING STN U/S.

Enroute airport

EDJA - Memmingen

METEOROLOGICAL SERVICE LIMITED TO

C1455/23 NOTAMR C1452/23

- Q) EDMM/QFMLT/IV/BO /A /000/999/4759N01014E005
- A) EDJA B) 2305080638 C) 2305151000EST
- E) CEILING MEASUREMENT EQPT U/S. VIS AND RVR VALUES NOT AVBL.

TAXIWAY EDGE LIGHTS (UNSERVICEABLE

C1180/23 NOTAMR C0091/23

- Q) EDMM/QLYAS/IV/M /A /000/999/4759N01014E005
- A) EDJA B) 2304081204 C) 2307081200 EST
- E) TWY P EDGE LIGHTS U/S.

Enroute airport

LOWI - Innsbruck

OBSTACLE ERECTED

A0964/23 NOTAMN

- Q) LOVV/QOBCE/IV/M /A /000/999/4716N01121E005
- A) LOWI B) 2304250639 C) 2307240800 EST
- E) CRANE ERECTED AT POSITION 471620N 112308E (SCHULGASSE 6)

ELEVATION 650M/2133FT

HEIGHT ABOVE GROUND 32M/105FT

OBST DAY MARKED YES

OBST NIGHT MARKED YES

OBSTACLE ERECTED

A0931/23 NOTAMR A0930/23

- Q) LOVV/QOBCE/IV/M /AE/000/999/4716N01123E005
- A) LOWI B) 2304201433 C) 2407140800EST
- E) AD LOWI:

CRANE ERECTED AT PSN: 471616N 0112250E (HINTERWALDNERSTRASSE 6)

ELEV: 678M/2225FT AMSL

HEIGHT ABOVE GND: 31M/102FT AGL

OBST DAY MARKED: YES OBST NIGHT MARKED: YES

Enroute airport

EDMO - Oberpfaffenhofen

AERODROME

C0791/23 NOTAMN

- Q) EDMM/QFAXX/IV/NBO/A /000/999/4805N01117E005
- A) EDMO B) 2303091700 C) PERM
- E) VFR TFC EXPECT DLA DURING TESTING PHASE OF REMOTE TWR.

Enroute airport

LOWS - Salzburg

TAXIWAY LIMITED TO

A1075/23 NOTAMN

- Q) LOVV/QMXLT/IV/M /A /000/999/4748N01300E005
- A) LOWS B) 2305080400 C) 2305122300
- E) TWY D AND TWY L BETWEEN EXIT 3 AND EXIT 4 LIMITED UP TO CODE C A/C DUE TO WIP

NOTAMs: Page 16 of 30

A0936/23 NOTAMN

- Q) LOVV/QICAS/I /NBO/A /000/999/4748N01300E005
- A) LOWS B) 2305100700 C) 2305101300
- E) ILS OES 109,90 MHZ RWY 15 ON MAINTENANCE DUE TO CALIBRATION FLT.
- IN CASE OF LOW VISIBILITY MAINTENANCE WILL BE SUSPENDED AND ILS

WILL PERFORM TO CAT III.

Enroute airport

LOWL - Linz

OBSTACLE ERECTED

A1064/23 NOTAMN

- Q) LOVV/QOBCE/IV/M /A /000/999/4814N01411E005
- A) LOWL B) 2305080500 C) 2305261400
- E) CRANE ERECTED AT HOERSCHING

PSN: 1222M EAST OF THR RWY08 AND 1700M SOUTH OF RCL

MAX HEIGHT ABOVE GND 36M/118FT

ELEVATION 324M/1063FT AMSL

OBST DAY AND NIGHT MARKED

OBSTACLE ERECTED

A1040/23 NOTAMR A0348/23

- Q) LOVV/QOBCE/IV/M /A /000/999/4814N01411E005
- A) LOWL B) 2305030645 C) 2307311400 EST
- E) CRANES ERECTED AT PASCHING

PSN: 395M WEST OF THR RWY26 AND 2523M NORTH OF RCL

MAX HEIGHT ABOVE GND 25M/82FT

ELEVATION 323M/1060FT

OBST DAY AND NIGHT MARKED

FUEL AVAILABILITY NOT AVAILABLE

A0950/23 NOTAMR A0670/23

- Q) LOVV/QFUAU/IV/NBO/A /000/999/4814N01411E005
- A) LOWL B) 2304240805 C) 2307152100
- E) AVGAS NOT AVAILABLE

TAXIWAY CLOSED

A0898/23 NOTAMR A0243/23

- Q) LOVV/QMXLC/IV/M /A /000/999/4814N01411E005
- A) LOWL B) 2304180805 C) 2307111400 EST
- E) TWY C BTN RWY AND HOLDINGPOINT C CLSD

EXC AIR-TAXIING HELICOPTERS

OBSTACLE ERECTED

A0899/23 NOTAMR A0151/23

- Q) LOVV/QOBCE/IV/M /A /000/999/4814N01411E005
- A) LOWL B) 2304180803 C) 2307111400
- E) CRANE ERECTED AT HOERSCHING

PSN: 407M EAST OF THR RWY08 AND 743M SOUTH OF RCL

MAX HEIGHT ABOVE GND 45M/148FT

ELEVATION 335M/1100FT

OBST DAY AND NIGHT MARKED

FIREFIGHTING AND RESCUE CHANGED

A0764/23 NOTAMR A0401/23

- Q) LOVV/QFFCH/IV/NBO/A /000/999/4814N01411E005
- A) LOWL B) 2303310610 C) 2306290900 EST
- E) DURING OPERATIONAL HOURS FIREFIGHTING CAT 7 IS AVBL FOR SCHEDULED FLIGHTS APPRORIATE HIGHER CAT IS AVBL

OBSTACLE ERECTED

A0739/23 NOTAMN

- Q) LOVV/QOBCE/IV/M /A /000/999/4814N01411E005
- A) LOWL B) 2303291000 C) 2306211400EST
- E) CRANE ERECTED AT HOERSCHING

PSN: 1500M EAST OF THR RWY08 AND 1150M SOUTH OF RCL

MAX HEIGHT ABOVE GND 24M/79FT

ELEVATION 312M/1024FT

OBST DAY AND NIGHT MARKED

NOTAMs: Page 17 of 30

OBSTACLE ERECTED

A0604/23 NOTAMR A2828/22

- Q) LOVV/QOBCE/IV/M /A /000/999/4814N01411E005
- A) LOWL B) 2303141418 C) 2306071400 EST
- E) MOBILE CRANE ERECTED AT PASCHING

PSN: 990M WEST OF THR RWY26 AND 1330M NORTH OF RCL

MAX HEIGHT ABOVE GND 45M/147FT

ELEVATION 338M/1109FT

OBST DAY AND NIGHT MARKED

OBSTACLE ERECTED

A0518/23 NOTAMR A2821/22

- Q) LOVV/QOBCE/IV/M /A /000/999/4814N01411E005
- A) LOWL B) 2303020715 C) 2305301400EST
- E) CRANE ERECTED AT HOERSCHING

PSN: 927M EAST OF THR RWY08 AND 1350M SOUTH OF RCL

MAX HEIGHT ABOVE: GND 56M/184FT

ELEVATION: 350M/1149FT OBST DAY AND NIGHT MARKED

FIR CZQM

AIRCRAFT ENTRY REQUIREMENTS CHANGED

H0902/23 NOTAMR H0055/23

- Q) CZXX/QOECH/IV/NBO/E/000/999/5440N06941W999
- A) CZUL CZQM CZQX B) 2304111424 C) 2307111800EST
- E) ALL ACFT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL AIRSPACE (INCLUDING FLT WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG. ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVENED.

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CANADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION (AT) TC.GC.CA.

VOR UNSERVICEABLE

H0820/23 NOTAMR H0582/23

- Q) CZQM/QNVAS/IV/BO/AE/000/999/4455N06324W025
- A) CYHZ B) 2303311806 C) 2306302359 EST
- E) HALIFAX VOR YHZ 115.1MHZ U/S

FIR KZWY

AIRSPACE RESERVATION ACTIVATED

(NEW TODAY)
[Inactive during flight]

A0517/23 NOTAMN

- Q) KZWY/QXXXX////000/210/
- A) KZWY
- B) 2305091400
- C) 2305091630
- E) DUE TO MIL STNR ALT RESERVATION 1FW WI THE NEW YORK OCEANIC CTA/FIR, NEW YORK OCEANIC WILL NOT ACCEPT IFR FLT WI AN AREA DEFINED AS 370000N0724000W TO 370000N0690000W TO 383000N0690000W TO 382000N0695700W THEN ALONG THE ZNY CTA/FIR BDRY TO POINT OF ORIGIN.
- F) SFC
- G) FL210

AIRSPACE RESERVATION ACTIVATED A0518/23 NOTAMN

(NEW TODAY)

Q) KZWY/QXXXX/////

A) KZWY

NOTAMs: Page 18 of 30

- B) 2305091400
- C) 2305121630
- D) DAILY 1400-1630
- E) DUE TO MIL STNR ALT RESERVATION 1FW WI THE NEW YORK OCEANIC CTA/FIR, NEW YORK OCEANIC WILL NOT ACCEPT IFR FLT WI AN AREA DEFINED AS 370000N0724000W TO 370000N0690000W TO 383000N0690000W TO 382000N0695700W THEN ALONG THE ZNY CTA/FIR BDRY TO POINT OF ORIGIN.
- F) SFC
- G) FL210

FLIGHT PLAN PROCESSING, FILING AND RELATED CONTINGENCY

A0278/20 NOTAMR A0415/15

- Q) KZWY/QXXXX/////
- A) KZWY
- B) 2004131817
- C) PERM

E) NEW YORK RADIO (FORMERLY ARINC) REQUESTS THAT ALL FLIGHT PLANS THAT ARE FILED INTO ANY OF THE NEW YORK FIR OR CTA INCLUDE THE FOLLOWING ADDRESS WHEN FILING THEIR FLIGHT PLANS:KNYCZZZX. ANY QUESTIONS PLEASE CONTACT ANTHONY ABATE OF NEW YORK RADIO AT 631-244-2483

AIRCRAFT ENTRY REQUIREMENTS CHANGED

A0052/22 NOTAMN

- Q) TXKF/QOECH/IV/NBO/E /000/999/3222N06441W999
- A) TXKF B) 2204010300 C) PERM
- E) ACFT ENTRY ROMNTS INSTL. ALL VISITING ACFT MUST BE EQUIPPED WITH ACAS II (TCAS II VERSION 7.1) IN ACCORDANCE WITH SARPS ANNEX 6 PART I AND PART II. NOTICE DETAILS: HTTPS://WWW.BCAA.BM/NOTICES

FIR CZQX

VOR/DME UNSERVICEABLE

H1163/23 NOTAMN

- Q) CZQX/QNMAS/IV/BO/AE/000/999/4854N05432W025
- A) CYQX B) 2305031030 C) 2307151930
- E) GANDER VOR/DME YQX 112.7MHZ/CH74X U/S

AIRCRAFT ENTRY REQUIREMENTS CHANGED

H0902/23 NOTAMR H0055/23

- Q) CZXX/QOECH/IV/NBO/E/000/999/5440N06941W999
- A) CZUL CZQM CZQX B) 2304111424 C) 2307111800EST
- E) ALL ACFT, REGARDLESS OF THE STATE OF REGISTRY, DIRECTLY OR INDIRECTLY OWNED, CHARTERED, LEASED, OPERATED OR OTHERWISE CONTROLLED BY A PERSON CONNECTED WITH EITHER THE RUSSIAN FEDERATION OR OF BELARUS OR BY A CORPORATION OR ENTITY THAT IS INCORPORATED OR FORMED UNDER THE LAWS OF THE RUSSIAN FEDERATION OR BELARUS, AND ALL OPERATORS HOLDING AN AIR OPERATOR CERTIFICATE (AOC) ISSUED BY RUSSIAN FEDERATION AND/OR BELARUSIAN AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY CANADA'S TERRITORIAL ARSPACE (INCLUDING FLT WITHIN 12NM OF CANADA'S COASTS). EXCEPTIONS PERMITTED FOR ACFT EXPERIENCING INFLIGHT EMERG. ALL AUTH OBTAINED PRIOR TO 27 FEB 2022 FOR ACFT AND OPS SUBJECT TO THIS NOTAM ARE REVOKED. HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022

HUMANITARIAN, SAR, MEDEVAC AND ANY OTHER FLT SEEKING AN EXCEPTION TO THIS RESTRICTION MUST RECEIVE AUTH GRANTED AFTER 27 FEB 2022 FM THE MINISTER OF TRANSPORT TO OPERATE IN CANADA'S TERRITORIAL AIRSPACE. AFFECTED ACFT WISHING TO OBTAIN SUCH AN AUTH OR CLR INTO CANADA'S TERRITORIAL AIRSPACE MAY APPLY TO THE MINISTER OF TRANSPORT AT 1-877-992-6853 OR 1-613-992-6853 OR BY EMAIL AT OPERATIONS.AVIATION(AT)TC.GC.CA.

FIR EGGX

OVERFLYING OF

V0010/23 NOTAMN

- Q) EGXX/QROXX/IV/NBO/W /000/999/5218N01451W999
- A) EGTT EGPX EGGX B) 2304211441 C) 2307192359 EST
- E) AIRSPACE SECURITY WARNING ISSUED BY THE DEPARTMENT FOR TRANSPORT-HAZARDOUS SITUATION IN SUDAN. UK CIVIL AIR OPERATORS ARE RECOMMENDED NOT TO ENTER FIR KHARTOUM (HSSS) WITHIN THE TERRITORY AND AIRSPACE OF SUDAN. POTENTIAL RISK FROM ANTI-AIRCRAFT WEAPONRY AND HEIGHTENED MILITARY ACTIVITY. CONTACT UK DEPARTMENT FOR TRANSPORT +44 (0)207-082 6639 OR +44 (0)207-944-3111 OUT OF HOURS. FOR FURTHER DETAILS. 2023-04-0410/AS6.
- F) SFC G) UNL

NOTAMs: Page 19 of 30

OVERFLYING OF

V0008/23 NOTAMN

- Q) EGXX/QROXX/IV/NBO/W /000/999/5218N01451W999
- A) EGTT EGPX EGGX B) 2303170930 C) 2306152359
- E) CURRENT AIRSPACE WARNING SECURITY HAZARDOUS SITUATION IN MALI REPLACE THE CURRENT ENTRY WITH THE FOLLOWING: UK CIVIL AIR OPERATORS ARE ADVISED TO TAKE POTENTIAL RISK INTO ACCOUNT WITHIN FIR NIAMEY (DRRR) AND FIR DAKAR (GOOO) WITHIN THE TERRITORY AND AIRSPACE OF MALI. POTENTIAL RISK FROM ANTI-AIRCRAFT WEAPONRY. UPPER ALTITUDE TO READ UNLIMITED. CONTACT UK DEPARTMENT FOR TRANSPORT +44 (0)207-082 6639 OR +44 (0)207-944 3111 OUT OF HOURS. UK AIP ENR 1.1, PARAGRAPH 1.4.5 REFERS. 2023-03-0374/AS6 F) SFC G) UNL

FIR LFFF

HELIPORT

P4201/22 NOTAMN

- Q) LFFF/QOBCE/IV/M /A /000/999/4851N00246E005
- A) LFXX B) 2212121025 C) 2306122359
- E) MARNE LA VALLEE CENTRE HOSPITALIER HELIPORT, CRANE ERECTED
- 312/0.1NM FR HLP PSN: 485101N 0024601E HEIGHT: 140FT

ELEV: 532FT LIGHTING: NIGHT AND DAY

HELIPORT

P4198/22 NOTAMR P4195/22

- Q) LFFF/QOBCE/IV/M /A /000/999/4851N00246E005
- A) LFXX B) 2212121017 C) 2306122359
- E) 2 MOBILE CRANES AT 'MARNE LA VALLEE HOSPITAL CENTER' HELISTATION, BELOW NORTH-WEST FUNNEL, 600M FROM THE HELISTATION : GIVE PRIORITY

TO SOUTH-EAST FUNNEL FOR ALL MOVEMENTS

- MOBILE CRANE 1

PSN: 485106N 0024551E

HGT: 138FT ELEV: 563FT

LGT: DAY AND NIGHT

- MOBILE CRANE 2

PSN: 485108N 0024553E

HGT: 89FT ELEV: 173FT

LGT: DAY AND NIGHT.

HELIPORT

- P4134/22 NOTAMR P2939/22
- Q) LFFF/QOBCE/IV/M /A /000/999/4847N00216E005
- A) LFXX B) 2212061530 C) 2309061800
- E) LE PLESSIS ROBINSON CENTRE CHIRURGICAL MARIE LANNELONGUE :

OBST : TOWER CRANE : RDL 171/2.9NM HLP ARP

- PSN : 484413N 0021708E
- HEIGHT : 131FT
- ELEV : 395FT
- LIGHTING : DAY AND NIGHT.

HELIPORT

P4133/22 NOTAMR P3041/22

- Q) LFFF/QOBCE/IV/M /A /000/999/4850N00208E005
- A) LFXX B) 2212061527 C) 2309092359
- E) VERSAILLES CENTRE HOSPITALIER :

OBST : TOWER CRANE NEAR HLP - RDL : 028/0.08NM ARP HLP

PSN: 484955N 0020743E

HEIGHT : 153FT ELEV : 657FT

LIGHTING : DAY AND NIGHT.

HELIPORT

P4132/22 NOTAMR P3062/22

- Q) LFFF/QOBCE/IV/M /A /000/999/4812N00318E005
- A) LFXX B) 2212061524 C) 2309082359
- E) SENS CENTRE DE SECOURS PRINCIPAL

OBST (TREES) NEAR HLP:

- OBST 1 - WITHIN NORTH WEST FUNNEL: PSN: 481133N 0031820E RDL322/85M ARP

NOTAMs: Page 20 of 30

```
ELEV: 283FT
HEIGHT : 17FT
- OBST 2 - WITHIN SOUTH EAST FUNNEL :
PSN : 481127N 0031825E RDL156/138M ARP
ELEV: 294FT
HEIGHT: 28FT
OBST NOT LIGHTED
HELIPORT
P4131/22 NOTAMR P3277/22
Q) LFFF/QOBCE/IV/M /A /000/999/4756N00153E005
A) LFXX B) 2212061522 C) 2309301800
E) 'SARAN POLE SANTE ORELIANCE' HELISTATION
TWR CRANE OPR AT 'SARAN' - RDL080/0.37NM HLP ARP:
- PSN: 475621.80N 0015315.80E
- HGT: 150FT
- ELEV: 535FT
- LIGHTING: NIGHT AND DAY.
HELIPORT
P4116/22 NOTAMR P3742/22
Q) LFFF/QOBCE/IV/M /A /000/999/4750N00155E005
A) LFXX B) 2212051524 C) 2310311800
E) ORLEANS CENTRE HOSPITALIER HELIPORT :
TOWER CRANE OPR, RDL 045/0.76NM ARP HELIPORT
PSN : 475038N 0015556E
HEIGHT : 131FT
ELEV : 477FT
LIGHT: NIGHT AND DAY
                                                                                                   (NEW TODAY)
HELIPORT
P1805/23 NOTAMN
Q) LFFF/QOBCE/IV/M /A /000/999/4915N00227E005
A) LFXX B) 2305090832 C) 2308082359
E) CREIL CENTRE HOSPITALIER LAENNEC
OBST CREIL CENTRE HOSPITALIER LAENNEC HELISTATION :
GROUP OF TREES IN THE TKOFF FUNNEL 199
RDL 192/0.05NM HELISTATION ARP
PSN 491446N 0022726E
HEIGHT 36FT
ELEV 256FT
EXCEEDING 10FT.
HELIPORT
                                                                                                   (NEW TODAY)
P1804/23 NOTAMN
Q) LFFF/QOBCE/IV/M /A /000/999/4915N00227E005
A) LFXX B) 2305090831 C) 2308082359
E) OBST HLP 'CREIL HOSPITAL CENTER LAENNEC', RDL032/0.03NM ARP HPL,
GROUP OF TREES IN THE RETREAT PHASE 199:
- PSN: 491451N 0022729E
- HGT: 26FT
- ELEV: 257FT
- EXCEEDING: 10FT.
                                                                                                   (NEW TODAY)
HELIPORT
P1803/23 NOTAMN
Q) LFFF/QOBCE/IV/M /A /000/999/4915N00227E005
A) LFXX B) 2305090827 C) 2308082359
E) OBST 'CREIL CENTRE HOSPITALIER LAENNEC' HELISTATION :
GROUP OF TREES IN THE RETREAT PHASE 349
RDL 158/0.04NM HELISTATION ARP:
PSN : 491447N 0022729E
HEIGHT : 60FT
ELEV: 279FT
EXCEEDING : 20FT.
                                                                                                   (NEW TODAY)
HELIPORT
P1802/23 NOTAMN
Q) LFFF/QOBCE/IV/M /A /000/999/4915N00227E005
A) LFXX B) 2305090826 C) 2308082359
E) OBST HLP 'CREIL HOSPITAL CENTER LAENNEC', RDL346/0.03NM HLP ARP,
TREES WITHIN TKOF FUNNEL 349:
```

- PSN: 491451N 0022727E

- HGT: 36FT

- ELEV: 260FT

- EXCEEDING: 14FT.

NOTAMs: Page 21 of 30

HELIPORT P1726/23 NOTAMN Q) LFFF/QOBCE/IV/M /A /000/999/4849N00221E005 A) LFXX B) 2305031337 C) 2308031927 E) OBST 'KREMLIN BICETRE CENTRE HOSPITALIER' HELIPORT : OBST : BUILDING RDL251/0.03NM HLP PSN: 484834N 0022120E ELEV 294FT HGT 21FT LGT DAY AND NIGHT. HELIPORT P1725/23 NOTAMN Q) LFFF/QOBCE/IV/M /A /000/999/4849N00221E005 A) LFXX B) 2305031336 C) 2308031927 E) KREMLIN BICETRE CENTRE HOSPITALIER HLP: OBSTACLE - RDL065/0.05NM HLP ARP TYPE: BUILDING PSN: 484836N 0022127E ELEV: 305FT HGT: 45FT LGT: NONE HELIPORT P1723/23 NOTAMN Q) LFFF/QOBCE/IV/M /A /000/999/4849N00221E005 A) LFXX B) 2305031333 C) 2308031927 E) OBST KREMLIN BICETRE CENTRE HOSPITALIER HLP - RDL 256/0.06NM HLP ARP TYPE: BUILDING PSN: 484833N 0022117E ELEV: 347FT HGT: 72FT LGT NONE HELIPORT P1564/23 NOTAMN Q) LFFF/QOBCE/IV/M /A /000/999/4914N00401E005 A) LFXX B) 2304210911 C) 2310202359 E) 'REIMS CENTRE HOSPITALIER REGIONAL' HELISTATION: CRANE OPR: - PSN: 491355N 0040049E - HGT: 120FT - ELEV: 467FT - LGT: NIGHT AND DAY HELIPORT P1540/23 NOTAMR P4091/22 Q) LFFF/QOBCE/IV/M /A /000/999/4952N00215E005 A) LFXX B) 2304200814 C) 2401041830 E) CRANE OPR NEARBY 'AMIENS CENTRE HOSPITALIER UNIVERSITAIRE SUD 2' HLP : - PSN : 495227N 0021520E - HEIGHT: 102FT - ELEV : 309FT - LIGHTING : DAY/NIGHT HELIPORT P1539/23 NOTAMR P4147/22 Q) LFFF/QOBCE/IV/M /A /000/999/4952N00215E005 A) LFXX B) 2304200810 C) 2305221700 E) 'AMIENS CENTRE HOSPITALIER UNIVERSITAIRE SUD 2' HLP : - TWR CRANE OPR NEARBY HELIPORT RDL059/0.46NM ARP - PSN : 495248N 0021604E - HEIGHT : 134FT - ELEV : 348FT - LGT : NIGHT AND DAY

HELIPORT

P1537/23 NOTAMR P0268/23

- Q) LFFF/QOBCE/IV/M /A /000/999/4952N00215E005
- A) LFXX B) 2304200803 C) 2310041830
- E) CRANE OPR NEARBY 'AMIENS CENTRE HOSPITALIER UNIVERSITAIRE SUD 2' $\ensuremath{\mathsf{HLP}}$:
- PSN : 495227N 0021520E
- HEIGHT : 102FT
- ELEV : 309FT
- LGT : NIGHT AND DAY

HELIPORT P1490/23 NOTAMN Q) LFFF/QOBCE/IV/M /A /000/999/4846N00037E005 A) LFXX B) 2304180000 C) 2306170000 E) 'L'AIGLE CENTRE HOSPITALIER' HLP: OBSTACLES WITHIN THE NORTH WEST FUNNEL -OBSTACLE NR 1 - RDL300/80M HLP PSN: 484602N 0003633E HEIGHT: 13FT ELEV: 777FT LIGHTING: NIL - OBSTACLE NR 2 - RDL 296/92M HLP PSN484602N 000363E HEIGHT: 26FT ELEV: 790FT LIGHTING: NIL HELIPORT P1486/23 NOTAMN Q) LFFF/QOBCE/IV/M /A /000/999/4846N00037E005 A) LFXX B) 2304180000 C) 2307172359 E) L'AIGLE CENTRE HOSPITALIER HELIPORT : OBST IN NORTH-WEST FUNNEL: -OBST 1 : PSN: 484602N 0003633E RDL300/80M FATO HEIGHT : 13FT ELEV: 767FT LIGHTING : NIL -OBST 2 : PSN: 484602N 0003632E RDL296/92M FATO HEIGHT: 26FT ELEV: 781FT LIGHTING : NIL HELICOPTER ALIGHTING AREA/PLATFORM HEL ALIGHTING AREA

P1263/23 NOTAMN

Q) LFFF/QOBCE/IV/M /A /000/999/4853N00221E005

A) LFXX B) 2304010500 C) 2403312359

E) PARIS CENTRE HOSPITALIER LARIBOISIERE :

TOWER CRANE NEW 'LARIBOISIERE' WORKSITE : RDL 347/77M HLP ARP

-PSN : 485300N 0022115E

-HGT : 149FT -ELEV: 324FT

-LGT : DAY AND NIGHT.

HELIPORT

P1040/23 NOTAMN

Q) LFFF/QOBCE/IV/M /A /000/999/4914N00401E005

A) LFXX B) 2303270300 C) 2308072359

E) 'REIMS REGIONAL HOSPITAL CENTER': TOWER CRANE WITHIN HLP

PSN: 491335N 0040114E

HEIGHT: 99FT ELEV: 417FT LIGHTING: DAY

HELIPORT

P0755/23 NOTAMN

Q) LFFF/QOBCE/IV/M /A /000/999/4851N00246E005

A) LFXX B) 2303011327 C) 2308022359

E) MARNE LA VALLEE CENTRE HOSPITALIER:

OBST BLDG BELOW NORTH WEST FUNNEL RDL 316/187M HLP.

PSN: 485059.6N 0024604.4E

HGT 145.27FT

LGTD DAY NGT

OBST 2 ANTENNAS ON BLDG BELOW SOUTH EAST FUNNEL 119/196M HLP.

PSN: 485051.7N 0024619.8E

HGT ANTENNA 1 136.8FT - ANTENNA 2 136.2FT

LGTD DAY NGT

HELIPORT

P0737/23 NOTAMN

Q) LFFF/QOBCE/IV/M /A /000/999/4756N00153E005

A) LFXX B) 2303020500 C) 2307312359

NOTAMs: Page 23 of 30

E) OBST : CRANE OPR 'SARAN POLE SANTE ORELIANCE' HLP :

RDL036/0.26NM ARP HELISTATION PSN: 475630.75N 0015256.75E

HGT : 128FT ELEV : 510FT

LGT : DAY AND NIGHT.

HELIPORT

P0622/23 NOTAMN

- Q) LFFF/QOBCE/IV/M /A /000/999/4756N00153E005
- A) LFXX B) 2302230700 C) 2312151700
- E) TOWER CRANE AT 'SARAN POLE SANTE ORELIANCE' HLP RDL105/0.23NM ARP HLP

PSN: 475614.55N 0015302.63E

HEIGHT : 118FT ELEV : 501FT

LIGHTING : DAY AND NIGHT

HET TPORT

P0244/23 NOTAMR P4246/22

- Q) LFFF/QOBCE/IV/M /A /000/999/4955N00105E005
- A) LFXX B) 2301201009 C) 2308311700
- E) DIEPPE CENTRE HOSPITALIER:

OBST: TWR CRANE NEAR HLP: RDL 323/0.15NM HLP ARP

PSN : 495512N 0010440E HEIGHT : 107FT

ELEVATION : 128FT

LIGHTING : DAY AND NIGHT.

AREA CONTROL CENTRE CLOSED

M0966/23 NOTAMN

- O) LFXX/OSCLC/IV/NBO/E /000/999/4912N00005E325
- A) LFFF LFRR LFEE LFBB B) 2304031255 C) 2307092359
- E) LE CENTRE DE DETECTION ET DE CONTROLE DE RAKI 07.927 CINQ MARS LA PILE EST FERME. AUCUN SERVICE D ALERTE, DE CONTROLE ET D ASSISTANCE
- NE SERA ASSURE CAUSE: MISE A NIVEAU INDUSTRIELLE
- LE CDC DE MARINA REPREND LA ZONE DE RAKI ET LE CDC DE LYON REPREND
- LA ZONE HISTORIQUE DE RIESLING.
- CDC BIV MARINA: 865 118 8126 05 58 06 84 51
- CDC BIV RAMBERT: 864 942 6655 04 87 65 56 55
- CDC CINQ MARS LA PILE POC : 02 47 96 28 63.

HELIPORT

H0522/22 NOTAMN

- Q) LFFF/QLUXX/IV/NBO/A /000/999/4851N00246E005
- A) LFXX B) 2212121030 C) 2306122359
- E) MARNE LA VALLEE HOSPITAL CENTER HLP, PREFER SOUTH EAST TRAJECTORY FOR RRIVAL AND DEPARTURE DUE TO OBSTACLE.

HELIPORT CLOSED

H0122/23 NOTAMN

- Q) LFFF/QFPLC/IV/BO /A /000/999/4900N00140E005
- A) LFXX B) 2303270912 C) 2306272002
- E) 'MANTES LA JOLIE CENTRE HOSPITALIER FRANCOIS QUESNAY' HLP: CLSD

HELIPORT CLOSED

H0089/23 NOTAMN

- Q) LFFF/QFPLC/IV/BO /A /000/999/4800N00246E005
- A) LFXX B) 2303080000 C) 2306082359
- E) AMILLY CENTRE HOSPITALIER HLP CLSD DUE TO WIP.

PSN: N475948 0024628E.

GNSS AREA-WIDE OPERATIONS

F0753/23 NOTAMN

- O) LFXX/OGWAU/IV/NBO/E /000/999/4740N00319W207
- A) LFRR LFFF LFBB B) 2305100700 C) 2305101400
- D) 0700-0900 1200-1400
- E) POSSIBLE GNSS JAMMING : DISTURBANCE OF THE SIGNAL RECEIVED BY GPS RECEIVERS IN THE GAVRES AREA

INTERFERENCE DIRECTION TO THE SOUTH AT AN ANGLE BETWEEN 090 AND 270 VOLUME OF IMPACT :

NORTHERN SECTOR: HALF-SPHERE RADIUS 120NM CENTRED ON PSN 474002N 0031832W

SOUTHERN SECTOR : HALF-SPHERE RADIUS 207NM CENTRE ON PSN 474002N

(NEW TODAY)

NOTAMs: Page 24 of 30

0031832W

- VERTICAL LIMITS : SFC/UNL
- CONTACT : ACTIVITY RESPONSIBLE : +33(0)6 62 83 87 09
- AVAILABLE INFORMATION ON LFRH 122.700 MHz, ARMOR 124.725 MHz
- IN CASE OF OBSERVED GPS INTERFERENCE, REPORT THE INFORMATION TO THE COMPETENT ATS SERVICES .

VOR UNSERVICEABLE (NEW TODAY)

F0716/23 NOTAMN

- Q) LFFF/QNVAS/IV/BO /AE/000/999/4902N00113E025
- A) LFOE B) 2305090800 C) 2305101600
- E) VORTAC EVX, VOR PART 112.400MHZU/S DUE TO MAINT :
- DO NOT USE, POSSIBLE FALSE INDICATIONS

AERONAUTICAL INFORMATION SERVICE

F0714/23 NOTAMN

- Q) LFXX/QAFXX/IV/NBO/E /000/999/4412N00040E460
- A) LFBB LFEE LFFF LFMM LFRR B) 2305030400 C) 2306010400
- E) DUE TO AN INTER-PROFESSIONAL SOCIAL MOVEMENT AFFECTING ALL AREAS OF

ACTIVITY, MAJOR DISRUPTIONS ARE POTENTIALLY EXPECTED IN DSNA ATC CENTERS (ACCS, APP, TOWER) IN FRANCE AND OVERSEAS DEPARTMENTS.

A MINIMUM SERVICE WILL BE ENSURED IN SOME DSNA ATC CENTERS IDENTIFIED IN THE DECREE NUMBER 85-1332 MODIFIED OF DECEMBER 17, 1985. ACTUAL ATC CAPACITY WILL BE DETERMINED ACCORDING TO AVAILABLE STAFF.

RMK 1: IN PARTICULAR, MININUM SERVICE WILL BE IN PLACE AT PARIS ACC (LFFF) ON WEDNESDAYS AND SATURDAYS, INCLUDING NIGHT SHIFTS BEFORE AND AFTER.

RMK 2: INFORMATION ON THE REAL-TIME SITUATION AND CLOSURES OF ATS SERVICES WILL BE AVAILABLE ON THE FOLLOWING INTERNET WEBSITE: HTTPS://CDM.DSNA.FR

RMK 3: ADDITIONAL NOTAMS WILL BE ISSUED IF NEEDED DEPENDING ON THE EVOLUTION OF THE SITUATION.

AIRCRAFT ENTRY REQUIREMENTS

F0687/23 NOTAMN

- O) LFXX/OXXXX/I /BO /E /000/999/4412N00040E460
- A) LFBB LFFF LFEE LFMM LFRR B) 2304211442 C) 2305312359
- E) FRENCH AIR CARRIERS AND CAPTAINS OF AIRCRAFT IN CHARGE OF AIR SERVICES OPERATED BY CARRIERS HOLDING AN OPERATING LICENSE ISSUED BY FRANCE,

WHETHER THEY ARE CONTRACTUAL CARRIERS AND/OR OPERATING CARRIERS, OR PERFORMING AIR SERVICES THROUGH A WET LEASE OR A CODESHARE AGREEMENT AS WELL AS FOR ANY FLIGHT MADE WITH AN AIRCRAFT REGISTERED IN FRANCE, ARE REQUESTED NOT TO PENETRATE IN THE PART OF THE KHARTOUM FIR (HSSS)

LOCATED OVER SUDAN TERRITORY AND NOT TO IDENTIFY SUDAN AIRPORTS AS ALTERNATE WHEN PLANNING FLIGHT OPERATIONS.

AIRCRAFT ENTRY REQUIREMENTS CHANGED

F0551/23 NOTAMR F0146/23

- Q) LFXX/QOECH/I /NBO/E /000/999/4412N00042E455
- A) LFMM LFFF LFRR LFEE LFBB B) 2303301014 C) 2305312359
- E) RUSSIA AND BELARUS RESTRICTIONS :
- 1- ALL AIRCRAFT REGISTERED IN RUSSIA OR OPERATED BY RUSSIAN AIR CARRIERS, INCLUDING AS A MARKETING CARRIER IN CODE-SHARING OR BLOCKED-SPACE ARRANGEMENTS OR OWNED, CHARTERED OR OPERATED BY A RUSSIAN NATURAL OR LEGAL PERSON, ENTITY OR BODY ARE PROHIBITED TO LAND IN, TAKE OFF FROM OR OVERFLY THE FRENCH SOVEREIGN AIRSPACE EXCEPT IN CASE OF EMERGENCY LANDING OR EMERGENCY OVERFLIGHT AND EXCEPT FOR FLIGHTS HOLDING A PERMISSION DELIVERED IN ACCORDANCE WITH THE APPROPRIATE UE REGULATION BY THE FRENCH AUTHORITIES 2- ALL AIRCRAFT OPERATED BY BELARUSIAN AIR CARRIERS, INCLUDING AS A MARKETING CARRIER IN CODE-SHARING OR BLOCKED-SPACE ARRANGEMENTS, TO LAND IN, TAKE OFF FROM OR OVERFLY THE FRENCH SOVEREIGN AIRSPACE EXCEPT IN CASE OF EMERGENCY LANDING OR EMERGENCY OVERFLIGHT AND EXCEPT FOR FLIGHTS HOLDING A PERMISSION DELIVERED IN ACCORDANCE WITH THE APPROPRIATE UE REGULATION BY THE FRENCH AUTHORITIES 3- IT SHALL BE **PROHIBITED** TO PARTICIPATE, KNOWINGLY AND INTENTIONALLY, IN ACTIVITIES THE OBJECT OR EFFECT OF WHICH IS TO CIRCUMVENT THESE PROHIBITIONS.

AIRCRAFT ENTRY REQUIREMENTS

F0469/23 NOTAMN

- Q) LFXX/QXXXX/IV/NBO/E /000/999/4412N00040E460
- A) LFFF LFBB LFMM LFEE LFRR B) 2303210745 C) 2306212359

NOTAMs: Page 25 of 30

E) FRENCH AIR CARRIERS AND CAPTAINS OF AIRCRAFT IN CHARGE OF AIR SERVICES OPERATED BY CARRIERS HOLDING AN OPERATING LICENSE ISSUED BY FRANCE, WHETHER THEY ARE CONTRACTUAL CARRIERS AND/OR OPERATING CARRIERS, OR PERFORMING AIR SERVICES THROUGH A WET LEASE OR A CODESHARE AGREEMENT AS WELL AS FOR ANY FLIGHT MADE WITH AN AIRCRAFT REGISTERED IN FRANCE, ARE REQUESTED TO MAINTAIN AT ALL TIMES A FLIGHT LEVEL ABOVE OR EQUAL TO FL260 IN THE AIRSPACE OF SOMALIA (FIR MOGADISHU (HCSM) EXCEPT IN THE MARITIME PART OF FIR MOGADISHU HCSM LOCATED NORTH OF PARALLEL 113000N WHERE FLIGHTS ARE AUTHORIZED WHILE EXERCISING AT ALL TIME GREAT CAUTION BELOW AN ALTITUDE OF 5000FT. THIS NOTAM SUPERSEDES THE RESTRICTIONS CONCERNING SOMALIA AIRSPACE (FIR MOGADISHU HCSM) ISSUED IN AIC 24/22.

AREA NAVIGATION ROUTE TRIGGER

F0378/23 NOTAMN

- Q) LFXX/QANTT/I /BO /E /195/999/4412N00040E460
- A) LFBB LFEE LFFF LFMM LFRR B) 2305050000 C) 2305182359
- E) TRIGGER NOTAM AIRAC AIP SUP AIP 032/23 WEF 05 MAY TIL 27 OCT 2023:

USE OF SOME CONDITIONAL ROUTES (CDR) AND FRA DIRECT ROUTES (DCT) IN UIR FRANCE ON SPECIFIED BUSY DAYS AND PUBLIC HOLIDAYS.

AREA NAVIGATION ROUTE CHANGED

F0379/23 NOTAMN

- Q) LFXX/QANCH/I /NBO/E /195/999/4412N00040E460
- A) LFBB LFEE LFFF LFMM LFRR B) 2305050000 C) 2310272359
- E) USE OF SOME CONDITIONAL ROUTES (CDR) AND CERTAIN FRA DIRECT ROUTES

(DCT) IN UIR FRANCE ON SPECIFIED BUSY DAYS AND PUBLIC HOLIDAYS. - AIRAC AIP SUP AIP 032/23:

THIS AIP SUP IS AVBL AT WWW.SIA.AVIATION-CIVILE.GOUV.FR

FIR EDUU

No relevant Notams found

FIR LSAS

AIRCRAFT ENTRY REQUIREMENTS CHANGED

A0152/23 NOTAMR A0826/22

- Q) LSAS/QOECH/IV/NBO/E /000/999/4645N00808E999
- A) LSAS B) 2303291801 C) 2306302359EST
- E) UKRAINIAN CRISIS

ALL ACFT AND ALL OPERATORS HOLDING AIR OPERATOR CERTIFICATE (AOC)
ISSUED BY BELARUSIAN AUTHORITIES PROHIBITED TO USE SWISS AIRPORTS EXC
WITH PERMISSION OF APPROPRIATE AUTHORITIES OF SWITZERLAND AND IN
CASE OF EMERG LDG. FLT WITH A VALID DIPLOMATIC CLR NOT AFFECTED.

AIRCRAFT ENTRY REQUIREMENTS CHANGED

A0153/23 NOTAMR A0828/22

- Q) LSAS/QOECH/IV/NBO/E /000/999/4645N00808E999
- A) LSAS B) 2303291801 C) 2306302359EST
- E) SWISS AIR CARRIERS AND COMMANDERS OF AIRCRAFT IN CHARGE OF AIR SERVICE MANAGED BY CARRIERS HOLDERS OF OPERATING LICENCE ISSUED BY SWITZERLAND, WHETHER THEY ARE CONTRACTUAL CARRIERS AND/OR DE FACTO CARRIERS, OR PERFORMING AIR SERVICE WITH COMMERCIAL CHARTER AGREEMENT OR WITH CODE SHARING AND TO ALL FLIGHT PERFORMED WITH SWISS AIRCRAFT REGISTRATION, ARE REQUESTED TO CONSULT EASA SIB-2021-10 AND ARE REQUESTED TO AVOID MINSK FIR (UMMV).

FOREIGN AIR CARRIERS INBOUND SWITZERLAND ARE RECOMMENDED TO AVOID MINSK FIR (UMMV).

AIRCRAFT ENTRY REQUIREMENTS CHANGED

A0154/23 NOTAMR A0827/22

- Q) LSAS/QOECH/IV/NBO/E/000/999/4645N00808E999
- A) LSAS B) 2303291801 C) 2306302359 EST
- E) UKRAINIAN CRISIS
- 1. ALL AIRCRAFT OWNED, CHARTERED, OPERATED OR OTHERWISE CONTROLLED BY CITIZENS OF THE RUSSIAN FEDERATION AND ALL OPERATORS HOLDING AIR OPERATOR CERTIFICATE (AOC) ISSUED BY THE RUSSIAN FEDERATION AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY THE SWISS AIRSPACE EXC HUMANITARIAN FLT, SEARCH AND RESCUE FLT AND LEASED ACFT ONE-WAY RTN FLT WITH THE PERMISSION OF THE APPROPRIATE SWISS AUTHORITIES AND IN CASE OF EMERGENCY LDG OR EMERGENCY

NOTAMs: Page 26 of 30

OVERFLIGHT.

FLIGHTS WITH A VALID DIPLOMATIC CLEARANCE NOT AFFECTED. 2. AIRCRAFT OPERATORS OF NON-SCHEDULED FLT BETWEEN RUSSIA AND SWITZERLAND, OPERATED DIRECTLY OR VIA A THIRD COUNTRY, MUST NOTIFY

ALL RELEVANT INFORMATION CONCERNING THE FLT PRIOR TO THEIR OPERATION

AND AT LEAST 48 HR IN ADVANCE TO THE FEDERAL OFFICE OF CIVIL

AVIATION. CONTACT FOR NOTIFICATION AND DOCUMENTS

WWW.BAZL.ADMIN.CH/AVIATIONSANCTIONS.

ATS ROUTE CHANGED

A0073/23 NOTAMN

- Q) LSAS/QARCH/IV/BO/E/065/660/4645N00808E999
- A) LSAS B) 2302101208 C) PERM
- E) REF AIP, PAGE ENR 3.3-21:

ATS RTE T163 SEGMENT DITON-ROTOS:

MAG TR SHALL READ 252 DEG INSTEAD OF 072 DEG.

ATS RTE T163 SEGMENT ROTOS-LUTIX:

MAG TR SHALL READ 261 DEG INSTEAD OF 081 DEG.

FIR LOVV

MILITARY OPERATING AREA ACTIVATED

(NEW TODAY)

[Inactive during flight]

A1084/23 NOTAMN

- Q) LOVV/QRMCA/IV/BO /W /105/245/4723N01414E046
- A) LOVV B) 2305090745 C) 2305091200
- D) 0745-0855 1130-1200
- E) MILITARY TRAINING AREA MTA SCHOBER ACTIVATED:

REF AIP AUSTRIA, ENR 5.2-3.

FOR DETAILED INFORMATION ABOUT ACTIVITY CONTACT

WIEN INFORMATION FREQ 124.400MHZ, FREQ 134.625MHZ OR

MILITARY RADAR FREQ 131.025MHZ.

F) FL105 G) FL245

AIRCRAFT ENTRY REQUIREMENTS

(NEW TODAY)

A1083/23 NOTAMR A0328/23

- Q) LOVV/QAFXX/IV/NBO/E /000/999/4743N01319E159
- A) LOVV B) 2305081139 C) 2308040800 EST
- E) TO ENSURE SAFE AND EXPEDITIOUS DELIVERY OF COVID-19 VACCINES,

AIRCRAFT OPERATORS OF FLIGHTS CARRYING SUCH VACCINES SHOULD ASK

APPROVAL FROM (AIS/ARO WIEN) FOR EXEMPTION FROM ATFM MEASURES FOR

EACH FLIGHT DEEMED CRITICAL. UPON APPROVAL, STS/ATFMX AND

RMK/VACCINE SHALL BE INSERTED IN ITEM 18 OF THE FLIGHT PLAN.

AIRCRAFT OPERATORS CARRYING COVID 19 VACCINES REGULARLY MAY REQUEST

APPROVAL IN ADVANCE FOR ALL FLIGHTS INVOLVED.

AIP AUSTRIA ENR1.9 CHAPTER 1.1.1, 1.1.6 AND 3.7 TO BE CHECKED.

THE ATFM APPROVAL REQUEST FORM CAN BE FOUND UNDER THE FOLLOWING LINK HTTPS://TINYURL.COM/YYUROG6S

AREA CONTROL CENTRE HOURS OF SERVICE ARE NOW

A1068/23 NOTAMN

- Q) LOVV/QSCAH/IV/BO /E /000/999/4743N01319E159
- A) LOVV B) 2305080600 C) 2305141430
- E) SER HOURS OF MILITARY CONTROL CENTER MCC (WIEN) ARE NOW:

DAILY 0600-1430

REF AIP AUSTRIA, ENR 1.1, ITEM 2.8.2.4.2.

EXERCISES WILL TAKE PLACE

A1057/23 NOTAMN

- Q) LOVV/QXXXX/IV/NBO/AE/000/999/4700N01526E010
- A) LOWG B) 2305041900 C) 2306042000
- D) DAILY 1900-2000
- E) ART PROJECT WITHIN CITY OF GRAZ 'LANDMARKS OF FUTURE' WILL TAKE PLACE.

BE ADVISED: CLOCK TOWER (SCHLOSSBERG) WILL BE ILLUMINATED BY A BLINKING FACADE LIGHT SENDING OUT MORSE CODE (SOS) WITH 1 HZ.

RESTRICTED AREA ACTIVATED

(NEW TODAY)

A1010/23 NOTAMN

- Q) LOVV/QRRCA/IV/BO /W /025/165/4755N01619E003
- A) LOVV B) 2305100700 C) 2305101330
- E) RESTRICTED AREA FELIXDORF LO R 2B ACTIVATED:

REF AIP AUSTRIA ENR 5.1-2.

FOR DETAILED INFORMATION ABOUT ACTIVITY CONTACT

WIEN INFORMATION FREQ 118,525MHZ

F) 2500FT AMSL G) FL165

NOTAMs: Page 27 of 30

ASCENT OF FREE BALLOON WILL TAKE PLACE

A0987/23 NOTAMN

- Q) LOVV/QWLLW/IV/NBO/W /000/999/4841N01521E020
- A) LOVV B) 2305030300 C) 2305102300
- D) DAILY 0300-2300
- E) ASCENT OF RADIOSONDE OUT OF ALLENTSTEIG

PSN: 484113N 0152056E DIAMETER: 1.5M ON GND

WEIGHT: 270G LENGTH: 40M COLOUR: RED

RATE OF ASCENT: 330M/MIN MAXIMUM ALTITUDE: 25000M F) GND G) 25000M AGL

AIRCRAFT ENTRY REQUIREMENTS

A0935/23 NOTAMR A0643/23

- Q) LOVV/QAFXX/IV/NBO/E /000/999/4743N01319E159
- A) LOVV B) 2304210759 C) 2307200800 EST

E) MILITARY INVASION OF UKRAINE BY RUSSIAN FEDERATION: ALL RUSSIAN REGISTERED AIRCRAFT AND AIRCRAFT OWNED, CHARTERED OR OPERATED BY NATURAL OR LEGAL PERSONS FROM THE RUSSIAN FEDERATION OR BY OPERATORS HOLDING AIR OPERATOR CERTIFICATE (AOC) ISSUED BY THE RUSSIAN FEDERATION AUTHORITIES ARE PROHIBITED TO ENTER, EXIT OR OVERFLY AUSTRIAN AIRSPACE EXCEPT HUMANITARIAN, SAR AND LEASED AIRCRAFT ONE-WAY RETURN FLIGHTS WITH THE PERMISSION OF THE APPROPRIATE AUSTRIAN AUTHORITIES AND IN CASE OF EMERGENCY LANDING OR EMERGENCY OVERFLIGHT. ALL AIRCRAFT OPERATORS OF NON-SCHEDULED FLIGHTS (PRIVATE AND COMMERCIAL) BETWEEN RUSSIA AND AUSTRIA, OPERATED DIRECTLY OR VIA A THIRD COUNTRY, SHALL NOTIFY ALL RELEVANT INFORMATION CONCERNING THE FLIGHT, AT LEAST 48 HOURS IN ADVANCE TO AUSTRO CONTROL. CONTACT: FLIGHTPERMISSION (AT) AUSTROCONTROL.AT

MILITARY OPERATING AREA

A0770/23 NOTAMN

- O) LOVV/ORMXX/IV/BO /W /145/285/4715N01455E046
- A) LOVV B) 2304010000 C) 2306291000 EST
- E) MILITARY TRAINING AREA MURTAL (MUT) ESTABLISHED.

LATERAL LIMITS:

475145.00N 0141828.00E - 475141.00N 0142433.00E -

475126.00N 0144233.00E - 475001.00N 0153044.00E -

474903.00N 0153436.00E - 474806.44N 0153821.75E -

464312.41N 0150033.45E - 463551.30N 0143344.35E -

464117.86N 0141150.72E - 470355.38N 0135248.00E -

475145.00N 0141828.00E.

LOWER LIMIT: FL145.

UPPER LIMIT: FL285.

ACTUAL TIME OF ACTIVATION WILL BE ANNOUNCED BY SEPERATE NOTAM.

REF AIP AUSTRIA ENR 5.2.

F) FL145 G) FL285

MILITARY OPERATING AREA ACTIVATED

A0769/23 NOTAMN

- Q) LOVV/QRMXX/IV/BO /W /395/660/4756N01420E106
- A) LOVV B) 2304010000 C) 2306291000 EST
- E) MILITARY TRAINING AREA MACH AREA VIENNA (MAV) ESTABLISHED.

AREA WITH COORDINATES:

484850N 0150855E - 483950N 0160200E - 483850N 0164310E - 482215N 0164210E - 480320N 0165320E - 474810N 0162455E -

465450N 0155705E - 463815N 0134100E - 464030N 0130910E -

464855N 0122505E - 470720N 0121745E - 471045N 0120050E

473240N 0120855E - 473450N 0123710E - 472405N 0125750E -

472550N 0130610E - 474140N 0131150E - 480405N 0125555E - 483015N 0135025E - 482950N 0144105E - 484850N 0150855E

EFFECTIVENESS WILL BE ANNOUNCED BY NOTAM.

REF AIP AUSTRIA ENR 5.2.

F) FL395 G) FL660

CONTROLLER-PILOT DATA LINK COMMUNICATIONS

A0715/23 NOTAMR A2930/22

- Q) LOVV/QAFXX/I /BO /E /000/999/4743N01319E159
- A) LOVV B) 2303241032 C) 2306161000 EST

NOTAMs: Page 28 of 30

E) REF AIP AUSTRIA, GEN 3.4 ITEM 3.4.

INCREASED CPDLC USAGE WILL BE ENDEAVOURED BY ATC IN THE AREA OF RESPONSIBILITY OF ACC WIEN AND APP LOWW.

ALL DATA LINK EQUIPPED AIRCRAFT (CPDLC ATN VDL MODE 2) ARE REQUESTED TO LOG ON TO ACC WIEN / APP WIEN. THE DATA LINK ADDRESS FOR ACC WIEN/APP WIEN IS LOVV.

FLIGHT CREWS SHALL EXPECT TO RECEIVE UPLINK MESSAGES ESPECIALLY IN SITUATIONS OF HIGH RTF FREQUENCY LOAD AND ARE REQUESTED TO REACT TO THEM ASAP.

AERONAUTICAL INFORMATION SERVICE

A0716/23 NOTAMR A2931/22

- Q) LOVV/QAFXX/I /NBO/E /000/999/4743N01319E159
- A) LOVV B) 2303241032 C) 2306161000EST
- E) FOR EN-ROUTE OPERATIONS THE RESPECTIVE VOR SHALL BE SELECTED FOR NAVIGATION INSTEAD OF THE NDB IN CASE OF HOMONYMOUS IDENTIFIERS. THIS APPLIES TO LNZ, GRZ, SBG AND KFT.

FLIGHT CREWS ARE ADVISED TO MONITOR THE CORRECT SELECTION OF THE VOR FOR EN-ROUTE OPERATIONS. IN CASE THE USAGE OF THE RESPECTIVE NDB IS REQUIRED, ATC SHALL BE INFORMED UPON INITIAL CONTACT.

METEOROLOGICAL SERVICE

A0495/23 NOTAMR A2924/22

- Q) LOVV/QFMXX/IV/BO /E /000/999/4743N01319E159
- A) LOVV B) 2302280801 C) 2305291000 EST
- E) METAR, LOCAL ROUTINE AND SPECIAL REPORTS ARE PREPARED IN THREE DIFFERENT QUALITY LEVELS AS PUBLISHED IN THE AIP UNDER GEN 3.5 AND ANNOUNCED AS FOLLOWS:

HUMAN OBS: METEOROLOGICAL REPORTS WHICH ARE QUALITY CONTROLLED BY A HUMAN OBSERVER ON SITE. THEY ARE NOT MARKED WITH THE LABEL 'AUTO' AND ALWAYS DISSEMINATED WITH TREND AND, WHERE APPROPRIATE, WITH SUPPLEMENTARY INFORMATION.

AUTO REMOTE OBS: METEOROLOGICAL REPORTS WHICH ARE QUALITY CONTROLLED BY A REMOTE STATION WITH THE HELP OF CAMERAS. THEY ARE MARKED WITH THE LABEL 'AUTO' AND ALWAYS DISSEMINATED WITH TREND AND, WHERE APPROPRIATE WITH SUPPLEMENTARY INFORMATION.

AUTO OBS: METEOROLOGICAL REPORTS WHICH ARE NOT QUALITY CONTROLLED. THEY ARE MARKED WITH THE LABEL 'AUTO' AND DISSEMINATED WITHOUT TREND AND WITHOUT SUPPLEMENTARY INFORMATION.

FIR LHCC

VOR UNSERVICEABLE (NEW TODAY)

A2273/23 NOTAMN

- Q) LHCC/QNVAS/IV/BO /E /000/999/4650N01807E025
- A) LHCC B) 2305100800 C) 2305101200
- E) SAGVAR DVOR/DME SVR DVOR PART FREQ 117.7MHZ $\overline{\text{OUT}}$ OF SERVICE DUE TO MAINT.

DISTANCE MEASURING EQUIPMENT UNSERVICEABLE

(NEW TODAY)
[Inactive during flight]

A2272/23 NOTAMN

- Q) LHCC/QNDAS/IV/BO /E /000/999/4650N01807E025
- A) LHCC B) 2305090800 C) 2305091200
- E) SAGVAR DVOR/DME SVR DME PART CH124X OUT OF SERVICE DUE TO MAINT.

AIRCRAFT ENTRY REQUIREMENTS

A2274/23 NOTAMR A1938/23

- O) LHCC/OAFXX/IV/NBO/E /000/999/4730N01928E144
- A) LHCC B) 2305041043 C) 2305182359EST
- E) MILITARY INVASION OF UKRAINE BY RUSSIAN FEDERATION ONGOING MILITARY ACTIVITY IN UKRAINE AND THE AIRSPACE WITHIN 200NM ALONG BORDER UKRAINE/RUSSIA IN THE MOSCOW FIR USE OF A WIDE RANGE OF GROUND AND AIRBORNE WARFARE SYSTEMS WHICH POSE A HIGH RISK FOR CIVIL FLIGHTS OPERATING AT ALL ALTITUDES AND FLIGHT LEVELS. AIR CARRIERS HOLDING OPERATING LICENCE ISSUED BY HUNGARY - PILOTS IN COMMAND OF ACFT CONDUCTING AIR SERVICES BY HUNGARIAN OPERATING LICENCE HOLDERS AND OPERATORS OF HUNGARIAN REGISTERED ACFT SHALL NOT ENTER FIR LVIV (UKLV), FIR KYIV (UKBV), UIR KYIV (UKBU), FIR DNIPROPETROVSK (UKDV), FIR SIMFEROPOL (UKFV), FIR ODESA (UKOV), FIR ROSTOV-NA-DONU (URRV). SAID OPERATORS AND AIRCRAFT OWNERS SHALL ALSO AVOID FLIGHT OPERATIONS WITHIN THE BUFFER ZONE EXTENDING OUT TO 200NM ALONG THE UKRAINE/RUSSIA BORDER. OPERATIONS WITHIN THE FIR CHISNAU (LUUU) AIRSPACE SHALL ONLY BE UNDERTAKEN IN COMPLIENCE WITH APPLICABLE AERONAUTICAL PUBLICATIONS ISSUED BY REPUBLIC OF MOLDOVA. ADDITIONAL RISK ASSESSMENT AND FLIGHT PLANNING DECISIONS SHALL BE TAKEN BEFORE OPERATING IN FOLLOWING AIRSPACE: MOSCOW (UUWV).

NOTAMs: Page 29 of 30

AIRCRAFT ENTRY REQUIREMENTS

A2202/23 NOTAMR A1871/23

- Q) LHCC/QAFXX/IV/NBO/E /000/999/4730N01928E144
- A) LHCC B) 2305020623 C) 2305162359 EST
- E) MILITARY INVASION OF UKRAINE BY RUSSIAN FEDERATION: ALL RUSSIAN REGISTERED AIRCRAFT AND ALL AIRCRAFT OWNED, CHARTERED OR OPERATED BY ANY RUSSIAN NATURAL OR LEGAL PERSON, OPERATORS HOLDING OPERATING LICENCE (OL)OR EQUIVALENT ISSUED BY THE RUSSIAN FEDERATION AUTHORITIES, INCLUDING AS A MARKETING CARRIER ARE PROHIBITED TO ENTER, EXIT OR OVERFLY HUNGARIAN AIRSPACE EXCEPT HUMANITARIAN, SAR AND LEASED AIRCRAFT ONE-WAY RETURN FLIGHTS WITH THE PERMISSION OF THE HUNGARIAN CAA AND IN CASE OF EMERGENCY LANDING OR EMERGENCY OVERFLIGHT.

AIRCRAFT ENTRY REQUIREMENTS

A2138/23 NOTAMR A1824/23

- Q) LHCC/QAFXX/IV/NBO/E /000/999/4730N01928E144
- A) LHCC B) 2304270637 C) 2305112359EST
- E) ALL FLIGHTS TO/FROM AIRPORTS OF HUNGARY, OR OVERFLYING HUNGARIAN TERRITORY, ARE NOT ALLOWED IF AIRCRAFT ARE OPERATED BY BELARUSSIAN AIR CARRIERS AND/OR REGISTRATED IN BELARUS AND/OR INCLUDED IN THE REG EC NO 765/2006 EXCEPT FOR AIRCRAFT IN EMERGENCY OR HUMANITARIAN FLIGHTS.

AIRCRAFT ENTRY REQUIREMENTS

A2137/23 NOTAMR A1825/23

- Q) LHCC/QAFXX/IV/NBO/E /000/999/4730N01928E144
- A) LHCC B) 2304270628 C) 2305112359EST
- E) AIR CARRIERS HOLDING OPERATING LICENCE ISSUED BY HUNGARY PILOTS IN COMMAND OF ACFT CONDUCTING AIR SERVICES BY HUNGARIAN OPERATING LICENCE HOLDERS AND OPERATORS OF HUNGARIAN REGISTERED ACFT ARE NOT PERMITTED TO ENTER MINSK FIR (UMMV) UNLESS THE USE OF THAT AIRSPACE IS DEEMED NECESSARY TO ENSURE SAFE OPERATION IN CASE OF UNFORESEEN CIRCUMSTANCES. FOREIGN AIR CARRIERS INBOUND AND OUTBOUND EU ARE RECOMMENDED TO AVOID BELARUS MINSK FIR (UMMV).

FIR LZBB

No relevant Notams found

NOTAMs: Page 30 of 30