Replacement Cost Estimate

Prepared by: User DAVID.SOL@IBIGROUP.C

Valuation ID: BT6WP39.1

(In Canadian Dollars)

Owner Information

Name: XM8 ONLINE Date Entered: 08/29/2023 Street: - Date Calculated: 08/29/2023

City, Province Postal Code: -, - T2G 5E1 Created By: User DAVID.SOL@IBIGROUP.C

Country: Canada User: 8D XM8Profile

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 1600
Use: Single Family Detached Year Built: 2000

Home Quality Grade: **Custom** Cost per Finished Sq. Ft.: \$193.06

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: **6-7 Corners - L Shape**Percent of lowest level that is finished: **100%**Foundation Type: **100% Basement**Basement Quality Adjustment: None

Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Walk-out Basement: No

Exterior

Roof Shape: Gable

Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: **100% Wood Framing** Exterior Wall Finish:

70% Stucco - Traditional Hard Coat, 30% Brick Veneer

Interior

Average Wall Height: 9 Interior Wall Material: 100% Drywall

Floor Coverings: 40% Carpet, 40% Hardwood - Plank, Interior Wall Finish: 50% Paint, 40% Wallpaper,

20% Tile - Ceramic 10% Paneling

Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 1 Half Bath, 3 Full Bath

Bedrooms: 1 Medium - (10'x10'), 1 Large - (14'x12'), Living Areas: 1 Small - (14'x10'), 2 Large - (20'x14'),

4 Extra Large - (16'x14') 1 Extra Large - (22'x16')
Dining Rooms: 1 Medium - (18'x12') Entry/Foyer: 1 Small - (8'x6')

Laundry Rooms: 1 Small - (7'x5'), 1 Medium - (10'x8')

Hallways: 1 Large - (15'x6'), 1 Extra Large - (15'x8')

Nooks: 1 Medium - (10'x10') Utility Rooms: 2 Medium - (10'x8')

Walk-In Closets: 2 Medium - (10'x8')

•

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None Size: Medium

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: **100% Quartz** Hood - Built-in Hardwood, 1 Space Saver Microwave, Room Features: Chair Rail

1 Cook Top, 1 Built-in Oven, 1 Built-in Refrigerator,

1 Built-in Freezer

Cabinets: Peninsula Bar, 10 Glass Cabinet Doors

Bath (Above Ground Room): Quality Adjustment: None

Type: Full Bath

Fixtures: 1 Nat. Marble Tub/Shower Surr., 1 Jetted Tub,

1 Extra Sinks, 1 Brass Faucets

Size: Medium

Vanity Tops: 100% Quartz

Bath (Above Ground Room): Quality Adjustment: None Size: Medium Type: Full Bath Vanity Tops: 100% Quartz Fixtures: 1 Nat. Marble Tub/Shower Surr., 1 Extra Sinks, 1 Brass Faucets Bath (Above Ground Room): Quality Adjustment: None Size: Small Type: Half Bath Vanity Tops: 100% Quartz Bath (Basement Room): Quality Adjustment: None Size: Medium Type: Full Bath Vanity Tops: 100% Quartz Fixtures: 1 Nat. Marble Tub/Shower Surr., 1 Extra Sinks, 1 Brass Faucets Bedroom (Above Ground Room): Size: Medium Quality Adjustment: None Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding Bedroom (Above Ground Room): Quality Adjustment: None Size: Large Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding Bedroom (Above Ground Room): Quality Adjustment: None Size: X-Large Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding Bedroom (Basement Room): Quality Adjustment: None Size: X-Large Room Features: Cornice or Crown Molding Bedroom (Basement Room): Quality Adjustment: None Size: X-Large Room Features: Cornice or Crown Molding Bedroom (Basement Room): Quality Adjustment: None Size: X-Large Room Features: Cornice or Crown Molding Living Area (Above Ground Room): Size: Small Quality Adjustment: None Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding, 1 Decorative Beams Living Area (Above Ground Room): Quality Adjustment: None Size: Large Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding, 1 Decorative Beams Living Area (Basement Room): Quality Adjustment: None Size: Large Room Features: Cornice or Crown Molding, 1 Decorative **Beams** Living Area (Basement Room): Quality Adjustment: None Size: X-Large Room Features: Cornice or Crown Molding, 1 Decorative Beams Dining Room (Above Ground Room): Quality Adjustment: None Size: Medium Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding Entry/Foyer (Above Ground Room): Quality Adjustment: None Size: Small Room Features: Cathedral/Vaulted Ceiling, Cornice or Crown Molding Laundry Room (Above Ground Room):

Laundry Room (Basement Room):

Size: Medium Quality Adjustment: None

Hallway (Above Ground Room):

Quality Adjustment: None Size: Large

Room Features: Cornice or Crown Molding

Hallway (Basement Room):

Quality Adjustment: None Size: X-Large

Room Features: Cornice or Crown Molding

Nook (Above Ground Room):

Quality Adjustment: None Size: Medium

Room Features: Cathedral/Vaulted Ceiling, Cornice or

Crown Molding

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Utility Room (Basement Room):

Quality Adjustment: None Size: Medium

Walk-In Closet (Above Ground Room):

Quality Adjustment: None Size: Medium

Walk-In Closet (Basement Room):

Quality Adjustment: None Size: Medium

Attached Structures

Porch #1:

Square Footage: 120 Material: Concrete Porch

Covered: 100% Enclosed: 25%

Outdoor Fireplace: No

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Specialty Systems: 1 Water Softener

Fireplace #1:

Type: Masonry Fireplace Fireplace Details: 1 Brick Hearth, 1 Custom Mantel,

1 Stone Face

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 2 Ceiling Fan

Interior Doors and Millwork: 1 Built-in Bookcase/Entertain.

Other Interior Features: 1 Laundry Tub Center

Specialty Windows

2 Specialty Window Medium (12 - 23 SF)

Estimated Cost Breakdown

Appliances: \$20,574.95 Electrical: \$20,517.64 Exterior Finish: \$44,391.77 Floor Covering: \$35,907.59 Heating/AC: \$15,911.71 Interior Finish: \$200,277.15 Plumbing: \$34,397.65 Roofing: \$11,143.40

Rough Framing: \$51,527.75 Specialty Features: \$4,952.07

Windows: \$16,179.98 Permits: \$5,742.85

Other Fees and Taxes: \$156,265.90

Estimated Replacement Cost

Calculated Value:

\$617,790.40

(\$601,888.00 - \$633,692.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

The following slab items are excluded from this value: Foundation
23.7.15 PL:ABCAXV AUG23