Replacement Cost Estimate

Prepared by: User DAVID.SOL@IBIGROUP.C

Valuation ID: BU3NW65.1

(In Canadian Dollars)

Owner Information

Name: XM8 ONLINE Date Entered: 09/10/2023 Street: 123 FLOOD WAY Date Calculated: 09/10/2023

City, Province Postal Code: CALGARY, AB T2G5E1 Created By: User DAVID.SOL@IBIGROUP.C

Country: Canada User: 8D XM8Profile

General Information

Most Prevalent Number of Stories: 1 Story Sq. Feet: 2500
Use: Single Family Detached Year Built: 2000

Home Quality Grade: **Standard** Cost per Finished Sq. Ft.: \$158.28

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 8-10 Corners - T,U,Z Shape
Foundation Type: 100% Crawlspace
Foundation Meterial: 100% Congrete
Foundation Type: None (0, 15 degrees)

Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Exterior

Roof Shape: **Gable** Number of Dormers: 0

Roof Construction: 100% Wood Framed Roof Cover: 100% Composition - Architectural Shingle

Exterior Wall Construction: **100% Wood Framing** Exterior Wall Finish:

70% Stucco - Traditional Hard Coat, 30% Brick Veneer

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 20% Carpet, 20% Sheet Vinyl, Interior Wall Finish: 100% Paint

20% Vinyl Plank, 20% Laminate, 20% Hardwood - Plank

Ceiling Finish: 100% Paint

Rooms
Kitchens: 1 Large - (15'x11')
Bathrooms: 1 Half Bath, 1 Full Bath, 1 1.5 Bath

Bedrooms: 1 Medium - (10'x10'), 2 Large - (14'x12'), Living Areas: 1 Medium - (18'x12'), 1 Large - (20'x14')

1 Extra Large - (16'x14') Entry/Foyer: 1 Medium - (10'x10')

Dining Rooms: 1 Medium - (18'x12')

Hallways: 1 Medium - (15'x4'), 1 Large - (15'x6')

Laundry Rooms: 1 Medium - (10'x8')

Utility Rooms: 1 Large - (12'x10')

Nooks: 1 Medium - (10'x10') Walk-In Closets: 1 Large - (12'x10')

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None

Size: Large

Appliances: 1 Garbage Disposal, 1 Dishwasher, 1 Range Counters: 100% Plastic Laminate

Hood, 1 Free Standing Range Cabinets: Peninsula Bar Bath (Above Ground Room):

Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bath (Above Ground Room):

Quality Adjustment: None Size: Small

Type: Half Bath Vanity Tops: 100% Plastic Laminate

Bath (Above Ground Room):

Quality Adjustment: None Size: Large

Type: 1.5 Bath Vanity Tops: 100% Plastic Laminate

Fixtures: 1 Ceramic Tile Tub/Shower Surr.

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Large

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Large

Bedroom (Above Ground Room):

Quality Adjustment: None Size: X-Large

Living Area (Above Ground Room):

Quality Adjustment: None Size: Medium

Room Features: Cathedral/Vaulted Ceiling

Living Area (Above Ground Room):

Quality Adjustment: None Size: Large

Room Features: Cathedral/Vaulted Ceiling

Dining Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Entry/Foyer (Above Ground Room):

Quality Adjustment: None Size: Medium

Laundry Room (Above Ground Room):

Quality Adjustment: None Size: Medium

Hallway (Above Ground Room):

Quality Adjustment: None Size: Medium

Hallway (Above Ground Room):

Quality Adjustment: None Size: Large

Nook (Above Ground Room):

Quality Adjustment: None Size: Medium

Utility Room (Above Ground Room):

Quality Adjustment: None Size: Large

Walk-In Closet (Above Ground Room):

Quality Adjustment: None Size: Large

Attached Structures

Porch #1:

Square Footage: 200 Material: Concrete Porch

Covered: 100% Enclosed: 0%

Outdoor Fireplace: No

Deck #1:

Square Footage: 120 Material: Treated Deck

Covered: 0% Enclosed: 0% Shape: Rectangle Height: 3

Levels: 1 Benches Length(ft): 0

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 3 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Estimated Cost Breakdown

 Appliances: \$2,708.80
 Electrical: \$15,252.88

 Exterior Finish: \$50,627.10
 Floor Covering: \$15,241.00

 Heating/AC: \$14,356.79
 Interior Finish: \$99,056.22

 Plumbing: \$15,073.69
 Roofing: \$12,936.06

 Rough Framing: \$57,272.76
 Windows: \$9,404.86

Permits: \$3,678.32 Other Fees and Taxes: \$100,089.00

Estimated Replacement Cost

Calculated Value:

\$395,697.47

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

The following slab items are excluded from this value: Foundation

23.7.15 PL:ABCAXV_SEP23