Replacement Cost Estimate

Prepared by: User DAVID.SOL@IBIGROUP.C

Valuation ID: BT2UM65.1

(In Canadian Dollars)

Owner Information

Name: XM8 ONLINE Date Entered: 08/09/2023 Street: -Date Calculated: 08/09/2023

City, Province Postal Code: -, - T2G 5E1 Created By: User DAVID.SOL@IBIGROUP.C

Country: Canada User: 8D XM8Profile

General Information

Most Prevalent Number of Stories: 2 Stories Sq. Feet: 1200 Use: Single Family Detached Year Built: 2000

Home Quality Grade: Above Average Cost per Finished Sq. Ft.: \$169.61

Site Access: Average - No Unusual Constraints

Foundation

Foundation Shape: 4-5 Corners - Square/Rectangle Foundation Type: 100% Basement Percent of lowest level that is finished: 100% Basement Quality Adjustment: None

Foundation Material: 100% Concrete Property Slope: None (0 - 15 degrees)

Walk-out Basement: No

Exterior Number of Dormers: 0 Roof Shape: Gable

Roof Cover: 100% Composition - Architectural Shingle Roof Construction: 100% Wood Framed

Exterior Wall Construction: 100% Wood Framing Exterior Wall Finish:

70% Stucco - Traditional Hard Coat, 30% Brick Veneer

Interior

Average Wall Height: 8 Interior Wall Material: 100% Drywall

Floor Coverings: 25% Carpet, 50% Hardwood - Plank, Interior Wall Finish: 75% Paint, 25% Wallpaper

25% Tile - Ceramic Ceiling Finish: 100% Paint

Rooms

Kitchens: 1 Medium - (11'x10') Bathrooms: 2 Full Bath

Bedrooms: 2 Medium - (10'x10'), 3 Large - (14'x12') Living Areas: 1 Large - (20'x14') Dining Rooms: 1 Small - (14'x10') Hallways: 1 Small - (10'x3')

Nooks: 1 Small - (8'x6') Utility Rooms: 1 Small - (7'x5')

Room Details

Kitchen (Above Ground Room):

Quality Adjustment: None Size: Medium

Appliances: 1 Dishwasher, 1 Space Saver Microwave, Counters: 100% Quartz

1 Free Standing Refrigerator, 1 Built-in Range Cabinets: Peninsula Bar

Bath (Above Ground Room): Quality Adjustment: None Size: Medium

Type: Full Bath Vanity Tops: 100% Quartz

Fixtures: 1 Cult. Marble Tub/Shower Surr.

Bath (Basement Room): Quality Adjustment: None Size: Medium

Type: Full Bath

Vanity Tops: 100% Quartz

Fixtures: 1 Cult. Marble Tub/Shower Surr. Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium

Bedroom (Above Ground Room):

Quality Adjustment: None Size: Medium Bedroom (Above Ground Room):

Quality Adjustment: None Size: Large

Bedroom (Basement Room):

Quality Adjustment: None Size: Large

Bedroom (Basement Room):

Quality Adjustment: None Size: Large

Living Area (Above Ground Room):

Quality Adjustment: None Size: Large

Room Features: Cornice or Crown Molding

Dining Room (Above Ground Room):

Quality Adjustment: None Size: Small

Hallway (Above Ground Room):

Quality Adjustment: None Size: Small

Nook (Above Ground Room):

Quality Adjustment: None Size: Small

Utility Room (Basement Room):

Quality Adjustment: None Size: Small

Attached Structures

Porch #1:

Square Footage: 50 Material: Concrete Porch

Covered: 100% Enclosed: 25%

Outdoor Fireplace: No

Systems

Heating: 1 Forced Air Heating System Air Conditioning: 1 Central Air Conditioning

Home Features

Exterior Doors: 2 Exterior Doors, 1 Sliding Patio Door Electrical Features: 1 Electrical Service Size - 200 amp

Lighting: 1 Ceiling Fan

Estimated Cost Breakdown

 Appliances: \$4,273.21
 Electrical: \$12,192.72

 Exterior Finish: \$41,483.44
 Floor Covering: \$17,767.44

 Heating/AC: \$14,619.05
 Interior Finish: \$79,462.78

Plumbing: \$10,846.20 Roofing: \$4,461.98

Rough Framing: \$33,523.33 Specialty Features: \$254.33 Windows: \$6,346.01 Permits: \$2,837.90

Other Fees and Taxes: \$77,220.86

Estimated Replacement Cost

Calculated Value:

\$305,289.25

(\$297,431.00 - \$313,147.00)

The estimated replacement costs and other data reflected herein in this "Report" represent approximated costs to rebuild a structure similar to the structure described herein. The estimate is (i) intended to reflect pricing for labor, materials, applicable permits and fees, sales tax, and contractor's overhead and profit and (ii) not intended to reflect costs for major excavation or land value.

This Report is not intended to: (i) serve as the sole source of information, but rather one of several sources, for estimating replacement costs and not guaranteed to represent actual replacement costs; (ii) serve as a statement as to the existence or condition of the structure or property; and (iii) serve as market value appraisals or an assessment of market conditions. This Report has not been adapted to or conformed to any mortgage-lending or real estate-industry regulations, standards or purposes and, without limitation, may not be used or distributed for any real estate-related purpose, including distribution to a mortgage lending institution or use for purposes of a real estate closing. Residential property prefill powered by SmartSource®. The Verisk Logo, 360Value® and SmartSource are registered trademarks of Insurance Services Office, Inc.

The following slab items are excluded from this value: Foundation

23.5.9 PL:ABCAXV_AUG23