



Close these jumpers to hard-set I2C mode.

Gyro Address = 0x6B

Accel/Mag Address = 0x1D







Set the SDO\_G and SDO\_XM to set the gyro and accel/mag I2C addresses:

SDOG/XM	XM Addr.	G Addr.
0	0x1E	0x6A
1	0x1D	0x6B

Released under the Creative Commons Attribution Share-Alike 3.0 License http://creativecommons.org/licenses/by-sa/3.0



TITLE: lsm9ds0-breakout

Design by: Jim Lindblom REU: v10

Date: 1/21/2014 11:45:32 AM Sheet: 1/1

