

EcoSense AI Report

Decision Summary

Main issue is high anomaly frequency. Best next step is stabilize operating schedule.

Technical Summary

Top issue: High anomaly frequency

Top cause: daily usage is inconsistent

Top action: Stabilize operating schedule

Confidence: 65/100 (medium)

Detected Issues

- High anomaly frequency | severity=high | confidence=0.88
- Unstable usage pattern | severity=medium | confidence=0.81
- High base load | severity=high | confidence=0.84

Recommended Actions

- Stabilize operating schedule

when=today | impact=high | urgency=high

Check whether cooling, lighting, or heavy equipment is being used inconsistently

- Reduce after-hours load

when=today | impact=high | urgency=high

Check always-on equipment and switch off unnecessary loads after operating hours

Likely Causes

- factor=irregular_schedule

impact=daily usage is inconsistent

evidence=variability ratio=0.16

confidence=0.82

- factor=always_on_load

impact=some loads may be left on continuously

evidence=minimum consumption=139.99 kWh

confidence=0.85