

EcoSense AI Report

Decision Summary

Main issue is high anomaly frequency. Best next step is continue monitoring. Decision also considers building size and occupancy.

Technical Summary

Decision rationale for selected building:

- Building context: type=residential_tower, area=52000.0, flats=170.0, occupancy=530.0
- Consumption pattern: avg=231.9 kWh, min=140.0 kWh, max=348.5 kWh, variability ratio=0.16, anomalies=9, trend=stable
- Normalized intensity: kWh/sqft=0.004458863247863247, kWh/flat=1.363887581699346, kWh/occupant=0.43747337526205443
- Statistical cause signal: No major cause identified
- Decision priority: Continue monitoring
- Confidence: 89/100 (high)
- Compliance score: 67 (Acceptable)

Detected Issues

- High anomaly frequency | severity=high | confidence=0.88
- Unstable usage pattern | severity=medium | confidence=0.81
- High base load | severity=high | confidence=0.84

Evidence

- [bm25] Buildings with high usage variability should review HVAC and lighting schedules.
- [bm25] Energy audits should prioritize anomaly-heavy buildings for operational inspection.
- [bm25] Always-on base loads often indicate standby waste or uncontrolled equipment operation.
- [bm25] Replacing inefficient cooling equipment can significantly reduce long-term energy use.
- [statistical] Consumption stats: avg=231.9 kWh, min=140.0 kWh, max=348.5 kWh

Compliance

Score: 67

Status: Acceptable