## Contoso Safety 360 Form

	☐ At Risk Behavior
☐ Safety Suggestion	⊠Safety Recognition
☐ Equipment	☐ Material Handling
☐Slips, Trips, Falls	⊠Spill, Release, Environmental
□Electrical	□PPE
□Ergonomics	□ Other Safety
⊠Significant	□ Not Significant
Findings: Spills of lubrication oils were disc	covered in area 8-80 on the 8th floor.
In addition, equipment 8-ax1 has some yellow	
, , , , , , , , , , , , , , , , , , ,	
Constant Columbiance Maintenance tasks are	performed immediately. Workers are released today.
Suggested Solutions: Maintenance tasks are Sign offs are required by immediate supervisor.	performed immediately. Workers are released today.
sign ons are required by infinediate supervisor.	
Submitter: Hayat Hassen	
Submitter: Hayat Hassen Department: Manufacture floors	Date: July 11, 2022
	Date: July 11, 2022
Department: Manufacture floors	Date: July 11, 2022
Department: Manufacture floors  Owner: Sonila Rama	Date: July 11, 2022
Department: Manufacture floors  Owner: Sonila Rama Suggested solutions are implication for defined. Pariedic inspec	olemented. In addition, an enhanced safety check
Department: Manufacture floors  Owner: Sonila Rama Solution Suggested solutions are imp	olemented. In addition, an enhanced safety check