⊠ Hazardous Condition	☐ At Risk Behavior
☐Safety Suggestion	☐ Safety Recognition
\[\sqrt{2} = \cdot \cd	
⊠ Equipment	☐ Material Handling
☐ Slips, Trips, Falls	☐ Spill, Release, Environmental
□Electrical	□PPE
□Ergonomics	⊠ Other Safety
⊠Significant	☐ Not Significant
F' I' Mold plate was thrown out of CNC	Magnetic Plate was being used
Findings: Mold plate was thrown out of CNC. Mold went through Plexi Glass Roof.	. Magnetic Plate was being used.
iviola went through Flexi Glass Roof.	
Suggested Solutions: Fix the equipment a	b1, exam equipment room to make sure that
all safety conditions be met.	
Submitter: Daleen du Plessis	
Department: Tower Room	Date: July 26, 2022
Department. Tower Room	Date. July 20, 2022
Owner: Etleva Hysa	
Solution Fixed the equipment ab1, exam equipment room to make sure that all safety	
Description: conditions are met. Expand	ed Checklist.
Target Date: July 29, 2022	Close Date: July 28, 2022
Submitter Approval: Yes	,

\square Hazardous Condition	☐ At Risk Behavior
⊠Safety Suggestion	⊠Safety Recognition
□Equipment	☐ Material Handling
☐Slips, Trips, Falls	☐ Spill, Release, Environmental
□ Electrical	⊠PPE
☐ Ergonomics	□Other Safety
	Editor sarety
⊠Significant	□ Not Significant
Findings: Insufficient PPEs for Equipment ope	erators on 1st floor, 3rd floor, 7th floor, and
Basement.	
Suggested Solutions: Borrow 300 PPEs fro	m shipping room and order 5000 PPEs right away.
Reengineering selected PPEs for a small back up b	patch.
-	
Submitter: Sonila Rama	
	D-t-: 1
Department: Manufacture floors	Date: July 5, 2022
Owner: Sonila Rama	
Solution	nt team by end of the day today. Inform
Description: supervisor.	
Target Date: July 15, 2022	Close Date: July 15, 2022
Submitter Approval: Yes	

☐ Hazardous Condition	☐ At Risk Behavior	
⊠Safety Suggestion	⊠Safety Recognition	
_		
⊠Equipment	⊠ Material Handling	
☐Slips, Trips, Falls	☐ Spill, Release, Environmental	
□Electrical	□PPE	
□Ergonomics	☐ Other Safety	
⊠Significant	□ Not Significant	
Single Aliana Maintenances tooling set ah3 needs	to be replaced or refurbished within 2 weeks.	
Findings: Maintenances tooling set ab3 needs Suggested actions be to complete within 2 weeks		
Suggested detions be to complete within 2 weeks	Tront the day of reporting.	
3466cstc4 3014t10113.	schedule to refurbish and replace specified tooling.	
Suggested actions be to complete within 2 weeks from the day of reporting.		
Submitter: Gifti Boru		
Department: Manufacture floors	Date: July 16, 2022	
Owner: Sonila Rama		
ones in the storage	if possible. Otherwise replace tools with new	
Description: Ones in the storage.		
Target Date: June 23, 2022	Close Date: June 21, 2022	
Submitter Approval: Yes		

\square Hazardous Condition	☐ At Risk Behavior
⊠Safety Suggestion	⊠Safety Recognition
⊠ Equipment	☐ Material Handling
☐Slips, Trips, Falls	☐ Spill, Release, Environmental
□Electrical	□PPE
□Ergonomics	⊠Other Safety
⊠Significant	☐ Not Significant
Findings: Maintenances tooling set ab3 needs	s to be replaced or refurbished within 2 weeks.
Wear and tear degrees are ahead of schedule.	
Wedi and teal degrees are alleded of softensies	
3486cstca 3014tions.	schedule to refurbish and replace specified tooling.
Suggested actions be to complete within 2 weeks	from the day of reporting.
Submitter: Gifti Boru	
Department: Control Room	Date: July 11, 2022
•	•
Owner: Sonila Rama	
ones in the storage	I if possible. Otherwise replace tools with new
Description: Ones in the storage.	
Target Date: July 20, 2022	Close Date: July 20, 2022
Submitter Approval: Yes	

	⊠At Risk Behavior	
☐Safety Suggestion	⊠Safety Recognition	
□ Equipment	☐ Material Handling	
⊠Slips, Trips, Falls	⊠Spill, Release, Environmental	
□Electrical	□PPE	
□Ergonomics	⊠ Other Safety	
⊠Significant	□ Not Significant	
Findings: Equipment rooms are not organized	d and cleaned via set guidelines.	
There are spills on 3 rd floor area 3-58.	1 und occured the 200 Sundammen.	
Poquest current shift y		
3466c3tc4 3014t10113.	workers to enhance daily maintenance and cleaning.	
Sign offs are required by immediate supervisor.		
Submitter: Hayat Hassen		
Department: Manufacture floors	Date: August 16, 2022	
Conila Roma		
Owner: Sonila Rama Suggested solutions are imp	clamanted in addition an enhanced safety check	
list is defined Periodic inspe	Solution Suggested solutions are implemented. In addition, an enhanced safety check list is defined. Periodic inspections will be performed.	
Description.		
Target Date: August 16, 2022	Close Date: August 16, 2022	
Submitter Approval: Yes		