

Date: 2026-02-10

Equipment: Hydraulic Press #A12

Location: Line 3

Observed Problem: Cylinder pressure drop noted, irregular noise at 08:15

Inspection Steps:

- Visually inspected hoses — no visible leak
- Pressure gauge reading: 1450 PSI (normal 1500-1600 PSI)
- Checked valve actuator — movement inconsistent

Corrective Action:

- Tightened valve actuator linkage
- Replaced worn pressure relief seal

Outcome: Pressure stable at 1520 PSI; noise resolved

Technician: J. Lin

Date: 2026-02-12

Equipment: Air Compressor C07

Issue: Overheating during operation

Checks:

- Coolant level: OK
- Fan blades clogged — cleaned
- Belt tension low — adjusted

Corrective Action:

- Cleaned cooling fins; checked bearing play

Result: Temperature normalized; scheduled annual service

Technician: L. Wang