





Decapsulation
(Nitric acid...)



Discover blown fuse
(May need FIB to
expose layer)



Deposit new material over fuse