△ string with hex value to byte

```
ardugebruiker
                                                                       Feb '21 post #1
how to convert string to byte?
eg: string "60" to byte 0x60
eg: string "a5" to byte 0xa5
thx in advance
christop
                                                                       Feb '21 post #2
Use strtoul(). Set the base to 16, and you can just pass in NULL for the endptr argument,
like so:
char s[] = "60";
byte b = strtoul(s, nullptr, 16);
 // b is now 0x60
ardugebruiker
                                                                       Feb '21 post #3
okay and how to convert string to char[]?
eg
String a = "60";
to ...
ardugebruiker
                                                                       Feb '21 post #4
String test = "60";
char charbuf[2];
test.toCharArray(charbuf, 8);
byte b = strtoul(s, nullptr, 16);
---error = exit status 1
's' was not declared in this scope
anon73444976
                                                                       Feb '21 post #5
char charbuf[2]; is not big enough to contain your string
christop
                                                                       Feb '21 post #6
You don't need to copy the String to a string. Use c_str() to get to the String's internal
string buffer:
 String test = "60";
 byte b = strtoul(test.c_str(), nullptr, 16);
Closed on Jun 10, '21
```

This topic was automatically closed 120 days after the last reply. New replies are no longer allowed.

Skip to main content

Back to top

Help Center

Contact Us

Trademark & Copyright

Brand Guidelines

Distributors

Careers

© 2020 Arduino

Terms of Service

Privacy Policy

Security

Cookie Settings

FOLLOW US