Show Stoppers

We Found None!

Problems Automatically Fixed

Insufficient Soldermask Clearance (2 violations)	1 2
Insufficient Silkscreen Line Width (10 violations)	1 2 3 4 5