

Slim WISC assembly: quick reference

Please watch the video for full instruction: tinyurl.com/slimwisc


Components



Assembly




 Peel film off both sides of plastic




Peel backing off foam and center along top edge of mask

Foam should be 1.75 inches in from each side



3. Double staple elastic on both sides close to edge

(do not staple through foam)



 Package in groups of 10 with a printed disclaimer sheet in a clear bag

> Disclaimer sheet PDF is on the laser computer desktop if you need more