

12/30/13

Press RES_PCA on the calibration screen

YES

Power off

Jog the axis until fault disappears