



OF PEMBROKE PINES

16150 PINES BLVD.
PEMBROKE PINES, FLORIDA 33027
SERVICE: 954-443-2332
MV36474
www.lexusofpembrokepines.com

A Craig Zinn Quality Control 9/27/929 592

CUSTOMER NO.	304968	ADVISOR	JOSUE LUNA CHAVARR	317723	TAG NO.	0155	INVOICE DATE	06/12/23	INVOICE NO.	LPCS91983
PURNA DIVYA THURAGA 500F FALLS BLVD APT 6213 QUINCY, MA 02169-8184 turagapurnadivya@gmail.com		LABOR RATE	LICENSE NO.		MILEAGE	26,775	COLOR	CAVIAR/BLAC	STOCK NO.	
		YEAR/MAKE/MODEL	197 LEXUS/NX300/		DELIVERY DATE	03/14/19	DELIVERY MILES			
		VEHICLE ID NO.	J T J B A R B Z X K 2 2 0 8 4 5 9		SELLING DEALER NO.	01730719	PRODUCTION DATE			
RESIDENCE PHONE	786-635-8889	BUSINESS PHONE	COMMENTS		P.O. NO.	06/12/23	MO:	26776		

JOB# 1 CHARGES

LABOR
D# 1 04LEZ01 (0) REPLACE 1 TIRE TECH(S):261453 50.00
CUSTOMER REQUEST TO REPLACE PASSENGER REAR
Mount & Balance 1 Tire 1 Tire

PARTS-QTY--FP-NUMBER-----DESCRIPTION-----LIST PRICE-UNIT PRICE-
1 90942-03280-S WHEEL WEIGHT 1.99 1.99 1.99
2 90942-03210-X WHEEL WEIGHT/ 0.99 0.99 1.98
1 DT009-32460-YK OEA 225/60R18 YK 297.99 297.99 297.99
TOTAL - PARTS 301.96

JOB# 1 TOTALS-----
LABOR 50.00
PARTS 301.96

JOB# 1 JOURNAL PREFIX LPCS JOB# 1 TOTAL 351.96

JOB# 2 CHARGES-----
LABOR
D# 2 01LEZ104 *25 PT INSPECTION TECH(S):261453 INTERNAL
PERFORM 25 POINT INSPECTION
Done

JOB# 2 TOTALS-----
JOB# 2 JOURNAL PREFIX LPCS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES-----

LABOR
D# 3 01LEZ02B TEXT/EMAIL APPROVAL TECH(S):261453 INTERNAL
I HEREBY CONSENT TO RECEIVE AUTOMATICALLY-DIALED AND/
OR PRE-RECORDED TELEPHONE CALLS OR TEXT MESSAGES, FROM LEXUS
OF PEMBROKE PINES AT THE TELEPHONE NUMBER(S) I HAVE PROVIDED
LEXUS OF PEMBROKE PINES MAY PLACE SUCH CALLS TO: (1) NOTIFY
YOU REGARDING YOUR PURCHASE, LEASE OR REPAIR; (2) CONTACT
YOU WITH ADVERTISEMENTS; OR (3) AS OTHERWISE NECESSARY TO
SERVICE YOUR ACCOUNT OR ENFORCE THIS AGREEMENT, APPLICABLE
LAW, OR ANY OTHER AGREEMENT WE MAY HAVE WITH YOU. CONSENT IS
NOT A CONDITION OF SERVICES OR PURCHASE.
D

PARTS-QTY--FP-NUMBER-----DESCRIPTION-----LIST PRICE-UNIT PRICE-
1 00276-00900 WHEEL LK,ALLOY 85 41.99 41.99 41.99
TOTAL - PARTS 41.99

JOB# 3 TOTALS-----
PARTS 41.99

JOB# 3 JOURNAL PREFIX LPCS JOB# 3 TOTAL 41.99

JOB# 4 CHARGES-----

LABOR-----

DISCLAIMER OF WARRANTIES
The seller hereby expressly disclaims all warranties,
either express or implied, including any implied
warranty of merchantability or fitness for a particular
purpose, and neither assumes nor authorizes any
other person to assume for it any liability in
connection with the sale of said products.

**ALL PARTS INSTALLED ARE NEW
UNLESS SPECIFIED OTHERWISE
AS BEING USED OR REMANUFACTURED.**

*Thank
You*



OF PEMBROKE PINES

16150 PINES BLVD.
PEMBROKE PINES, FLORIDA 33027
SERVICE: 954-443-2332
MV36474
www.lexusofpembrokepines.com

ISS

A Craig Zinn Alternative Credit Corp. 997-929-5592

CUSTOMER NO. 304968	ADVISOR JOSUE LUNA CHAVARR	TAG NO. 0155	INVOICE DATE 06/12/23	INVOICE NO. LPC591983
PURNADIVYA THURAGA 500F FALLS BLVD APT 6213 QUINCY, MA 02169-8184 turagapurnadivya@gmail.com	LABOR RATE	LICENSE NO.	MILEAGE 26,775	COLOR CAVIAR/BLAC
	YEAR / MAKE / MODEL 19/LEXUS/NX300/		DELIVERY DATE 03/14/19	DELIVERY MILES
	VEHICLE I.D. NO. J T J B A R B Z X K 2 2 0 8 4 5 9	F.T.E. NO.	P.O. NO.	SELLING DEALER NO.
RESIDENCE PHONE 786-635-8889	BUSINESS PHONE	COMMENTS	R.O. DATE 06/12/23	PRODUCTION DATE 01/30/19
				MO: 26776

LABOR
D# 4 01LEZ00 FLOOR MAT INSPECTION TECH(S):261453 INTERNAL

WARNING: DO NOT STACK THE FLOOR MATS IN ANY VEHICLE. THE RETAINING HOOKS AND OR CLIPS ARE DESIGNED TO ACCOMMODATE ONLY ONE FLOOR MAT AT A TIME. MAT STACKING CAN CAUSE AN UNSAFE CONDITION

THE RETAINING HOOKS (CLIPS) ARE DESIGNED TO ACCOMMODATE ONLY ONE FLOOR MAT AT A TIME. DO NOT INSTALL ANOTHER FLOOR MAT(S) ON TOP OF AN EXISTING DRIVERS FLOOR MAT. YOU SHOULD NEVER INSTALL FRONT DRIVERS FLOOR MAT WITHOUT ALL RETAINING HOOKS CLIPS SECURING THE MAT FIRMLY IN PLACE.

NOTE- IF YOUR VEHICLE ARRIVED WITH DOUBLE STACKED FLOOR MATS THE ADDITIONAL STACKED DRIVERS FRONT FLOOR MAT HAS BEEN REMOVED AS A SAFETY PRECAUTION DURING YOUR DEALER SERVICE VISIT TODAY. DOUBLE STACKING FLOOR MATS CAN LEAD TO A POTENTIALLY DANGEROUS SITUATION- PLEASE SEE YOUR SERVICE ADVISOR WITH ANY CONCERNs. THANK YOU FOR YOUR COOPERATION

JOB# 4 TOTALS

JOB# 4 JOURNAL PREFIX LPCS JOB# 4 TOTAL 0.00

MISC-----CODE-----DESCRIPTION-----	CONTROL NO-----
JOB # A DS DATA STORAGE FEE	0.97
JOB # A C1 SHOP SUPPLIES	4.00
	TOTAL - MISC 4.97

PAID
JUN 12 2023
\$ DB# CR

TOTALS-----

LEXUS OF PEMBROKE PINES: "A GREAT CAR DESERVES A GREAT DEALER".

TOTAL LABOR....	50.00
TOTAL PARTS....	343.95
TOTAL SUBLET...	0.00
TOTAL G.O.G....	0.00
TOTAL MISC CHG.	4.97
TOTAL MISC DISC	0.00
TOTAL TAX.....	27.93

TOTAL INVOICE \$ **426.85**

CUSTOMER SIGNATURE

Thank You