
STANDARD DEPARTURE CHART -INSTRUMENT



STANDARD DEPARTURE CHART -INSTRUMENT

RORT / TARAMA RNAV SID

■ GAHRA TWO DEPARTURE

RWY18

Serial Numbe	Path Descriptor	Waypoint Identifier	Fly Over		Magnetic Variation		Turn Direction	Altitude (FT)	'		Navigation Specification
001	VA	_	_	177 (172.8)	■ -4.5	_	_	+500	_	_	Basic RNP1
002	DF	GAHRA	_	_	■ -4.5	_	L	+3000	_	_	Basic RNP1

RWY36

Serial Number	Path Descriptor	Waypoint Identifier	Fly Over		Magnetic Variation		Turn Direction		'		Navigation Specification
001	VA	_	_	357 (352.8)	■ -4.5	_	_	+500	_	_	Basic RNP1
002	DF	GAHRA	_	_	■ -4.5	_	R	+3000	_	_	Basic RNP1