

INSTRUMENT APPROACH CHART



INSTRUMENT APPROACH CHART

Visual Prescribed Track for LDA Z RWY23

Visual Prescribed Track for LDA Z RWY23



In case of GO AROUND, pilot should report ATC as soon as practicable.

Until receiving ATC instructions, aircraft turn left HDG 229° for joining HME R177 and missed approach procedure.

CHANGE: Correction of misdescription (ITL COORD)