STANDARD DEPARTURE CHART -INSTRUMENT

RJNG / GIFU SID

NORIC TWO DEPARTURE

RWY28: Climb via GFT R-285 to GFT 6DME, then turn right,....

RWY10: Turn left, climb via GFT R-090 to GFT 7DME, then turn left,....

....climb via GFT R-044 to HOUBA.

: When Take off RWY10/28, maintain rate of climb 300ft/NM Note

or more until passing 11,500ft.

Caution: When take off RWY10, high terrain exists in southeast side of airport

(Right of departure course).

NEO TWO DEPARTURE

RWY28: Climb via GFT R-285 to GFT 6DME, then turn right,....

RWY10: Turn left, climb via GFT R-090 to GFT 7DME, then turn left,....

....climb via GFT R-308 to IBUKI. Cross IBUKI at or above 11,000ft.

: When Take off RWY10/28, maintain rate of climb 300ft/NM Note

or more until passing 4,500ft.

Caution: When take off RWY10, high terrain exists in southeast side of airport

(Right of departure course).

