
STANDARD DEPARTURE CHART - INSTRUMENT

RJFM / MIYAZAKI

RNAV SID and TRANSITION

KIZAK TWO DEPA MADOG TRANS	RNAV1			
Note 1) DME/DME/IRU or GNSS required. **The aircraft equipped with only DME/DME/IRU must be able to update its position without delay at the starting point of take-off roll. 2) RADAR service required.	Critical DME	RWY27 TGE : 4.0NM to KIZAK - KIZAK		
	DME GAP	RWY09 : DER - 4.0NM to KIZAK RWY27 : DER - 4.0NM to KIZAK		
	Inappropriate Navaids	See AD1.1.6.10.3. Inapp	propriate NAVAIDs for RNAV1	

VAR 7° W(2016)



KIZAK TWO DEPARTURE

RWY09: Climb on HDG092° at or above 500FT, direct to KIZAK.

RWY27: Climb on HDG272° at or above 500FT, direct to FM700, to FM701, to FM702, to KIZAK.

NOTE RWY09: 5.0% climb gradient required up to 500FT. NOTE RWY27: 7.0% climb gradient required up to 900FT.

MADOG TRANSITION

From KIZAK, to HIROS at or above 11000FT, to MADOG.

STANDARD DEPARTURE CHART - INSTRUMENT

RJFM / MIYAZAKI

RNAV SID and TRANSITION

KIZAK TWO DEPARTURE

RWY09

Serial Number	Path Descriptor	Waypoint Identifier	Fly Over		Magnetic Variation		Turn Direction			l	Navigation Specification
001	VA	_	_	092 (085.2)	-6.8	_	_	+500	_	_	RNAV1
002	DF	KIZAK	_	_	-6.8	_	R	_	_	_	RNAV1

RWY27

Serial Number	Path Descriptor	Waypoint Identifier	Fly Over	Course °M(°T)	Magnetic Variation	Distance (NM)	Turn Direction	Altitude (FT)	Speed (KIAS)	Vertical Angle	Navigation Specification
001	VA	_	_	272 (265.2)	-6.8	_	_	+500	-	_	RNAV1
002	DF	FM700	_	_	-6.8	_	_	_	1	_	RNAV1
003	TF	FM701	_	002 (355.2)	-6.8	5.6	-	_	-	_	RNAV1
004	TF	FM702	_	092 (085.2)	-6.8	4.7	ı	_	-	_	RNAV1
005	TF	KIZAK	_	152 (144.5)	-6.8	17.1	ı	_	ı	_	RNAV1

MADOG TRANSITION

Serial Number	Path Descriptor	Waypoint Identifier	Fly Over	Course °M(°T)	Magnetic Variation	1	Turn Direction	Altitude (FT)	Speed (KIAS)	Vertical Angle	Navigation Specification
001	IF	KIZAK	_	-	-6.8	_	1	-	_	_	RNAV1
002	TF	HIROS	_	076 (069.0)	-6.8	31.8	_	+11000	_	_	RNAV1
003	TF	MADOG	_	045 (038.4)	-6.8	15.4	_	_	_	_	RNAV1