STANDARD DEPARTURE CHART - INSTRUMENT

RJAH / HYAKURI

SID and TRANSITION

OGITU ONE DEPARTURE

RWY 03R/03L: Climb RWY HDG to 600FT,....

RWY 21R/21L: Climb RWY HDG to 600FT, turn right HDG 062° to intercept and

proceed....

....via HUC R032 to OGITU.

Cross HUC R032/5.5DME at or below 7000FT, cross OGITU at or

below 10000FT.

Note: This SID for VOR equipped aircraft only.

IWAKI TRANSITION

From over OGITU, proceed via IXE R213 to IXE VOR/DME.

OKUJI TRANSITION

From over OGITU, via HUC R032 to 32.5DME, turn left to intercept and proceed via HUC 35.2DME counterclockwise ARC to OKUJI.

Cross OKUJI at or above 9000FT.

