## STANDARD DEPARTURE CHART-INSTRUMENT

**RJCJ / CHITOSE** SID

## MUKAWA FIVE DEPARTURE

RWY 36R/36L: Climb via RWY HDG to 500ft or above, turn right within 4NM,climb via MKE R-336 to MKE VOR/DME, then via MKE R-202 to TOBBY.

> Cross MKE R-336/12DME at or above 3,000ft. Cross MKE VOR/DME at or below 11,000ft.

RWY 18R/18L: Climb via RWY HDG to 500ft or above, turn left, climb via MKE R-321 to MKE VOR/DME, then via MKE R-202 to TOBBY.

Cross MKE R-321/10DME at or above 3,000ft.

