#### STANDARD DEPARTURE CHART - INSTRUMENT

### **RJAW / IWOTO**

### SID and TRANSITION

## IWO TWO DEPARTURE

RWY 07/25 : Climb RWY HDG to 1000' or above, then proceed as directed by ATC. Remarks: IWO TWO DEPARTURE is not illustrated.

# CHIDORI TWO DEPARTURE

RWY 07 : Climb RWY HDG to 1000' or above, turn left HDG305° to intercept

and proceed via IJT R-335 (336° from OX) to CHIDORI.

RWY 25 : Climb RWY HDG to 1000' or above, turn right HDG005° to intercept

and proceed via IJT R-335 (336° from OX) to CHIDORI.

# **CHIDORI TRANSITION**

After CHIDORI, proceed via IJT R-335 (336° from OX) to NORTH CHIDORI. Cross NORTH CHIDORI at assigned altitude.

