



DATE : 18 SEPTEMBER 2025

FOR : THE PRESIDENT

FROM : OPERATIONS

**SUBJECT: PROPOSED LEIAAI OPNS MEMO 0166-25:
BOD GUIDANCE DATED 26 AUGUST 2025**

Sir/Mam:

Attached is the proposed LEIAAI Opns Memo 0166-25 in reference to the **LEIAAI BOD Memo No. 146-25 Subject: BOD Guidance, received dated September 17, 2025**

For your information and approval.

Mrs. Sobasa
-mrsobasa-

COORDINATION:

Head Opns Support _____

MM _____

CFO/Acctg _____

HR/Admin _____

Registrar _____

Logistics _____

ICT _____

[Signature]

RECOMMEND APPROVAL/DISAPPROVAL:

VPO _____

VPA _____

APPROVED/DISAPPROVED:

PRESIDENT _____

REMARKS:

Main Office: San Fernando Airport, Poro Point Freeport Zone, San Fernando City, 2500 La Union, Philippines
Extension Office: 2nd floor, Col. Godofredo M. Juliano Bldg., Bayani Rd., AFPOVAI Ph 5, Western Bicutan, 1630 Taguig City

LEIAAI Opns Memo 166-25

MEMORANDUM

TO : ALL CONCERNED OFFICES/DEPARTMENTS

FROM : THE PRESIDENT

SUBJECT : BOD GUIDANCE DATED 26 AUGUST 2025

DATE : SEPTEMBER 18, 2025

Reference: LEIAAI BOD Memo No. 146-25 Subject: BOD Guidance dated 26 August 2025

All concerned offices and departments are hereby directed to take appropriate action on the following guidance from the Board of Directors:

1. On timeline of Tecnam Training:
 - Admin/HR Department to verify the training schedule availability for November and December 2025.
 - Adjust the academic training of Flight Instructors scheduled for September 2025.
 - Present the revised timeline in next SBM.
2. On Student Update:
 - Registrar to present in the next SBM:
 - o Projected number of flyable student pilots until year-end.
 - o Include an assumption based on the average number of monthly students enrolled from the 1st semester to the current month.
 - o Projected number of students to be enrolled for 3rd and 4th quarter.
3. On Repair of two (2) Rotax Engine:
 - Quality Manager to specify in the TPQSM the required oil type for engine break-in and operational use of newly overhauled engines.
 - Maintenance Department to confirm the correct oil specification with the Technical Representatives.
 - Logistics Office to:
 - o Check if there are any local manufacturers or suppliers of Rotax parts.
 - o Maintain regular follow-ups with Condor and Bowman, and revise the presentation and update the project timeline accordingly.

4. On Cebu Satellite Operations:

- Operations Department to present the status update of Cebu Satellite Operations, including ATOC inclusion, Flight Instructor, and Students for Cebu.
- HR Department to coordinate with CIAAI regarding the confirmation of Mr. Catubig as replacement for Ms. De Luna.

5. Regarding Simulator Equipment:

- ICT to maintain a logbook of all discrepancies and issues identified with the simulator.
- Ensure proper reporting to the Management and BOD on the status and discrepancies of Simulator.

6. Other Matters:

- HR and Operations Department to
 - o Expedite the training of Flight Instructors for Tecnam Equipment Capability.
 - o Identify a Pilot who will be responsible for evaluating the Sky Courier in Hawaii.
- HR Department to
 - o Present the status of Flight Instructors with pending applications to other companies.
 - o HOLD all pertinent documents (e.g., flying time, COR, etc.) for those with unserved training bonds until accountabilities are cleared.
- Operations Department to
 - o Conduct proper evaluation of prospective UPRT Pilot Trainees.
 - o Train at least a maximum of five (5) Flight Instructor, starting this year with two (2) Flight Instructor.

For your strict compliance

CAPT JOSEPH M. PALOMILLO
President



**LEADING EDGE INTERNATIONAL
AVIATION ACADEMY INC.**

A subsidiary of ACDI Multisource Cooperative

Main Office: San Fernando Airport, Poro Point Freeport Zone, San Fernando City, 2500 La Union, Philippines
Extension Office: 2nd floor, Col. Godofredo M. Juliano Bldg., Bayani Rd., AFPOVAI Ph 5, Western Bicutan, 1630 Taguig City

BOD MEMO NO 146- 25

TO : CAPT JOSEPH M PALOMILLO
President
FROM : THE CHAIRPERSON
SUBJECT : BOD GUIDANCE DATED 26 AUGUST 2025
DATE : 27 August 2025

Ref SBM dated 26 August 2025

Management is hereby advised to take appropriate action to the following;

1. Timeline on Tecnam Training
 - Verify training schedule availability for November and December 2025.
 - Adjust the academic training of Flight Instructors on September 2025.
 - Present the revised timeline on next SBM.
2. Students Update
 - To Present the following on the next SBM – August 28, 2025
 - a. Projected number of flyable student pilots until end of the year.
 - b. Include an assumption based on the average number of monthly students enrolled for the 1st semester to current month.
 - c. Projected number of students to be enrolled for 3rd and 4th quarter.
3. Repair of 2 Rotax Engine
 - Specify in the TPQSM the type of oil required for engine break-in of a newly overhauled engine and operational use.
 - Confirm the correct oil specification with the Technical Representative.
 - Check if there are any local manufacturers or suppliers of Rotax parts.
 - Maintain regular follow-ups with Condor and Bowman.
 - Revise the presentation and update the project timeline accordingly.
4. Cebu Satellite Operations
 - Present the status update of Cebu Satellite Operations
 - a. Include the ATOC inclusion, Flight Instructor and Students for Cebu.
 - Coordinate with CIAAI on the confirmation on the acceptance of Mr. Catubig as the replacement of Ms De Luna.
5. Regarding the Simulator Equipment
 - Maintain a logbook of all discrepancies and issues identified with the simulator.
 - Ensure proper reporting to the Management and BOD on the status and discrepancies of Simulator.



**LEADING EDGE INTERNATIONAL
AVIATION ACADEMY INC.**

A subsidiary of ACDI Multinational Cooperative

Main Office: San Fernando Airport, Poro Point Freeport Zone, San Fernando City, 2500 La Union, Philippines
Extension Office: 2nd floor, Col. Godofredo M. Juliano Bldg., Bayani Rd., AFPOVAI Ph 5, Western Bicutan, 1630 Taguig City

6. Other Matters

- Expedite the training for Flight Instructors for Tecnam Equipment Capability.
- Identify a Pilot who will be responsible for evaluating the Sky Courier in Hawaii.
- Present status of Flight Instructors with pending applications with other companies.
- On unserved Training Bond, HOLD all pertinent documents (i.e. flying time, COR, etc.) until all accountabilities are cleared and settled.
- Conduct proper evaluation of prospective UPRT Pilot Trainees.
- Conduct at least a maximum of five (5) Flight Instructors, start this year with two (2) Flight Instructors.

Provide updates on actions taken and submit significant updates to the Board.



GAMMAD