

Incident Post-Mortem: Cluster Zero Cascading Failure

1. Incident Summary

At 14:02 UTC, Cluster Zero experienced a total blackout. This was initiated by a 'Phantom Leak' in the 'Vortex-7' cooling subsystem, which caused the 'Mainframe-Alpha' thermal sensors to provide false-positive readings.

2. Root Cause Analysis

The 'Vortex-7' leak was traced back to a faulty valve supplied by 'Valv-Co', a subsidiary of 'Neo-Tech Industries'. The false-positive from 'Mainframe-Alpha' caused the 'Sentinel Agent' to shut down the 'Power-Grid-Gamma', thinking there was a fire.

3. Cascading Effects

Shutting down 'Power-Grid-Gamma' severed the link to the 'Storage-Delta' array. This resulted in data corruption in the 'Customer-Insight-DB'. Ironically, the 'Healer-Agent' tried to fix the DB using backup data from 'Archive-Sigma', which was already corrupted by the thermal spike.

4. Remediation Plan

Replace all 'Valv-Co' hardware. Update 'Sentinel Agent' logic to cross-verify thermal readings with 'Auxiliary-Sensor-Beta'. Relocate 'Archive-Sigma' to a different geographic zone.