02_WASH on PORTB set bits 0, 1, 2, 3, 4 as input (START, FILL, TEMP, DONE) on PORTD set bits 0, 1, 2, 3 as output (WATER, W_DIR, HEAT, POWDER) START is off turn on WATER and W_DIR FILL is off turn off WATER and W DIR turn on HEAT TEMP is off turn off HEAT turn on POWDER wait 1s turn off POWDER DONE is off

turn on WATER