
X1

Цепь	Конт		
/STB		1	STB-
		2	SDIN
D0		3	RAØ
D1		4	RA1
D2		5	RA2
D3		6	RA3
D4		7	RA4
D5			RA5
D6			SCLK
D7		10	
/ACK		11	3000
NC		' ' 12	
NC			
NC		_13	
NC		_14	
NC		_15	
NC		_16	
/SELIN		17	P/V-
GND		18	GND
GND		19	─
		20	
GND		21	
GND		22	
GND		23	
GND		24	I
GND		25	
GND			



Все резисторы 4к7. C1 - 0.1mkF