



BV No. 235744

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. <u>21-6614</u> Issued By <u>BV</u>
	<u>DAMMAN</u>	<u>AUG 16, 2023</u>		<u>11:30</u>	
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
<u>SUDAJR</u>	<u>S40AJP-365</u>	<u>DAMMAN</u>		☒ Pass ☐ Fail	<u>BV-21-8657</u>
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
<u>JLG</u>	<u>1250 AJP</u>	<u>5002BS</u>	<u>HEWP</u>	<u>0300187431</u>	<u>FEB 15, 2024</u>

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
X	Periodic inspection AND function test for Boom supported elevating work platform As per AS 5-DRAMCO GIT-030, MS292.5	
	~ POSS ~	

RECEIVER NAME: THAYER SIGNATURE: [Signature] INSPECTOR NAME: [Signature]
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 180000