



# SGS INSPECTION SERVICES SAUDI ARABIA CO LTD

شركة اس جي اس لخدمات الفحص العربيّة السعوديّة المحدوده

P.O Box 0725, Jubail, Saudi Arabia - 31951  
Tel : + 966133400044 / Fax : + 966133420212  
Email : info@sgs.com

Report No: SGS-2026-SA-474



|                                                               |                                         |                                                  |                                       |                                                |                                               |                                    |
|---------------------------------------------------------------|-----------------------------------------|--------------------------------------------------|---------------------------------------|------------------------------------------------|-----------------------------------------------|------------------------------------|
| <b>LIFTING EQUIPMENT<br/>INSPECTION REPORT</b>                | <b>RPO No</b><br>NA                     | <b>CRM No</b><br>-                               | <b>Inspection date</b><br>15-Jul-2026 | <b>Inspection time</b><br>10:30                | <b>Previous sticker No</b><br>BV-5931         | <b>Issued By</b><br>Bureau Veritas |
| <b>Department / Contractor</b><br>Sudhir Equipment Rental Co. | <b>Equipment No.</b><br>SRC-STC-050-079 | <b>Equipment Location</b><br>HZEM-6 PARKING AREA | <b>Area</b><br>JAFURAH GCP-6          | <b>Inspection Result</b><br>PASS               | <b>New Sticker No.</b><br>SGS-PASS-6045       |                                    |
| <b>Manufacturer</b><br>SANY                                   | <b>Model</b><br>STC500C5                | <b>Capacity</b><br>50 t                          | <b>Type</b><br>TMS-H                  | <b>Equipment Serial Number</b><br>TC2050CG0072 | <b>Sticker Expiration Date</b><br>14-Oct-2026 |                                    |

Above Equipment was inspected by **SGS Inspection Services Saudi Arabia Co Ltd** in accordance with applicable Saudi Aramco GI's, ASME & API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

| No | NOTES / DEFICIENCIES                                                                                                                  | CORRECTIVE ACTION TAKEN |
|----|---------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| *  | Periodic visual inspection and functional test been carried out as per G.I.7.030 & ASME B30.5 and found OK at the time of inspection. |                         |
| *  | Boom length: 11.3 M - 44.0 M, Five Boom Section Max boom angle: 79.8°.                                                                |                         |
| *  | Main Hook, SWL:50 t, Weight: 400 KG, Serial #: HCZ2550645      Main Hoist Diameter: 16 MM, # of Fall: 04.                             |                         |
| *  | Aux Hook, SWL: 05 t, Weight:85 KG, Serial #: ZX25122712      Aux Hoist Diameter: 16 MM, # of Fall: 01.                                |                         |
| *  | Fly jib stowed during the time of inspection.                                                                                         |                         |
| *  | Plate #: 7593 UAA (Year Model:2026).                                                                                                  |                         |
| *  | Maintain PM service and lubricate all moving parts.                                                                                   |                         |

| User Name      | Badge No. | Telephone No. | Technical Reviewer Name | SGS Inspector Name | Certificate No. | Telephone No.  |
|----------------|-----------|---------------|-------------------------|--------------------|-----------------|----------------|
| Singh Harpreet | CAC015997 | 0535632319    | aqeel hashmi            | Mikecle Araneta    | 80019274        | +966-566714453 |
|                |           |               |                         |                    |                 |                |
| Signature      |           |               | Signature               |                    | Signature       |                |

When re-inspection is requested, a complete copy of this report should be ready to be reviewed by the inspector.

Distribution: Original - Proponent, 1st copy - Inspection Agency, 2nd copy - Inspector

Control Report Number : SGS/JBL/M-26/645 WO:-