

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE JAFURAH GCP-6 (HZEM-6)	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-STC-050-028	EQUIPMENT DESCRIPTION/TYPE TMS-H	SERIAL NO. TC2050CE1418	REPORT No.: SGS-2026-SA-473
CAPACITY (SWL) 50 t	MANUFACTURER SANY	FACILITY / LOCATION HZEM-6 PARKING AREA	
REQUESTED INSPECTION DATE 12-Jul-2026	RFI No SGS-RFI-09161	TASK COMPLETED DATE 15-Jul-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
1	GENERAL REQUIREMENTS					
1.1	Equipment documentation is available	ASME B30.5 Sec:5-2.1.5	✓			
1.2	Preventive Maintenance is established and updated records are maintained	ASME B30.5 Sec:5-2.3.1	✓			
1.3	Daily pre-operational inspection checklists are checked	GI 7.030 Para: 5.1.2	✓			
1.4	Vehicle government registration card (ISTIMARA) and Government periodic inspection are maintained and valid at all times for equipment that has a vehicle plate.	GI 7.030 Para: 7.1.2 Note:5	✓			
1.5	Durable load chart is provided in an accessible location	ASME B30.5 Sec: 5-1.1.3 (b)	✓			
1.6	Work areas chart is available	G.I. 7.025 ASME B30.5 Sec 5-1.1.3(2)	✓			
1.7	Operator is certified (for the inspected crane type/ model) and licensed	G.I. 7.025 ASME B30.5 Sec: 5-3.1.1	✓			
1.8	A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice	SAES-B067 Sec:4.4	✓			
1.9	Crane is painted safety yellow	SAES-B067 Sec:4.4			✓	
1.10	Crane is painted safety yellow-and-black stripes on offshore facilities	SAES-B067 Sec:4.4			✓	
1.11	Rated capacity of crane is marked (Arabic & English)	SAES-B067 Sec:4.4	✓			
1.12	Fire extinguisher is in place with minimum rating 10 BC	ASME B30.5 Sec: 5-3.4.10	✓			
1.13	Markings and direction of all control levers are clearly displayed	ASME B30.5 Sec:5-1.6.1-1 Sec:5-1.6.1-2	✓			
1.14	Crane backward stability is in accordance with manufacturers standard (minimum radius and no load condition)	ASME B30.5 Sec:5-1.2.1	✓			
2	INSPECTION POINTS (MOBILE & CRAWLER CRANES)					
2.1	Load- holding check valve for boom is operational	ASME B30.5 Sec:5-1.3.1 (d)	✓			
2.2	Two (2) full wraps of rope remain on the drum when hook is in the extreme low position	ASME B30.5 Sec:5-1.3.1	✓			
2.3	Swing control is smoothly operating on acceleration and deceleration	ASME B30.5 Sec:5-1.4.1	✓			

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE JAFURAH GCP-6 (HZEM-6)	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-STC-050-028	EQUIPMENT DESCRIPTION/TYPE TMS-H	SERIAL NO. TC2050CE1418	REPORT No.: SGS-2026-SA-473
CAPACITY (SWL) 50 t	MANUFACTURER SANY	FACILITY / LOCATION HZEM-6 PARKING AREA	
REQUESTED INSPECTION DATE 12-Jul-2026	RFI No SGS-RFI-09161	TASK COMPLETED DATE 15-Jul-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
2.4	Swing braking operates, as well as positive locking devices (manual and auto)	ASME B30.5 Sec: 5-1.4.2	✓			
2.5	Travel controls are properly operating/functioning	ASME B30.5 Sec: 5-1.1.3	✓			
2.6	Auxiliary travel controls function correctly for multiple control- station cranes	ASME B30.5 Sec: 5-1.5.1	✓			
2.7	Travel brakes and locks for crawler cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3			✓	
2.8	Travel brakes and locks for wheel-mounted cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	✓			
2.9	Power plant controls of superstructure -mounted power plant working properly	ASME B30.5 Sec: 5-1.6.3	✓			
2.10	Rotation-resistant and fiber-core ropes are not used for boom hoist reeving	ASME B30.5 Sec: 5-1.7.2			✓	
2.11	Sheave grooves have surface smoothness without any defects	ASME B30.5 Sec: 5-1.7.4	✓			
2.12	Sheave guards are in place on the lower block	ASME B30.5 Sec: 5-1.7.4	✓			
2.13	All sheaves can be lubricated (except permanently lubricated types)	ASME B30.5 Sec: 5-1.7.4 (d)	✓			
2.14	All cab glazing are safety glazing material	ASME B30.5 Sec: 5-1.8.1	✓			
2.15	Verify cab doors functionality and condition	ASME B30.5 Sec: 5-1.8.1	✓			
2.16	Seat belt is fitted and in good condition	ASME B30.5 Sec: 5-1.8.1 (f)	✓			
2.17	Walking platforms and areas of structure are skid-resistance	ASME B30.5 Sec: 5-1.8.2	✓			
2.18	Guard rails are fitted	ASME B30.5 Sec: 5-1.9.7			✓	
2.19	Fixed or telescoping bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1			✓	
2.20	Shock absorbing bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1			✓	
2.21	Hydraulic boom elevating cylinder, used as boom stop, is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	✓			
2.22	Boom angle indicator is fitted, operable, and can be read from the operator station	ASME B30.5 Sec: 5-1.9.1	✓			
2.23	Boom shut-off or hydraulic reliefs provided for high angle boom condition	ASME B30.5 Sec: 5-1.9.1 (d)	✓			

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE JAFURAH GCP-6 (HZEM-6)	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-STC-050-028	EQUIPMENT DESCRIPTION/TYPE TMS-H	SERIAL NO. TC2050CE1418	REPORT No.: SGS-2026-SA-473
CAPACITY (SWL) 50 t	MANUFACTURER SANY	FACILITY / LOCATION HZEM-6 PARKING AREA	
REQUESTED INSPECTION DATE 12-Jul-2026	RFI No SGS-RFI-09161	TASK COMPLETED DATE 15-Jul-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
2.24	Boom length indicator is fitted for telescoping booms ,and is working	ASME B30.5 Sec: 5-1.9.1	✓			
2.25	Anti-two-blocking devices are fitted and working (main and auxiliary)	ASME B30.5 Sec: 5-3.2.3	✓			
2.26	Operation and accuracy of the fitted Load Indicator, RCI or RCL (compare with load chart)	ASME B30.5 Sec: 5-1.9.10.2	✓			
2.27	LMI is fitted, operational and accurate for bool length, rated load, angle, radius, etc. (for 3 ton cranes or more)	ASME B30.5 Sec: 5-1.9.10.2	✓			
2.28	Outriggers and jacks are not leaking oil	ASME B30.5 Sec:5-2.1.3	✓			
2.29	Jack is in good operating condition at each outrigger	ASME B30.5 sec: ASME B30.5 Sec:5-2.1.3 (d)	✓			
2.30	Each outrigger jack locking device is functional (if fitted)	ASME B30.5 Sec: 5-1.9.3 (c)			✓	
2.31	No leakage from each jack seal when the crane is jacked up	ASME B30.5 Sec: 5-1.9.3 (c)	✓			
2.32	Outrigger jack bolts are fully secure	ASME B30.5 Sec: 5-1.9.3 (b)	✓			
2.33	All road wheel nuts are fully secure	ASME B30.5 Sec: 5-2.1.3(b)	✓			
2.34	All tires are serviceable and without damage or excess wear	ASME B30.5 Sec: 5-2.1.3(k)	✓			
2.35	Fuel tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	✓			
2.36	Hydraulic oil tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	✓			
2.37	Underside of chassis shows no obvious faults	ASME B30.5 Sec: 5-2.1.3	✓			
2.38	Outrigger boxes are not cracked	ASME B30.5 Sec: 5-2.1.3	✓			
2.39	Front and rear steering cylinder anchor points and pins are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.40	Track rod end joints are not worn and are secure	ASME B30.5 Sec: 5-2.1.3			✓	
2.41	Axle bolts and nuts are fully secure	ASME B30.5 Sec: 5-2.1.	✓			
2.42	Wheel hub oil seals are not leaking	ASME B30.5 Sec: 5-2.1.3	✓			
2.43	Brake linings are not oil contaminated	ASME B30.5 Sec: 5-2.1.3	✓			

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE JAFURAH GCP-6 (HZEM-6)	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-STC-050-028	EQUIPMENT DESCRIPTION/TYPE TMS-H	SERIAL NO. TC2050CE1418	REPORT No.: SGS-2026-SA-473
CAPACITY (SWL) 50 t	MANUFACTURER SANY	FACILITY / LOCATION HZEM-6 PARKING AREA	
REQUESTED INSPECTION DATE 12-Jul-2026	RFI No SGS-RFI-09161	TASK COMPLETED DATE 15-Jul-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
2.44	Brake hoses have not deteriorated, e.g. cracks, splits, leaks, etc.	ASME B30.5 Sec: 5-2.1.3	✓			
2.45	All chassis cross members are not cracked or corroded	ASME B30.5 Sec: 5-2.1.3	✓			
2.46	Transmission mounting bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.47	All drive shaft bolts and universal joints are not worn	ASME B30.5 Sec: 5-2.1.3	✓			
2.48	Ring gear bolts are fully secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.49	All hydraulic hoses under chassis have not deteriorated (cracks , splits , leaks)	ASME B30.5 Sec: 5-2.1.2	✓			
2.50	Engine shows no major oil leakage	ASME B30.5 Sec: 5-2.1.3	✓			
2.51	Radiator does not leak water	ASME B30.5 Sec: 5-2.1.3	✓			
2.52	Rope is free of kinking, crushing, birdcaging, or any other damage resulting in distortion of the rope structure • No more 1 broken wire protruding from the core • There are no reductions from nominal rope diameter of more than 5% For running ropes: • No more than 6 randomly broken wires in 1 lay or 3 broken wires in 1 strand of 1 lay For rotation resistance ropes • No more than 2 randomly distributed broken wires in six rope diameters or 4 randomly distributed broken wires in 30 rope diameters • Evidence of any heat damage from any cause.	ASME B30.5 Sec: 5-2.4.3	✓			
2.53	Main hoist drum mounting bolts are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.54	Rear telescope side and top wear pads are serviceable	ASME B30.5 Sec: 5-2.1.3	✓			
2.55	Bottom and side wear pads of telescope sections are serviceable	ASME B30.5 Sec: 5-2.1.3	✓			
2.56	Boom heel pin bushes are not worn (rock boom up and down to check this)	ASME B30.5 Sec: 5-2.1.3	✓			
2.57	Center swivel coupling pipes and hoses do not leak	ASME B30.5 Sec: 5-2.1.3	✓			
2.58	Center swivel coupling bolts are all secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.59	Boom lift cylinder anchor bolts and bushings are	ASME B30.5 Sec:	✓			

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE JAFURAH GCP-6 (HZEM-6)	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-STC-050-028	EQUIPMENT DESCRIPTION/TYPE TMS-H	SERIAL NO. TC2050CE1418	REPORT No.: SGS-2026-SA-473
CAPACITY (SWL) 50 t	MANUFACTURER SANY	FACILITY / LOCATION HZEM-6 PARKING AREA	
REQUESTED INSPECTION DATE 12-Jul-2026	RFI No SGS-RFI-09161	TASK COMPLETED DATE 15-Jul-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
	secure	5-2.1.3				
2.60	Swing gearbox bottom oil seal and drive gear are in a serviceable condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3	✓			
2.61	Wire rope clips shall be drop-forged steel of the single saddle U bolt or doubled saddle type clip for end termination.	ASME B30.5 Sec: 5-1.7.3(b)	✓			
2.62	Emergency switch / Power take off switch need to be verified	ASME B30.5 Sec: 5-1.6.1(e)	✓			
3	CRANE CAB					
3.1	Horn and wind speed anemometer are working	ASME B30.5 Sec: 5-3.2.1.6	✓			
3.2	Crane level indicator is fitted and working	ASME B30.5 Sec: 5-1.9.10.6	✓			
3.3	Engine gauges and associated indicators are working	ASME B30.5 Sec: 5-2.1.3 (g)	✓			
3.4	The warning sign stating power line required clearances is visible to the operator	ASME B30.5 Sec: 5-1.9.12(g)	✓			
3.5	Load block sheaves turn freely and are undamaged	ASME B30.5 Sec: 5-2.1.3 (c)	✓			
3.6	Dead end rope anchor is correctly made with a suitable wedge socket and loop-back termination	ASME B30.5 Sec: 5-1.7.3 (d)	✓			
3.7	Hook assemblies are equipped with safety latches	ASME B30.5 Sec: 5-1.7.6	✓			
3.8	Hook assembly labeling and manufacturer data is clearly marked	ASME B30.10 Sec : 10-1.8	✓			
3.9	Hook's weight is clearly marked/printed on the hook	ASME B30.10 Sec: 10-1.10.5 (b)	✓			
3.10	Safe working load of hook is clearly marked on the item	ASME B30.10 Sec : 10-1.8	✓			
3.11	Hook does not show defects such as nicks, cracks and gouges	ASME B30.10 Sec : 10-1.10.5 (d)	✓			
3.12	Hook is not bent or twisted	ASME B30.10 Sec : 10-1.10.5 (f)	✓			
3.13	Hook is not distorted in the throat opening • Max. allowable throat opening is 5% not to exceed 1 1/4 in. (6 mm) compared to new hook, or as per manufacturer recommendations	ASME B30.10 Sec : 10-1.10.5 (g)	✓			
3.14	Maximum wear in the hook bowl is not exceeding 10% (compared to new hook) or as per manufacturer recommendations	ASME B30.10 Sec : 10-1.10.5 (e)	✓			

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE JAFURAH GCP-6 (HZEM-6)	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-STC-050-028	EQUIPMENT DESCRIPTION/TYPE TMS-H	SERIAL NO. TC2050CE1418	REPORT No.: SGS-2026-SA-473
CAPACITY (SWL) 50 t	MANUFACTURER SANY	FACILITY / LOCATION HZEM-6 PARKING AREA	
REQUESTED INSPECTION DATE 12-Jul-2026	RFI No SGS-RFI-09161	TASK COMPLETED DATE 15-Jul-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
3.15	Hook is not cracked, gouged or shows nicks	ASME B30.10 Sec : 10-1.10.5 (d)	✓			
3.16	Hook can lock (if it is a self-locking hook)	ASME B30.10 Sec : 10-1.10.5 (h)			✓	
3.17	Inoperative latch (if provided) – any damaged latch or malfunctioning latch that does not close the hook's throat	ASME B30.10 Sec : 10-1.10.5 (i)			✓	
3.18	Rope guards and locked in position with pins (hook block)	ASME B30.5 Sec:5-1.7.4	✓			
3.19	Dead end rope anchor is fitted with a lock pin (hook block)	ASME B30.5 Figure 5-1.7.3-1	✓			
3.20	Dead end rope anchor is correctly made with a suitable wedge socket and loop- back termination	ASME B30.5 Figure 5-1.7.3-1	✓			
3.21	Reverse travel alarm is operational.	General	✓			
3.22	Turning signals and indicators are working correctly	General	✓			
3.23	Road lighting, including spotlights, are in good condition and operable	General	✓			
3.24	Dry friction brakes and clutches shall be protected against rain and other liquids such as oil and lubricants	ASME B30.5 Sec 5-1.9.8	✓			
4	CRAWLER CRANE					
4.1	Track pads are undamaged and drive chain are tensioned	ASME B30.5 Sec: 5-2.1.3 (h)			✓	
4.2	Drive sockets and drive chain tumblers are serviceable	ASME B30.5 Sec: 5-2.1.3 (h)			✓	
4.3	Top and bottom swing rollers and tracks are in good overall condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3 (a)			✓	
4.4	Track idlers are serviceable	ASME B30.5 Sec: 5-2.1.3 (a)			✓	
4.5	Back boom stops are functioning	ASME B30.5 Sec: 5-1.9.1 (a)			✓	
4.6	Back A-Frame is in good condition	ASME B30.5 Sec: 5-2.1.3 (a)			✓	
4.7	Boom cut-out (at maximum angle) is operable	ASME B30.5 Sec: 5-1.9.1 (a-2)			✓	
4.8	Power low lowering is operational	ASME B30.5 Sec: 5-1.3.2(a-1)			✓	
4.9	Boom hoist safety auxiliary ratchet / pawl lock is engaging	ASME B30.5 Sec: 5-1.3.1(c)			✓	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES		SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE JAFURAH GCP-6 (HZEM-6)		WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-STC-050-028	EQUIPMENT DESCRIPTION/TYPE TMS-H	SERIAL NO. TC2050CE1418	REPORT No.: SGS-2026-SA-473
CAPACITY (SWL) 50 t	MANUFACTURER SANY	FACILITY / LOCATION HZEM-6 PARKING AREA	
REQUESTED INSPECTION DATE 12-Jul-2026	RFI No SGS-RFI-09161	TASK COMPLETED DATE 15-Jul-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
4.10	Boom chords and lacings are undamaged (bent)	ASME B30.5 Sec: 5-2.1.3			✓	
4.11	Sheave grooves are free from surface defects that could cause rope damage.	ASME B30.5 Sec: 5-1.7.4 (a)			✓	
4.12	Pendant ropers are showing no broken wires (see no. 48)	ASME B30.5 Sec: 5-2.4.2			✓	
4.13	Operation of steering brakes is satisfactory	ASME B30.5 Sec: 5-1.5.3			✓	
4.14	Main machinery guarding is in place	ASME B30.5 Sec: 5-1.6.4			✓	
4.15	Main clutch is fully operational	ASME B30.5 Sec: 5-1.6.4			✓	
4.16	Main boom and hoist drum brakes are fully functional	ASME B30.5 Sec: 5-1.3.2(a-1)			✓	

REFERENCE DOCUMENTS:

- 1.ASME B30.5 - 2021 Issue: Mobile & Locomotive Cranes
- 2.ASME B30.10 - 2019 Issue: Hooks
- 3.SAES-B067 - 2020 Issue: Safety Identification and Safety Colors
- 4.SA GI 7.025-2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification
- 5.SA GI 7.030 - 2023 Issue: Inspection and Testing Requirements for Elevating/Lifting Equipment

Load Tested By (If Applicable):

Name	Signature	Date

✓ Inspected Witnessed by 3rd Party Certified Inspector:

Name	Signature	Certificate No. & Company:
Mikecle Araneta		80019274 & SGS Inspection Services Saudi Arabia Co Ltd

User Representative:

Name	Signature	Date
------	-----------	------

Jay Mark Dupio

15-Jul-2026

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES		SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE JAFURAH GCP-6 (HZEM-6)		WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-STC-050-028	EQUIPMENT DESCRIPTION/TYPE TMS-H	SERIAL NO. TC2050CE1418	REPORT No.: SGS-2026-SA-473
CAPACITY (SWL) 50 t	MANUFACTURER SANY	FACILITY / LOCATION HZEM-6 PARKING AREA	
REQUESTED INSPECTION DATE 12-Jul-2026	RFI No SGS-RFI-09161	TASK COMPLETED DATE 15-Jul-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
						