

## CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

|                                           |                            |                                        |
|-------------------------------------------|----------------------------|----------------------------------------|
| Date of thorough examination : 30-12-2025 | Date of issue : 30-12-2025 | Report No. : <b>ESICO-LFT-R25-7079</b> |
|-------------------------------------------|----------------------------|----------------------------------------|

|                                  |             |         |                                                   |
|----------------------------------|-------------|---------|---------------------------------------------------|
| Name & Address of employer       | Location    | Sticker | Standards                                         |
| SUDHIR EQUIPMENT RENTALS COMAPNY | RIYADH YARD | 8731    | ANSI/ITSDF ASME B56.1a- 2020 SASO GSO<br>ISO 5057 |

| Equipment Identification No | Equipment Description                                                                                                  | Safe Working Load(s) | Date of Manufacture | Manufacturer Name |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------|-------------------|
| S5FLT-015 OR<br>010502F0886 | FORKLIFT<br>MODEL: CPCD50<br>POWER:83KW<br>RATED LIFTING CAPACITY:5000KG<br>LOAD CENTER:600MM<br>SERVICE WEIGHT:9070KG | 5T                   | 2020-01             | HELI              |

|                                                                                         |                                              |                                                        |                                              |
|-----------------------------------------------------------------------------------------|----------------------------------------------|--------------------------------------------------------|----------------------------------------------|
| Is this the first examination after installaton or assembly at a new site or location?  | Yes - No <input checked="" type="checkbox"/> | Was the examination carried out within an interval of? | - 12 Months                                  |
| If the answer to the above question is YES, has the equipment been installed correctly? | Yes - No -                                   | In accordance with an examination scheme?              | Yes <input checked="" type="checkbox"/> No - |
|                                                                                         |                                              | After the occurence of exceptional circumstances?      | Yes - No <input checked="" type="checkbox"/> |

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE

Is the above an existing or imminent danger to persons, Note: This is a reportable defect? No

Is the above a defect which is not yet could become a danger to persons (if YES state the date by when) Yes by : N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE

Particulars of any tests carried out as part of the examination (if none state NONE) : VISUAL INSPECTION AND FUNCTIONAL TEST.

Observation/additional comments relative to this thorough examination : AT THE TIME OF I SPECTION THE FORKLIFT NEED TO PLACE THE REVERSE ALRAM, HORN,BECON LIGHT AND ONE HYDRULIC HOSE PIPE CHANGE.



For confirmation scan QR code  
search with report number : **ESICO-LFT-R25-7079**

☒ Safe to operate

Next Inspection : 29-12-2026

Inspected by : Jay Prakash

