



LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	DAMMAN	Sep 09, 2023		8:30	No. Initial Issued By 1
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDHAJR	SDIMESL-813	Dammam		☒ Pass ☐ Fail	BV-21-9528
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
DINGLI	Jep T1412AC	700kg	MEWP	C01391	MARCH 08, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
x	Initial Inspection and function test for SELF PROTECTING (circuit) work platform As per AS 5063-2008 92.6 "PASS"	

RECEIVER NAME: NSH SIGNATURE: [Signature] INSPECTOR NAME: Mohr
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800/9/06