



LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	DMMYOR	Sep 09, 2023		12:00	No. Initial Issued By
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDAIR	SDMESL-817	DMMYOR		☒ Pass ☐ Fail	BV-21-9531
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
DINGLI	JCPT1412AC	700LBS	MFmp	C01392	MARCH 08, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
4	Initial Inspector and Function Test for SELF PROPELLED Elevating work Platform. As per AS 3, para 6.5.3.1, AS 5192.6	
	Post	

RECEIVER NAME: SIGNATURE: INSPECTOR NAME:
BADGE#: TELEPHONE NO.: TELEPHONE NO.: