



LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. <u>INT-14</u> Issued By
	<u>Dammam</u>	<u>SEP 24, 2023</u>		<u>14:00</u>	
Department / contractor <u>SUDAIR</u>	Equipment Number <u>SOMESL-823</u>	Equipment Location <u>DMM YARD</u>		Equipment Result ☒ Pass ☐ Fail	New Sticker No. <u>BV-21-9565</u>
Manufacturer <u>DINGLI</u>	Model <u>Jcpt 1412AC</u>	Capacity <u>7000BS</u>	Type <u>MEWP</u>	Equipment Serial Number <u>A00068</u>	Sticker Expiration Date <u>MARCH 23, 2024</u>

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
X	Initial Inspection and Function Test Per SELF PROPOSED Elevating work Platform As Per AS 5081:2006 (S 7.0.3) AND 192.6 "Pass"	

RECEIVER NAME: ARF SIGNATURE: AR INSPECTOR NAME: M. O. M. S.
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800/9106