




BV No. 237184

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. <u>Initial</u> Issued By
	<u>Danmon</u>	<u>Oct 05, 2023</u>		<u>10530</u>	
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
<u>SUDHAR</u>	<u>S014ESL-830</u>	<u>DMM/YORO</u>		☒ Pass ☐ Fail	<u>BV-21-9593</u>
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
<u>DIMBELI</u>	<u>JcpT1412AC</u>	<u>7000BS</u>	<u>MFUP</u>	<u>A00071</u>	<u>APR 2024</u>

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
2	Initial inspection and further test for SELF PROTECTED elevating work platform AS PEROS S. 0.0006 657.03, and 92.6 "Pass" 	
RECEIVER NAME: <u>ADJ</u> SIGNATURE: <u>[Signature]</u> INSPECTOR NAME: <u>M. M. M.</u>		
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: <u>800 19106</u>		