



**BV No.** 237185

|                                                |                  |                    |      |                                                                        |                         |
|------------------------------------------------|------------------|--------------------|------|------------------------------------------------------------------------|-------------------------|
| <b>LIFTING EQUIPMENT<br/>INSPECTION REPORT</b> | Area             | Inspection Date    |      | Inspection Time                                                        | Previous Sticker        |
|                                                | Dorman           | Oct 05, 2023       |      | 1300                                                                   | No. JWHM Issued By      |
| Department / contractor                        | Equipment Number | Equipment Location |      | Equipment Result                                                       | New Sticker No.         |
| Suotice                                        | SD14ESL-831      | DMMYARD            |      | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail | BV-21-9594              |
| Manufacturer                                   | Model            | Capacity           | Type | Equipment Serial Number                                                | Sticker Expiration Date |
| DynGLT                                         | JCPT1412AC       | 7000LBS            | MFHP | A00074                                                                 | APR 04, 2024            |

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]