



BV No. 237187

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. <u>IWHM</u> Issued By
	<u>Dammam</u>	<u>OCT 05, 2023</u>		<u>15:30</u>	
Department / contractor <u>Suobate</u>	Equipment Number <u>SD16ESL-846</u>	Equipment Location <u>Dammam</u>		Equipment Result ☒ Pass ☐ Fail	New Sticker No. <u>BV-21-9596</u>
Manufacturer <u>Dingli</u>	Model <u>JCPT1614AC</u>	Capacity <u>7000LBS</u>	Type <u>MCWP</u>	Equipment Serial Number <u>C01386</u>	Sticker Expiration Date <u>APRIL 04, 2024</u>

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Initial inspection and function test for SELF PROTECTED (elevators) were not found As per AS S-000000 617.030, AN 87926 Ross	

RECEIVER NAME: ARJ SIGNATURE: [Signature] INSPECTOR NAME: M. O. M. B.

BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 196 6