



|                                                |                    |                     |             |                                                                        |                                                |
|------------------------------------------------|--------------------|---------------------|-------------|------------------------------------------------------------------------|------------------------------------------------|
| <b>LIFTING EQUIPMENT<br/>INSPECTION REPORT</b> | Area               | Inspection Date     |             | Inspection Time                                                        | Previous Sticker<br>No. <u>3m17a</u> Issued By |
|                                                | <u>Dammam</u>      | <u>JAN 04, 2024</u> |             | <u>9:00</u>                                                            |                                                |
| Department / contractor                        | Equipment Number   | Equipment Location  |             | Equipment Result                                                       | New Sticker No.                                |
| <u>SUDAIR</u>                                  | <u>S225J - 912</u> | <u>DMMY ORN</u>     |             | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail | <u>BV-23-0808</u>                              |
| Manufacturer                                   | Model              | Capacity            | Type        | Equipment Serial Number                                                | Sticker Expiration Date                        |
| <u>JLG</u>                                     | <u>G605J</u>       | <u>500 LBS</u>      | <u>MEWP</u> | <u>B300014422</u>                                                      | <u>JULY 03, 2024</u>                           |

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

| No. | DEFICIENCIES                                                                                                            | CORRECTIVE ACTION TAKEN |
|-----|-------------------------------------------------------------------------------------------------------------------------|-------------------------|
| x   | Initial inspection AND function test for<br>BOOM SUPPORTED Elevating work platform<br>AS PER S.O.R.M.C G-7.03. ANS 92.5 |                         |
|     | PASS                                                                                                                    |                         |
|     |                                                                                                                         |                         |
|     |                                                                                                                         |                         |
|     |                                                                                                                         |                         |
|     |                                                                                                                         |                         |
|     |                                                                                                                         |                         |
|     |                                                                                                                         |                         |
|     |                                                                                                                         |                         |
|     |                                                                                                                         |                         |
|     |                                                                                                                         |                         |
|     |                                                                                                                         |                         |

RECEIVER NAME: ALOJ SIGNATURE: [Signature] INSPECTOR NAME: M. Mozy

BADGE#: TELEPHONE NO.: TELEPHONE NO.: 800 196 6