



Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

RECEIVER NAME: ARot SIGNATURE: [Signature] INSPECTOR NAME: Hickory
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 804968