



Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Initial inspection and Function test for SELF SELF PROPELLED Elevating work platform. AS Per AS S.A.R.M.C. GJ7030. WMS97.6. Pass	

RECEIVER NAME: ARIR SIGNATURE: [Signature] INSPECTOR NAME: Flavio
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 970 6