



Previous Sticker
No. 2474 Issued By

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. _____ Issued By _____
	DAMMAN	JAN 22, 2024		13:00	
Department / contractor	Equipment Number	Equipment Location		Equipment Result ☒ Pass ☐ Fail	New Sticker No.
SUDAIR	S28AD-966	DAMMAN			BV-23-0854
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
DINGLI	BA28RT	250KG	MEWP	R00103	JULY 21, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
	* Initial Inspection was performed test for	
	Beam supported elevating with put beam	
	As per as shown to G57.03-ANSI 92.5	
	Pass	

RECEIVER NAME: DPH SIGNATURE: [Signature] INSPECTOR NAME: M. H. H.
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 676 08