



LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. <u>INT-114</u> Issued By
	Department / contractor <u>SUBAIR</u>	Equipment Number <u>5435JP-976</u>	Equipment Location <u>Dammam</u>	Equipment Result ☒ Pass ☐ Fail	New Sticker No. <u>BV-23-0896</u>
Manufacturer <u>JLG</u>	Model <u>1350SJP</u>	Capacity <u>500 LBS</u>	Type <u>MEWP</u>	Equipment Serial Number <u>0300208456</u>	Sticker Expiration Date <u>Aug 11, 2024</u>

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	INITIAL INSPECTION AND FUNCTION TEST FOR	
	BEAM SUPPORTED ERECTING WORK PLATFORM.	
	AS PER SUBMITTAL 657.02c AND 92.5	
	ALL	

RECEIVER NAME: APG SIGNATURE: [Signature] INSPECTOR NAME: Murphy
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800-9166