



## SGS INSPECTION SERVICES SAUDI ARABIA CO LTD

شركة اس جي اس لخدمات الفحص العربيّة السعوديّة المحدوده

P.O Box 0725, Jubail, Saudi Arabia - 31951  
Tel : + 966133400044 / Fax : + 966133420212  
Email : info@sgs.com

### CUSTOMER SATISFACTION SURVEY

|                                              |                                     |                                           |
|----------------------------------------------|-------------------------------------|-------------------------------------------|
| <b>Blue Sticker Inspection</b>               | <b>RFI No</b><br>SGS-RFI-08793      | <b>Inspection date</b><br>25-Feb-2026     |
| <b>Client</b><br>Sudhir Equipment Rental Co. | <b>Report No</b><br>SGS-2026-SA-156 | <b>Inspector Name</b><br>Shehzad Mubashar |
| <b>WO No</b>                                 | <b>CRM No</b><br>-                  | <b>RPO No</b><br>NA                       |

| S.No | Questions                                                                                         | Answer | Remarks |
|------|---------------------------------------------------------------------------------------------------|--------|---------|
| 1    | Did the Service provider Co. provide the right inspector with a valid qualification card?         | Yes    |         |
| 2    | Did the service provider Co. respond for inspection within the expected time frame?               | Yes    |         |
| 3    | Was the inspector wearing the required personal protective equipment (PPE) during the inspection? | Yes    |         |
| 4    | Did the inspection conducted safely and in accordance with Aramco's standards?                    | Yes    |         |

For any enquiry or concern, please contact: Inspection Dept. - ISSD Crane Inspection Unit (CIU)

[InspectionDeptOIDCraneInspectionUnitCIU@Exchange.Aramco.com.sa](mailto:InspectionDeptOIDCraneInspectionUnitCIU@Exchange.Aramco.com.sa)

Client Rep Signature

Khurshed  
Alom

|                                             |                  |                                                                       |                             |                                                                                     |
|---------------------------------------------|------------------|-----------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|
| SAUDI ARAMCO INSPECTION CHECKLIST           | SAIC NUMBER      | ISSUE DATE                                                            | DISCIPLINE                  |  |
| BOOM SUPPORTED ELEVATING WORK PLATFORM      | SAIC-U-7013      | 12-Jan-23                                                             | ELEVATING/LIFTING EQUIPMENT |                                                                                     |
| PROJECT TITLE<br><br>TAMIMI Workshop, Damam | WBS/BI/JO NUMBER | INSPECTION COMPANY<br><br>SGS Inspection Services Saudi Arabia Co Ltd |                             |                                                                                     |

|                                                 |                                                     |                                                       |                                                       |
|-------------------------------------------------|-----------------------------------------------------|-------------------------------------------------------|-------------------------------------------------------|
| EQUIPMENT ID NUMBER<br><b>S16SD-1559</b>        | EQUIPMENT DESCRIPTION/TYPE<br><b>MANLIFT (MEWP)</b> | SERIAL NO.<br><b>BTRC024F00186</b>                    | REPORT No.:<br><b>SGS-2026-SA-156</b>                 |
| CAPACITY (SWL)<br><b>320 Kg</b>                 | MANUFACTURER<br><b>DINGLI</b>                       | FACILITY / LOCATION<br><b>TAMIMI Workshop, dammam</b> |                                                       |
| REQUESTED INSPECTION DATE<br><b>23-Feb-2026</b> | RFI No<br><b>SGS-RFI-08793</b>                      | TASK COMPLETED DATE<br><b>25-Feb-2026</b>             | EQUIPMENT OWNER<br><b>Sudhir Equipment Rental Co.</b> |

| ITEM     | ACCEPTANCE CRITERIA                                                                                                          | REFERENCE                                 | PASS | FAIL | N/A | RE-INSP DATE |
|----------|------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------|------|------|-----|--------------|
| <b>1</b> | <b>GENERAL REQUIREMENTS:</b>                                                                                                 |                                           |      |      |     |              |
| 1.1      | Equipment documentation is available                                                                                         | ANSI/SAIA A92.5, Sec: 4.16.1.1 G.I. 7.030 | ✓    |      |     |              |
| 1.2      | Previous inspection reports are checked                                                                                      | ANSI/SAIA A92.5, Sec: 5.11.1.3 G.I. 7.030 | ✓    |      |     |              |
| 1.3      | Daily pre-operational inspection checklists are checked (if applicable)                                                      | GI 7.030 Para: 5.1.2                      | ✓    |      |     |              |
| 1.4      | Preventive Maintenance is established and updated records are maintained                                                     | ANSI/SAIA A92.5, Sec: 6.4.1               | ✓    |      |     |              |
| 1.5      | Equipment is operated by a qualified operator                                                                                | ANSI/SAIA A92.5 Sec: 4.13.13              | ✓    |      |     |              |
| 1.6      | Warning notice, cautions or restrictions for safe operation and maintenance are clearly displayed and legible                | ANSI/SAIA A92.5 Sec: 4.13.1               | ✓    |      |     |              |
| 1.7      | A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice | G.I. 7.030 Para: 5.6.2                    | ✓    |      |     |              |
| 1.8      | Manufacturer name, address, serial number and model are clearly marked or tagged                                             | ANSI/SAIA A92.5 Sec: 4.13.2               | ✓    |      |     |              |
| 1.9      | Safe working load and number of persons are clearly marked on the work platform                                              | ANSI/SAIA A92.5, Sec: 4.13.3              | ✓    |      |     |              |
| 1.10     | Maximum platform height and reach are clearly marked                                                                         | ANSI/SAIA A92.5 Sec: 4.13.4 & 5           | ✓    |      |     |              |
| 1.11     | Maximum travel height and travel directions are clearly marked                                                               | ANSI/SAIA A92.5 Sec: 4.13.9               | ✓    |      |     |              |
| 1.12     | Power rating are provided and marked (for AC and/or DC)                                                                      | ANSI/SAIA A92.5 Sec: 4.13.6               | ✓    |      |     |              |
| 1.13     | Platform and guardrails electrical insulation data are provided                                                              | ANSI/SAIA A92.5 Sec: 4.13.10              |      |      | ✓   |              |
| <b>2</b> | <b>INSPECTION POINTS:</b>                                                                                                    |                                           |      |      |     |              |
| 2.1      | Platform surfaces are at least 18" (width & length) and are slip-resistant                                                   | ANSI/SAIA A92.5 4.12.1                    | ✓    |      |     |              |
| 2.2      | Platform guardrails are provided and secure                                                                                  | ANSI/SAIA A92.5 4.12.2                    | ✓    |      |     |              |
| 2.3      | Platform guardrails are 42" height (+/- 3")                                                                                  | ANSI/SAIA A92.5 Sec: 4.12.2.1             | ✓    |      |     |              |
| 2.4      | Platform toeboard is fitted and at least 4" high                                                                             | ANSI/SAIA A92.5 Sec: 4.12.3               | ✓    |      |     |              |
| 2.5      | Moving parts are guarded                                                                                                     | ANSI/SAIA A92.5 Sec: 4.11                 | ✓    |      |     |              |
| 2.6      | Personnel on the platform is protected against the                                                                           | ANSI/SAIA A92.5 Sec:                      | ✓    |      |     |              |

|                                             |                  |                                                                       |                             |                                                                                     |
|---------------------------------------------|------------------|-----------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|
| SAUDI ARAMCO INSPECTION CHECKLIST           | SAIC NUMBER      | ISSUE DATE                                                            | DISCIPLINE                  |  |
| BOOM SUPPORTED ELEVATING WORK PLATFORM      | SAIC-U-7013      | 12-Jan-23                                                             | ELEVATING/LIFTING EQUIPMENT |                                                                                     |
| PROJECT TITLE<br><br>TAMIMI Workshop, Damam | WBS/BI/JO NUMBER | INSPECTION COMPANY<br><br>SGS Inspection Services Saudi Arabia Co Ltd |                             |                                                                                     |

|                                                 |                                                     |                                                       |                                                       |
|-------------------------------------------------|-----------------------------------------------------|-------------------------------------------------------|-------------------------------------------------------|
| EQUIPMENT ID NUMBER<br><b>S16SD-1559</b>        | EQUIPMENT DESCRIPTION/TYPE<br><b>MANLIFT (MEWP)</b> | SERIAL NO.<br><b>BTRC024F00186</b>                    | REPORT No.:<br><b>SGS-2026-SA-156</b>                 |
| CAPACITY (SWL)<br><b>320 Kg</b>                 | MANUFACTURER<br><b>DINGLI</b>                       | FACILITY / LOCATION<br><b>TAMIMI Workshop, dammam</b> |                                                       |
| REQUESTED INSPECTION DATE<br><b>23-Feb-2026</b> | RFI No<br><b>SGS-RFI-08793</b>                      | TASK COMPLETED DATE<br><b>25-Feb-2026</b>             | EQUIPMENT OWNER<br><b>Sudhir Equipment Rental Co.</b> |

| ITEM | ACCEPTANCE CRITERIA                                                                         | REFERENCE                     | PASS | FAIL | N/A | RE-INSP DATE |
|------|---------------------------------------------------------------------------------------------|-------------------------------|------|------|-----|--------------|
|      | hazards of moving parts of the aerial platforms.                                            | 7.10                          |      |      |     |              |
| 2.7  | Access to the platform is provided                                                          | ANSI/SAIA A92.5 Sec: 4.12.4   | ✓    |      |     |              |
| 2.8  | Access gates or openings shall be properly closed per the manufacturer's instructions       | ANSI/SAIA A92.5 Sec: 4.12.4   | ✓    |      |     |              |
| 2.9  | Electrical cables, wiring and components are undamaged                                      | ANSI/SAIA A92.5 Sec:8.3       | ✓    |      |     |              |
| 2.10 | Safety harness anchorage is fitted in the platform                                          | ANSI/SAIA A92.5 Sec: 4.12.5.1 | ✓    |      |     |              |
| 2.11 | Battery is secure, guarded and ventilated                                                   | ANSI/SAIA A92.5 Sec: 4.15.2   | ✓    |      |     |              |
| 2.12 | Outrigger position microswitches and interlocks are fully functional at their control panel | ANSI/SAIA A92.5 Sec: 4.7      |      |      | ✓   |              |
| 2.13 | Air, Hydraulic and fuel systems are not leaking                                             | ANSI/SAIA A92.5 Sec: 6.6.5    | ✓    |      |     |              |
| 2.14 | Emergency stop button is available at ground control station                                | ANSI/SAIA A92.5 Sec: 4.6.3    | ✓    |      |     |              |
| 2.15 | There are no loose nuts, bolts, missing, worn or damaged parts around the structure         | ANSI/SAIA A92.5 Sec: 6.6.2    | ✓    |      |     |              |
| 2.16 | The equipment is free of defective and/or corroded members/joints                           | ANSI/SAIA A92.5 Sec:6.4.3     | ✓    |      |     |              |
| 2.17 | Working environment is hazard free and machine can be safely operated                       | ANSI/SAIA A92.5 Sec:7.9       | ✓    |      |     |              |
| 2.18 | An hour meter is fitted                                                                     | ANSI/SAIA A92.5 Sec:4.15.3    | ✓    |      |     |              |
| 2.19 | A fire extinguisher is fitted (type depends on operating location)                          | ANSI/SAIA A92.5 General       | ✓    |      |     |              |
| 2.20 | All moving parts are lubricated                                                             | ANSI/SAIA A92.5 Sec: 6.6.5    | ✓    |      |     |              |
| 2.21 | All fluid levels for oil, water and hydraulic are adequate                                  | ANSI/SAIA A92.5 Sec: 6.6.5    | ✓    |      |     |              |
| 2.22 | Platform controls operate the machine correctly                                             | ANSI/SAIA A92.5 Sec: 6.6.1    | ✓    |      |     |              |
| 2.23 | Platform controls are clearly marked with direction and mode of operation                   | ANSI/SAIA A92.5 Sec: 4.6.1.6  | ✓    |      |     |              |
| 2.24 | Platform controls accessible to the operator                                                | ANSI/SAIA A92.5 Sec: 4.6.1.1  | ✓    |      |     |              |
| 2.25 | Platform controls return to "off" or "neutral" position when released                       | ANSI/SAIA A92.5 Sec: 4.6.1.4  | ✓    |      |     |              |
| 2.26 | Platform controls are protected against                                                     | ANSI/SAIA A92.5 Sec:          | ✓    |      |     |              |

|                                             |                  |                                                                       |                             |                                                                                     |
|---------------------------------------------|------------------|-----------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|
| SAUDI ARAMCO INSPECTION CHECKLIST           | SAIC NUMBER      | ISSUE DATE                                                            | DISCIPLINE                  |  |
| BOOM SUPPORTED ELEVATING WORK PLATFORM      | SAIC-U-7013      | 12-Jan-23                                                             | ELEVATING/LIFTING EQUIPMENT |                                                                                     |
| PROJECT TITLE<br><br>TAMIMI Workshop, Damam | WBS/BI/JO NUMBER | INSPECTION COMPANY<br><br>SGS Inspection Services Saudi Arabia Co Ltd |                             |                                                                                     |

|                                                 |                                                     |                                                       |                                                       |
|-------------------------------------------------|-----------------------------------------------------|-------------------------------------------------------|-------------------------------------------------------|
| EQUIPMENT ID NUMBER<br><b>S16SD-1559</b>        | EQUIPMENT DESCRIPTION/TYPE<br><b>MANLIFT (MEWP)</b> | SERIAL NO.<br><b>BTRC024F00186</b>                    | REPORT No.:<br><b>SGS-2026-SA-156</b>                 |
| CAPACITY (SWL)<br><b>320 Kg</b>                 | MANUFACTURER<br><b>DINGLI</b>                       | FACILITY / LOCATION<br><b>TAMIMI Workshop, dammam</b> |                                                       |
| REQUESTED INSPECTION DATE<br><b>23-Feb-2026</b> | RFI No<br><b>SGS-RFI-08793</b>                      | TASK COMPLETED DATE<br><b>25-Feb-2026</b>             | EQUIPMENT OWNER<br><b>Sudhir Equipment Rental Co.</b> |

| ITEM | ACCEPTANCE CRITERIA                                                                                                                                | REFERENCE                    | PASS | FAIL | N/A | RE-INSP DATE |
|------|----------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|------|------|-----|--------------|
|      | inadvertent operation                                                                                                                              | 1.3                          |      |      |     |              |
| 2.27 | Over-ride control for power functions is fitted at ground level control panel                                                                      | ANSI/SAIA A92.5 Sec: 4.6.2.1 | ✓    |      |     |              |
| 2.28 | Lower controls return to "off" or "neutral" position when released                                                                                 | ANSI/SAIA A92.5 Sec: 4.6.2.4 | ✓    |      |     |              |
| 2.29 | Lower controls are clearly marked for direction and mode of operation                                                                              | ANSI/SAIA A92.5 Sec: 4.6.2.6 | ✓    |      |     |              |
| 2.30 | Lower controls do not include drive and steering functions                                                                                         | ANSI/SAIA A92.5 Sec: 4.6.2.2 | ✓    |      |     |              |
| 2.31 | Lower controls are protected against inadvertent operation                                                                                         | ANSI/SAIA A92.5 Sec: 4.6.2.5 | ✓    |      |     |              |
| 2.32 | Boom raise/extend is operable from platform and ground control                                                                                     | ANSI/SAIA A92.5 Sec: 4.6.2.2 | ✓    |      |     |              |
| 2.33 | Boom lower/retract is operable from platform and ground control                                                                                    | ANSI/SAIA A92.5 Sec: 4.6.2.2 | ✓    |      |     |              |
| 2.34 | Platform rotation is operable from both platform and ground controls                                                                               | ANSI/SAIA A92.5 Sec:         | ✓    |      |     |              |
| 2.35 | Emergency stop button is operable from both platform and ground controls                                                                           | ANSI/SAIA A92.5 Sec: 4.6.3   | ✓    |      |     |              |
| 2.36 | Auxiliary/emergency lowering is operable from platform and ground controls                                                                         | ANSI/SAIA A92.5 Sec: 4.6.4   | ✓    |      |     |              |
| 2.37 | Auxiliary/emergency retracting is operable from platform and ground controls                                                                       | ANSI/SAIA A92.5 Sec: 4.6.4   | ✓    |      |     |              |
| 2.38 | Auxiliary/emergency rotating is operable from platform and ground controls                                                                         | ANSI/SAIA A92.5 Sec: 4.6.4   | ✓    |      |     |              |
| 2.39 | Hydraulic/Pneumatic systems are leak-free with platform raised                                                                                     | ANSI/SAIA A92.5 Sec: 4.10.2  | ✓    |      |     |              |
| 2.40 | Tilt alarm is operable (5 degrees out of level) (manually depress the edge of the tilt switch to cause alarm condition)                            | ANSI/SAIA A92.5 Sec: 4.7.3   | ✓    |      |     |              |
| 2.41 | Aerial platforms is fitted with a warning device at the platform which activates automatically when the aerial platform is at and beyond the slope | ANSI/SAIA A92.5 Sec: 4.6.6   | ✓    |      |     |              |
| 2.42 | Tilt alarm is not combined with boom raise cut-out (dependent on machine manufacturer)                                                             | ANSI/SAIA A92.5 Sec: 4.6.6   | ✓    |      |     |              |
| 2.43 | Steering is properly working when moving forward and in reverse directions                                                                         | ANSI/SAIA A92.5 Sec: 6.6.3.1 | ✓    |      |     |              |
| 2.44 | Brakes are in good working condition and can hold the machine on any slope (parking and moving)                                                    | ANSI/SAIA A92.5 Sec: 4.14.1  | ✓    |      |     |              |
| 2.45 | Extendable axles function is satisfactory (where fitted)                                                                                           | ANSI/SAIA A92.5 Sec: 7.3.3.8 |      |      | ✓   |              |

|                                             |  |                  |                                                                       |                             |                                                                                     |
|---------------------------------------------|--|------------------|-----------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|
| <b>SAUDI ARAMCO INSPECTION CHECKLIST</b>    |  | SAIC NUMBER      | ISSUE DATE                                                            | DISCIPLINE                  |  |
| BOOM SUPPORTED ELEVATING WORK PLATFORM      |  | SAIC-U-7013      | 12-Jan-23                                                             | ELEVATING/LIFTING EQUIPMENT |                                                                                     |
| PROJECT TITLE<br><br>TAMIMI Workshop, Damam |  | WBS/BI/JO NUMBER | INSPECTION COMPANY<br><br>SGS Inspection Services Saudi Arabia Co Ltd |                             |                                                                                     |

|                                          |                                              |                                                |                                                |
|------------------------------------------|----------------------------------------------|------------------------------------------------|------------------------------------------------|
| EQUIPMENT ID NUMBER<br>S16SD-1559        | EQUIPMENT DESCRIPTION/TYPE<br>MANLIFT (MEWP) | SERIAL NO.<br>BTRC024F00186                    | REPORT No.:<br>SGS-2026-SA-156                 |
| CAPACITY (SWL)<br>320 Kg                 | MANUFACTURER<br>DINGLI                       | FACILITY / LOCATION<br>TAMIMI Workshop, dammam |                                                |
| REQUESTED INSPECTION DATE<br>23-Feb-2026 | RFI No<br>SGS-RFI-08793                      | TASK COMPLETED DATE<br>25-Feb-2026             | EQUIPMENT OWNER<br>Sudhir Equipment Rental Co. |

| ITEM | ACCEPTANCE CRITERIA                                                                               | REFERENCE                       | PASS | FAIL | N/A | RE-INSP DATE |
|------|---------------------------------------------------------------------------------------------------|---------------------------------|------|------|-----|--------------|
| 2.46 | Outriggers (stabilizers) extension-retraction operation is satisfactory                           | ANSI/SAIA A92.5 Sec: 7.10.3     |      |      | ✓   |              |
| 2.47 | Extendable elevating assembly operation is satisfactory (retracted vs. extended)                  | ANSI/SAIA A92.5 Sec: 4.2.1      | ✓    |      |     |              |
| 2.48 | Elevating assembly operation is satisfactory (elevated vs. lowered)                               | ANSI/SAIA A92.5 sec: 4.2.1( c ) | ✓    |      |     |              |
| 2.49 | Wheels and tires are serviceable and undamaged                                                    | ANSI/SAIA A92.5 Sec: 7.3.3 (6)  | ✓    |      |     |              |
| 2.50 | Travel alarm is operable                                                                          | ANSI/SAIA A92.5 Sec: 6.6 (4)    | ✓    |      |     |              |
| 2.51 | Platform lowering alarm is operable                                                               | ANSI/SAIA A92.5 Sec: 6.6 (4)    | ✓    |      |     |              |
| 2.52 | Auxiliary power source available (to use in event of primary power loss)                          | ANSI/SAIA A92.5 Sec: 4.15.2     | ✓    |      |     |              |
| 2.53 | Platform does not descend when in raised position and the power is off                            | ANSI/SAIA A92.5 Sec: 4.6.3      | ✓    |      |     |              |
| 2.54 | Machine is safely drivable from the platform when raised (fast, slow, forward and reverse modes)  | ANSI/SAIA A92.5 Sec: 6.6.3.1    | ✓    |      |     |              |
| 2.55 | The platform does not descend when in raised position and the power is off                        | ANSI/SAIA A92.5 Sec: 4.6.3      | ✓    |      |     |              |
| 2.56 | Engine powered machines fuel lines are supported to minimize chafing                              | ANSI/SAIA A92.5 Sec: 4.15.1     | ✓    |      |     |              |
| 2.57 | Engine powered machines fuel lines are positioned to minimize exposure to engine and exhaust heat | ANSI/SAIA A92.5 Sec: 4.15.1     | ✓    |      |     |              |
| 2.58 | Engine powered machines exhaust system is provided with muffler                                   | ANSI/SAIA A92.5 Sec: 4.15.1     | ✓    |      |     |              |
| 2.59 | Installation of Anti- Entrapment device on work platform                                          | Letter No. CIU-L-019/2016       | ✓    |      |     |              |

#### REFERENCE DOCUMENTS:

- 1.ANSI/SAIA A92.5 - 2014 Issue: Boom - Supported Elevating Work Platforms
- 2.SAES-B067 - 2020 Issue: Safety Identification and Safety Colors
- 3.SA GI 7.025 -2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification
- 4.SA GI 7.030 - 2023 Issue: Inspection and Testing Requirements for Elevating/Lifting Equipment

#### Load Tested By (If Applicable):

|      |           |      |
|------|-----------|------|
| Name | Signature | Date |
|------|-----------|------|

|                                             |  |                  |                                                                       |                             |                                                                                     |
|---------------------------------------------|--|------------------|-----------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|
| SAUDI ARAMCO INSPECTION CHECKLIST           |  | SAIC NUMBER      | ISSUE DATE                                                            | DISCIPLINE                  |  |
| BOOM SUPPORTED ELEVATING WORK PLATFORM      |  | SAIC-U-7013      | 12-Jan-23                                                             | ELEVATING/LIFTING EQUIPMENT |                                                                                     |
| PROJECT TITLE<br><br>TAMIMI Workshop, Damam |  | WBS/BI/JO NUMBER | INSPECTION COMPANY<br><br>SGS Inspection Services Saudi Arabia Co Ltd |                             |                                                                                     |

|                                          |                                              |                                                |                                                |
|------------------------------------------|----------------------------------------------|------------------------------------------------|------------------------------------------------|
| EQUIPMENT ID NUMBER<br>S16SD-1559        | EQUIPMENT DESCRIPTION/TYPE<br>MANLIFT (MEWP) | SERIAL NO.<br>BTRC024F00186                    | REPORT No.:<br>SGS-2026-SA-156                 |
| CAPACITY (SWL)<br>320 Kg                 | MANUFACTURER<br>DINGLI                       | FACILITY / LOCATION<br>TAMIMI Workshop, dammam |                                                |
| REQUESTED INSPECTION DATE<br>23-Feb-2026 | RFI No<br>SGS-RFI-08793                      | TASK COMPLETED DATE<br>25-Feb-2026             | EQUIPMENT OWNER<br>Sudhir Equipment Rental Co. |

|      |                     |           |      |      |     |              |
|------|---------------------|-----------|------|------|-----|--------------|
| ITEM | ACCEPTANCE CRITERIA | REFERENCE | PASS | FAIL | N/A | RE-INSP DATE |
|------|---------------------|-----------|------|------|-----|--------------|

|  |
|--|
|  |
|--|

|                                                              |                                                                                     |                                                        |
|--------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------|
| √ Inspected    ☐ Witnessed by 3rd Party Certified Inspector: |                                                                                     |                                                        |
| Name                                                         | Signature                                                                           | Certificate No. & Company:                             |
| Shehzad Mubashar                                             |  | 80019275 & SGS Inspection Services Saudi Arabia Co Ltd |

|                      |                                                                                     |             |
|----------------------|-------------------------------------------------------------------------------------|-------------|
| User Representative: |                                                                                     |             |
| Name                 | Signature                                                                           | Date        |
| Khurshed Alom        |  | 26-Feb-2026 |

**SGS**

شركة اس جي اس لخدمات الفحص العربية السعودية المحدودة

**SGS Inspection Services Saudi Arabia Co Ltd**

P.O Box 0725, Jubail, Saudi Arabia - 31951 Tel : +966133400044 / Fax : + 966133420212

## Lifting Equipment Inspection Sticker

Sticker Serial No : SGS-PASS-6885

Equipment No : S16SD-1559

Equipment sl No : BTRC024F00186

Date Inspected : 25-Feb-2026

Next Inspection Date : 24-Aug-2026

Inspected By : Shehzad Mubashar

Inspector No : 80019275



[www.sgs.com](http://www.sgs.com)

Saudi Aramco Inspection Department Approved Contractor Agency



## SGS INSPECTION SERVICES SAUDI ARABIA CO LTD

شركة اس جي اس لخدمات الفحص العربيّة السعوديّة المحدوده

P.O Box 0725, Jubail, Saudi Arabia - 31951  
Tel : + 966133400044 / Fax : + 966133420212  
Email : info@sgs.com

Report No: SGS-2026-SA-156



|                                                               |                                    |                                                      |                                       |                                                 |                                               |                                     |
|---------------------------------------------------------------|------------------------------------|------------------------------------------------------|---------------------------------------|-------------------------------------------------|-----------------------------------------------|-------------------------------------|
| <b>LIFTING EQUIPMENT<br/>INSPECTION REPORT</b>                | <b>RPO No</b><br>NA                | <b>CRM No</b><br>-                                   | <b>Inspection date</b><br>25-Feb-2026 | <b>Inspection time</b><br>11:00                 | <b>Previous sticker No</b><br>2250            | <b>Issued By</b><br>Standard Arabia |
| <b>Department / Contractor</b><br>Sudhir Equipment Rental Co. | <b>Equipment No.</b><br>S16SD-1559 | <b>Equipment Location</b><br>TAMIMI Workshop, dammam | <b>Area</b><br>DAMMAM                 | <b>Inspection Result</b><br>PASS                | <b>New Sticker No.</b><br>SGS-PASS-6885       |                                     |
| <b>Manufacturer</b><br>DINGLI                                 | <b>Model</b><br>BT16CRT2           | <b>Capacity</b><br>320 Kg                            | <b>Type</b><br>MANLIFT (MEWP)         | <b>Equipment Serial Number</b><br>BTRC024F00186 | <b>Sticker Expiration Date</b><br>24-Aug-2026 |                                     |

Above Equipment was inspected by **SGS Inspection Services Saudi Arabia Co Ltd** in accordance with applicable Saudi Aramco GI's, ASME & API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

| No | NOTES / DEFICIENCIES                                                                                                        | CORRECTIVE ACTION TAKEN |
|----|-----------------------------------------------------------------------------------------------------------------------------|-------------------------|
| *  | Periodic Visual & Functional inspection carried out as per ANSI A92.5 & G.I 7.030 on boom supported elevating workplatform. |                         |
| *  | All safety devices found operational at the time of inspection.                                                             |                         |
| *  | Maintain P.M service.                                                                                                       |                         |
| *  |                                                                                                                             |                         |
| *  |                                                                                                                             |                         |
| *  |                                                                                                                             |                         |

|                                                                                     |                                |                                    |                                                                                      |                                               |                                                                                       |                                        |
|-------------------------------------------------------------------------------------|--------------------------------|------------------------------------|--------------------------------------------------------------------------------------|-----------------------------------------------|---------------------------------------------------------------------------------------|----------------------------------------|
| <b>User Name</b><br>Khurshed Alom                                                   | <b>Badge No.</b><br>2436938994 | <b>Telephone No.</b><br>0573470508 | <b>Technical Reviewer Name</b><br>aqeel hashmi                                       | <b>SGS Inspector Name</b><br>Shehzad Mubashar | <b>Certificate No.</b><br>80019275                                                    | <b>Telephone No.</b><br>+966-551594665 |
|  |                                |                                    |  |                                               |  |                                        |
| Signature                                                                           |                                |                                    | Signature                                                                            |                                               | Signature                                                                             |                                        |

When re-inspection is requested, a complete copy of this report should be ready to be reviewed by the inspector.

Distribution: Original - Proponent, 1st copy - Inspection Agency, 2nd copy - Inspector

Control Report Number : SGS/JBL/M-26/117 WO:-