REPORT OF INSPECTION

Cert. No.: 2105084	Date of Examination: 04/12/2025	Sticker No.: 01-88269

Equipment Owner	SUDHIR EQUIPMENT RENTAL CO.
Place of Inspection	DAMMAM YARD
Equipment Type	TOWER LIGHT
Manufacturer Name	WACKER NEUSON
Owner ID	STL-017
Serial No.	18201655
Model	LTS8K
No. of Lamp(s) & Power	4 LAMPS/4000 W
Vertical Mast Height (max)	8.5 MTR
Nature of Power	DIESEL

At the request of SUDHIR EQUIPMENT RENTAL CO., Surveyor to BUREAU VERITAS, acting within the General Conditions of Services of the Society, attended on 04/12/2025 at DAMMAM YARD to witness Test and/or to carry out Thorough Examination of the above-mentioned equipment as per EN 60204, ISO8528

Inspection Activities:

Prior to commencing performance test, visual inspection of the equipment was carried out and no visible defects were observed. The equipment was then operated to all the functions to verify the performance of the equipment.

Result of Inspection:

Based on the visual inspection of the TOWER LIGHT and upon post-performance test & thorough examination, the above mentioned equipment has been found free from damage and/or permanent deformation at the time of inspection & is considered to be safe for further use, subject to continuous maintenance being applied and qualified operator being employed.

Remarks:

- Maintain regular maintenance.
- Maintain regular housekeeping.

Next Inspection Due on or before: 03/06/2026

Issued at Al Khobar on 04/12/2025

Inspected by
Signature:

Name: MOHAMED OMARA
Position: Senior Inspector

Reviewed by
Signature:

Name: Ahmed Elabady
Position: Reviewer

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null & void should Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.
Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgement, fault or negligence committed by the personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.
This not is NOT an indication that the item(s) is (are) fir for any specific purpose and does not release the manufacture, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation patents, workmanship, materials, safety, performance in operation and/or reliability.

CHECKLIST OF TEST AND THOROUGH EXAMINATION

Inspection Sticker No.: 01-88269	Date of Examincation: 04/12/2025

	DESCRIPTION	CONDITION/REMARKS
1.	Condition of the mast	Satisfactory
2.	Condition of mast winch	Satisfactory
3.	Condition of mast cable	Satisfactory
4.	Condition of mast cradle locking pin	Satisfactory
5.	Condition of light fixtures	Satisfactory
6.	Condition of electrical box & wiring	Satisfactory
7.	Condition of light lens	Satisfactory
8.	Condition of energy source	Satisfactory
9.	Fire extinguisher (if fitted)	Unsatisfactory
10.	Ignition & electrical system condition	Satisfactory
11.	Exhaust & ventilation	Satisfactory
12.	Power generator set (if applicable)	Satisfactory
13.	Marking / Labels & warning signage	Satisfactory
14.	Foundation – tires, out-riggers, support stands	Satisfactory
15.	Structure – chassis, lifting points	Satisfactory
16.	Name plate	Satisfactory

Remarks: -SATISFACTORY

Inspector to Bureau Veritas
Signature:

Name: MOHAMED OMARA
Position: Senior Inspector

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null & void should Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.
Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgement, fault or negligence committed by the personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.
This not is NOT an indication that the item(s) is (are) fir for any specific purpose and does not release the manufacture, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation patents, workmanship, materials, safety, performance in operation and/or reliability.