



INSPECTION REPORT NO.001

BV JOB NO : RIY.INP. C03220217-EM05

page 1 of 2

PROJECT: Riyadh	Contract Ref: 4569959
Client: Sudhir	P/o nr:
Manufacturer: Wacker Neuson	P/o nr: N/A(Client to Manufacturer)
Inspection requested by: Sudhir	

SUPPL& Y / SUBJECT OF INSPECTION	ITEM / TAG No	QTY
Inspection of Tower Light	STL-085 / 18202169	01

Inspection Place & Date or Period:17th Feb '22 at

, Riyadh

Sticker # LFT-S-03-6304

Stage of inspection :☐ Before manufacturing☐ During manufacturing☒ Final☐ Packing**Kind of inspection:**☐ Pre-inspection meeting☐ Witnessing tests☒ Document review☒ Final Inspection

(for details see continuation sheet)

Stamping:☒ No ☐ ☒ ☐ ☒**Non Conformities Reports (NCR):**

oNCR's issued during reported period :

- N/A

o List of outstanding NCR's :

- N/A

Main Conclusions & Remarks: (for details see continuation sheet)

- Inspection equipment was found to be in satisfactory condition at the time of inspection.

Next visit scheduled: 16/08/2022**INSPECTIONS:****Results of inspection:** ☒ Satisfactory ☐ Unsatisfactory

INSPECTION REPORT NO.001

BV JOB NO : RIY.INP. C03220217-EM05

page 2 of 2

Introduction:

Inspection was carried out on 17th Feb. 2022, Riyadh, Saudi Arabia.

1. Attendees:

- Mr. Waseem (Sudhir company)
- Mr. Zulfiqar Ali(IVS Inspector-Bureau Veritas)

2. Applicable Documents & Status of Approval

See documents of reference,

3. Scope Of Inspection:

- Review of Inspection & Test Plan.
- Random Visual & Dimensional Inspection & review of reports

4. Details of inspection activities carried out w.r.t to Scope of Work:

Inspector reviewed the following documents at **Riyadh**.

- Inspection & Test Plan
- Final visual & dimensional Inspection reports.

Results of Inspection :

Equipment inspected was found to be in satisfactory condition at the time inspection.
Results of tests were satisfactory.

ANNEXES ☐ Yes ☒ No

Inspected by: Engr Zulfiqar Ali




Reviewed by: Bilal Haroon
IVS Team Leader



Distribution: ☒ Sudhir Company ☐ CONTRACTOR