



# شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

## CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

|                                           |                            |                                        |
|-------------------------------------------|----------------------------|----------------------------------------|
| Date of thorough examination : 21-06-2026 | Date of issue : 21-06-2026 | Report No. : <b>ESICO-LFT-R26-9470</b> |
|-------------------------------------------|----------------------------|----------------------------------------|

|                            |                 |         |                              |
|----------------------------|-----------------|---------|------------------------------|
| Name & Address of employer | Location        | Sticker | Standards                    |
| SUDHIR EQUIPMENT RENTALS   | AL HASSA 7 SITE | 11122   | SASO GSO EN 280 & ANSI A92.6 |

| Equipment Identification No   | Equipment Description                                                                                                             | Safe Working Load(s) | Date of Manufacture | Manufacturer Name |
|-------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------|-------------------|
| SD16ESL-1400 OR JAPC024F03328 | SCISSORLIFT<br>MODEL: S1614AC<br>Overall Length: 2.84 m<br>Platform Size (L x W): 2.64 m x 1.12 m<br>Max. Working Height: 15.70 m | 363 KG               | U/N                 | DINGLI            |

|                                                                                         |                                           |                                                                    |                                           |
|-----------------------------------------------------------------------------------------|-------------------------------------------|--------------------------------------------------------------------|-------------------------------------------|
| Is this the first examination after installaton or assembly at a new site or location?  | Yes - No <input checked="" type="radio"/> | Was the examination carried out within an interval of? - 12 Months | Yes <input checked="" type="radio"/> No - |
| If the answer to the above question is YES, has the equipment been installed correctly? | Yes - No -                                | After the occurence of exceptional circumstances?                  | Yes - No <input checked="" type="radio"/> |

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE

Is the above an existing or imminent danger to persons, Note: This is a reportable defect? No

Is the above a defect which is not yet could become a danger to persons (if YES state the date by when) Yes by : NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE

Particulars of any tests carried out as part of the examination (if none state NONE) : NONE

Observation/additional comments relative to this thorough examination : NO DEFECT FOUND AT THE TIME OF INSPECTION.



For confirmation scan QR code  
search with report number : **ESICO-LFT-R26-9470**

☒ Safe to operate

Next Inspection : 20-06-2027

Inspected by : ANSON

